

## **LKK Auto Consultants Pte Ltd**

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

		Reg. No: 199607	/198R GST Reg. No. 19	9-96071	198-R	
Affiliated to Federation Internationale Des Experts En Automobile						
	AUTO & GENERA	L INSURANCE (S) PL	R	ef:	CS/AGI21011622/Uuf3n2	
		INSURANCE) U AVENUE #03-01 PPING CENTRESINGAPORE	D	ate:	26/11/2021	
			С	ode:	AGI	
1. Policy Particulars :- THIRD PARTY CLAIM					1	
	Insured Veh.	SLZ 6870L	Veh. Inspected		SDA 6881G	
	Policy No.		Coverage (\$)		0.00	
	Claim No.	C10012459/KY	Excess (\$)		0.00	
	Assign From	IVY RATILLA	Assign Date		15/11/2021	
2. Vehicle Particulars & Condition						
	Make & Model	VOLKSWAGEN GOLF A7 (A)	c.c		1395	
	Engine No.	HIDDEN	Year of Reg.		2014	
	Chassis No.	WVWZZZAUZEW247563	Colour		BLACK	
	Odometer	22310 KM	Steering		IN ORDER	
	Brakes	IN ORDER	Modification		SPORTS RIM	
	General	GOOD				
3.	. Conditions of Tyres					
		Size	Make		Balance	
	R/H Front Tyre	205/55 R16	WEST LAKE		7 mm	
	L/H Front Tyre	205/55 R16	WEST LAKE		7 mm	
	R/H Rear Tyre	205/55 R16	WEST LAKE		7 mm	
	L/H Rear Tyre	205/55 R16	WEST LAKE		7 mm	
4.	Description of Damages					
	THE VEHICLE SUSTAINED DAMAGES AT THE REAR PORTION.					
	DAMAGES SEE DETAILS.					
5.	General Information					
	Accident Date	12/11/2021	Inspection Date		15/11/2021	
	Survey held at	FASTECH AUTO PTE LTD				
		1 KAKI BUKIT AVENUE 6 #01-46/48/50 AUTOBAY SINGAPORE 417883				
5a.	Remarks					
	A)THE INSPECTION	A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.				
5b.	D)IN ACCORDANC	Estimate Days of Repair				
	Lottinuto Dayo of Repair					

3 Working Days

ESTIMATED NORMAL PERIOD FOR REPAIR: