

ALG (Alsum)

COMFORTDELGRO ENGINEERING PTE LTD

Date: 15.11.2021

Time: 13:39:24

REPAIR ESTIMATE

Page: 1

COMPANY : THIRD PARTY'S CLAIMS (CAS)
CUSTOMER: 7010045
ADDRESS : COMFORT TRANSPORTATION PTE LTD
383 SIN MING DRIVE
SINGAPORE SINGAPORE 575717
65508755

JOB NO : 305494449
REGN NO : SH 7012C
MILEAGE : 0000000000
MAKE : TOYOTA
MODEL : PRIUS HYBRID(G4)
DATE OF REGN : 25.05.2017
DATE/TIME IN : 15.11.2021 10:30
ACCIDENT DATE : 13.11.2021

JOB / PARTS DESCRIPTION

QTY IND UNIT-PRICE DISC% AMOUNT

PART REQUISITION

0001 04-01-0302-2292-G COVER FRONT BUMPER^	1	499.90	25.00	374.92	de	
0002 04-01-0302-0574-G FENDER SUB-ASSY FRONT LH+	1	945.30	25.00	708.97	hb	
0003 04-01-0302-2297-G EMBLEM SIDE PANEL (HYBRID	1	86.50	25.00	64.87	wei	1531.70
0004 04-01-0302-2871-G SUPPORT FRONT BUMPER SIDE	1	81.70	25.00	61.27	Xun	1148.77

SUB-TOTAL : 1,210.03

JOB NATURE

0000 PB	PANEL BEATING	750.00	350	
0001 SP	SPRAYPAINT CHARGE	600.00	500	
0002 20-00	TUFF COAT ON AFFECTED PARTS.	50.00	30	880

SUB-TOTAL : 1,400.00

TOTAL : 2,610.03

2028.77

4/5 \$1600

2 days*

Juman!

MVA NAME & SIGNATURE

DATE :

SURVEYOR NAME & SIGNATURE

AUTHORISED : YES / NO

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to the insurance Company

Acknowledged by Repairer
Signature:
Date:

Tanfiah 974157417

WP 15/11/21 0440

1/5 resurvey after repair

2 days

Tanfiah C/Manager