

## COMFORT TRANSPORTATION PTE LTD

**REPAIR ESTIMATE**

Vehicle No. : SHC7024A

Make : HYUNDAI

Model : I-40

Date: 15/11/2021

Insurance: AIG

MVA: MS. Y Y

Qty	Parts Description / Labour	Type	Unit Price	Amount
1	REAR BUMPER COVER			\$553.00
1	REAR BUMPER CLIPS			\$22.00
1	REAR BUMPER SIDE BRACKET RH			\$35.60
1	REAR BUMPER REFLECTOR LAMP RH			\$32.00
1	EXHASUT SILENCER RH			\$967.70
1	EXHAUST PIPE CENTRE			\$730.10
1	EXHAUST PIPE HANGER			\$117.10
	<b>SUB TOTAL</b>			\$2,457.50
	<b>LESS 20%</b>			\$491.50
	<b>DISCOUNTED TOTAL</b>			<b>\$1,966.00</b>
1	REAR BUMPER REVERSE SENSOR			\$135.70
1	REAR BUMPER RUBBER MAT			\$50.00
				<b>\$185.70</b>
	<b>Labour Charge</b>			
	PANEL BEATING			\$450.00
	SPRAY PAINTING CHARGE			\$300.00
	REMOVE/ REFIX EXHAUST PIPE			\$150.00
	REMOVE/ REFIX REVERSE SENSOR			\$60.00
	<b>TOTAL LABOUR</b>			<b>\$960.00</b>
	<b>ESTIMATE TOTAL</b>			<b>\$3,111.70</b>

This is an initial estimate based on a visual inspection of the above vehicle. The final repair quantum will be prepared after the vehicle is surveyed by a motor Surveyor appointed by the insurance company.

**LKK Auto Consultants** hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary items must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

Dauphin 17475747  
 'in p' 15/11/2021 5pm  
 L/S Repair after repair  
 02 days  
 fuyh c. hant. w

Date/Time: 15.11.2021 11:09

Page : 1

**JOB CARD**

Sales Order: 4140848

JC NO: 305494444

Team: ARC Repair TP(CFSO)1

CUSTOMER

RMS CITYCAB PTE LTD

CUSTOMER NO. 7010070

ADDRESS 383 SIN MING DRIVE  
Singapore SINGAPORE 575717

Tel. (R) 65551188 (O)  
(P)

SCOUT CARD NO.

REGN NO.:

SHC7024A

MILEAGE

MAKE:

HYUNDAI

FUEL

E.....1/2.....F

MODEL

I-40

DATE/TIME IN  
15.11.2021 08:20

YR OF MANU.

17.03.2016

TARGET DATE

CHASSIS CODE

KMHLB41UMGU085582


COMPLETION DATE/TIME:

JOB DESCRIPTION

Accident Date: 14.11.2021  
NATURE: 3P 14.11.2021

S/NO LABOR CODE

DESCRIPTION



CHECKED & PASSED OUT BY:

SERVICE ADVISOR

CUSTOMER'S SIGNATURE

Acknowledgement Slip

Name:

No.:

Vehicle No.: SHC7024A

YY

Exit Pass

Vehicle No.:

SHC7024A

Name of Service Advisor

Signature/Date

Name of Service Advisor

Date

Vehicle returned to Service Reception upon collection

To be kept by Security Guard