

(08/11/13) Wef  
ASS. REC. BY: *James*

REF:

*CC4/LPC21011661/Rira3*

1562

### ASSIGNMENT

From:

Date:

Estimated Cost:

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No: *SMK 5738K*

at Workshop m/s *BORNEO MOTOR*

of *2 PANDAN CRUSANT*

Insured: *LPC*

Policy No.

Claims No.

Sum Insured:


Excess:

(Client's Record)

Make of Veh:

(Policy Condition)

Remark: The veh had commenced its  
repair at the time of inspection.



Bal. or Market Value:

*170K*

IDAC Accident Rpt:

Consistent? : Yes or No

GIA / PR Seen:

Consistent? : Yes or No

Est. Repairs:

days Res.: Yes or No

Lum Sum:

% 3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Vehicle: IN / OUT

Date:

Person Contacted:

Date / Time

Action / Instruction

*REPAIR LIMIT - 96K*

Veh No:

*SMK 5738K*

Yr Regn: *2019 / APR*

Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make:

*TOYOTA LEXUS ES 300H 40REX6C 2487*

Colour

*BLUE*

A/C: Insured / Std / NI / NA

Sp. Reading

*47103*

T/Radio: Insured / Std / NI / NA

Eng/No:

C/No:

*JTHB21B1202041232*

Gen. Cond: Good / Fair / Poor / Burnt

Steering: In order / Jammed / Leaked / Burnt or

Brake: In order / Jammed / Leaked / Burnt or

Modi: Nil / S Rim / STD A/Rim or

Tyre Size:

F:

*235/45R18*

R:

*2*

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or

Front

Rear

R/Bal.

*6*

mm

R/Bal.

*6*

mm

L/Bal.

*6*

mm

L/Bal.

*6*

mm

D.O.A.

*13/11/21*

D.O.I.

*18/11/21*

Survey held at

*BORNEO MOTOR*

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

The U/C / Chassis frame / Body Structure affected due to collision.

Date/Time, File Pass to?

☐

: Preli. Report

1)

☐

: Final Report

Date/Time, File Return to?

2)

Days Of Repair:

Resurvey No. of Trip:

Survey Fee:

Transportation:

Add Fee:

☐

: Site Insp (\$

) : S + RS, SI

☐

: Interview (\$

) : Photos

☐

: Tech. Invs (\$

) : Others

☐

: Weekend (\$

)

Report Format :

Lump Sum / I.B.I.: (\$

# Borneo Motors



JKK - Summer  
+6019-7856879  
Thu 18/11 - 10.30am.

## ESTIMATE

Account Details		Customer Details	
Lonpac Insurance Berhad 100 Beach Road #19-00 Shaw Tower Singapore 189702 Attn: Ms Lily Koh/Mr Chia	Account No.	Mr Lim Puay Huat 41 Lorong Marzuki Singapore 417108  Mobile: 96320319	
	S1000007 / ICLPI1		
	Document No.		
	0		
	Document Date		
	15/11/2021		

Year	Model	Variant	Reg. Date	Reg. No.	Kilometers	Wip No.	Order No. / Remarks
2019	AXZH10R	AEXGB S1	16/04/2019	SMK5738K	0	20323	61TP/SMK5738K/131121

Chassis No.	Engine No.	Terms	SA / Counter	Vehicle In	Collected On
JTHB21B1202041232	A25A5166348	60	Carine Yeo C L	--/--/----	0.00 --/--/---- 0.00

L	Cd	Job/Parts Description	Qty	Unit Price	Disc %	Amount
1	Z	BP-SUNDRY SUNDRIES T/P INS: LONPAC INS ACC DATE: 13.11.2021 T/P VEH: GBH6145K DATE IN: DATE SURVEY: DATE AUTHORIZE:				50 100.00
2	B	BP-LAB3 TO REMOVE ALL NECESSARY PARTS TO ENABLE REPAIRING AND STRAIGHTEN ON REAR BUMPER, REAR PANEL, BOOT COVER AND FIX NEW PARTS @ 866				2598 4330.00
3	B	BP-RES3 TO RESPRAY PAINT ON WHOLE REAR PORTION INCL REAR PANEL				3464 paid? 4452.00
4	B	BP-LAB3 TO REMOVE AND TRANSFER REAR BOOT'S COMPONENT AND MECHANISM TO NEW BOOT (NETT)				2968 433.00
5	B	BP-LAB3 TO REMOVE AND TRANSFER BOOT SPOILER TO ENABLE REPAIR (NETT)				216.50
6	B	BP-LAB3 TO REMOVE AND TRANSFER REAR REVERSE CAMERA TO NEW BOOT (NETT)				216.50

For & on behalf of Borneo Motors (Singapore) Pte Ltd	Customer's Signature	Charge Summary	Total
	Please acknowledge receipt of vehicle	Parts Labour Sublet Lubrication/Fluid Others	Less  Amount Due



No. : 196700086Z  
 No. : MR-8500000-9  
 andan Crescent  
 pore 128462, Tel no.: 6631 1388

## ESTIMATE

Account Details			Account No.		Customer Details		
Lonpac Insurance Berhad 100 Beach Road #19-00 Shaw Tower Singapore 189702 Attn: Ms Lily Koh/Mr Chia			S1000007 / ICLPI1		Mr Lim Puay Huat 41 Lorong Marzuki Singapore 417108  Mobile: 96320319		
			Document No.				
			0				
			Document Date				
			15/11/2021				
Year	Model	Variant	Reg. Date	Reg. No.	Kilometers	Wip No.	Order No. / Remarks
2019	AXZH10R	AEXGB S1	16/04/2019	SMK5738K	0	20323	61TP/SMK5738K/131121
Chassis No.		Engine No.	Terms	SA / Counter	Vehicle In		Collected On
JTHB21B1202041232		A25A5166348	60	Carine Yeo C L	--/--/----		0.00 --/--/---- 0.00
L	Cd	Job/Parts Description	Qty	Unit Price	Disc %	Amount	
7	Z	BP-SLANT SUPPLY BOOT SEALANT (NETT)				100.00	
8	Z	BP-SLANT SUPPLY REAR PANEL SEALANT (NETT)				100.00	
9	B	BP-LAB3 TO REMOVE AND RE-INSTALL REAR LUGGAGE TRIM, GARNISH ETC TO ENABLE REPAIR (NETT)				433.00	
10	B	BP-LAB3 TO REMOVE AND TRANSFER REAR SENSOR TO NEW BUMPER, REPLACE IF DAMAGE (NETT)				216.50	
11	B	BP-LAB3 TO CHECK WIRING AND LIGHTS FUNCTIONING AND CARRY OUT WATER LEAK TEST (NETT)				216.50	
12	B	BP-ECU3 TO RESET ECU & REPROGRAMME (NETT)				216.50	
13	T	BP-MISC1 SHOULD THE ABOVE VEHICLE BE SUBJECT TO TOTAL LOSS OR TOW OUT BY INSURANCE COMPANY OR BY THE OWNER PRIOR TO THE REPAIR A 6% OF THE QUOTATION PRICE WILL BE IMPOSED AS ADMIN CHARGES TO A MAX OF \$1000 + TOWING CHARGES IF APPLICABLE.					
For & on behalf of Borneo Motors (Singapore) Pte Ltd			Customer's Signature		Charge Summary		Total
			Please acknowledge receipt of vehicle		Parts Labour Sublet Lubrication/Fluid Others		Less
							Amount Due

No. : 196700086Z  
 No. : MR-8500000-9  
 andan Crescent  
 pore 128462, Tel no.: 6631 1388

## ESTIMATE

Account Details	Account No.	Customer Details
Lonpac Insurance Berhad 100 Beach Road #19-00 Shaw Tower Singapore 189702 Attn: Ms Lily Koh/Mr Chia	S1000007 / ICLP11	Mr Lim Puay Huat 41 Lorong Marzuki Singapore 417108 Mobile: 96320319
	Document No. 0	
	Document Date 15/11/2021	

Year	Model	Variant	Reg. Date	Reg. No.	Kilometers	Wip No.	Order No. / Remarks
2019	AXZH10R	AEXGB S1	16/04/2019	SMK5738K	0	20323	61TP/SMK5738K/131121
Chassis No.	Engine No.	Terms	SA / Counter	Vehicle In	Collected On		
JTHB21B1202041232	A25A5166348	60	Carine Yeo C L	--/--/----	0.00	--/--/----	0.00

L	Cd	Job/Parts Description	Qty	Unit Price	Disc %	Amount
14	Z	BP-MISC2 A DAILY STORAGE CHARGE AT THE RATE OF S\$25/- PER DAY WILL COMMENCE 7 DAYS AFTER ESTIMATE DATE. THESE CHGS WILL NOT APPLY IF REPAIRS ARE UNDERTAKEN BY BORNEO MOTORS.				
15	1	L52159-33979 COVER, RR BUMPER <i>coa</i>	1.00	1311.70		1311.70
16	2	L52171-33170 REINFORCEMENT, RR <i>?</i>	1.00	745.60		745.60
17	3	L52615-33210 ABSORBER, RR BUMPER <i>?</i>	1.00	113.20		113.20
18	4	L52582-33010 PROTECTOR, RR <i>?</i>	1.00	188.70		188.70
19	5	L52581-33010 PROTECTOR, RR <i>?</i>	1.00	187.20		187.20
20	6	L75895-78030 TAPE, MOULDING, NO.1 <i>ne</i>	2.00	40.10		80.20
21	7	L52158-33040 SUPPORT, RR BUMPER <i>?</i>	1.00	137.30		137.30
22	8	L52157-33040 SUPPORT, RR BUMPER <i>?</i>	1.00	137.30		137.30
23	9	L52197-53040 BRACKET, RR BUMPER <i>ne</i>	1.00	5.90		5.90
24	0	S52161-0K040 BUMPER CLIPS <i>ne</i>	20.00	4.10		82.00
25	1	L52463-33070 PAD, RR BUMPER, LH <i>ne</i>	1.00	13.90		13.90
26	2	L52462-33070 PAD, RR BUMPER, RH <i>ne</i>	1.00	11.60		11.60
27	3	L52105-33020 BUMPER SUB-ASSY, RR <i>sc</i>	1.00	683.70		683.70
28	4	L52568-33040 RETAINER, RR BUMPER <i>-</i>	1.00	167.10		167.10
29	5	L52198-53020 BRACKET, RR BUMPER LH <i>ne</i>	1.00	5.90		5.90

For & on behalf of	Customer's Signature	Charge Summary	Total
Borneo Motors (Singapore) Pte Ltd	Please acknowledge receipt of vehicle	Parts Labour Sublet Lubrication/Fluid Others	Less Amount Due



No. : 196700086Z  
 Reg No. : MR-8500000-9  
 Grandan Crescent  
 Singapore 128462, Tel no.: 6631 1388

## ESTIMATE

Account Details		Account No.	Customer Details					
Lonpac Insurance Berhad 100 Beach Road #19-00 Shaw Tower Singapore 189702 Attn: Ms Lily Koh/Mr Chia		S1000007 / ICLPI1	Mr Lim Puay Huat 41 Lorong Marzuki Singapore 417108  Mobile: 96320319					
		Document No. 0						
		Document Date 15/11/2021						
Year	Model	Variant	Reg. Date	Reg. No.	Kilometers	Wip No.	Order No. / Remarks	
2019	AXZH10R	AEXGB S1	16/04/2019	SMK5738K	0	20323	61TP/SMK5738K/131121	
Chassis No.		Engine No.	Terms	SA / Counter	Vehicle In		Collected On	
JTHB21B1202041232		A25A5166348	60	Carine Yeo C L	--/--/----		0.00 --/--/---- 0.00	
L	Cd	Job/Parts Description			Qty	Unit Price	Disc %	Amount
30	6	L52156-33020	SUPPORT, RR BUMPER ?			1.00	86.60	86.60
31	7	L52155-33020	SUPPORT, RR BUMPER ?			1.00	79.10	79.10
32	8	L58307-33191	PANEL SUB-ASSY, BODY ?			1.00	844.70	844.70
33	9	L64401-33870	PANEL SUB-ASSY, ?			1.00	1022.50	1022.50
34	0	L64461-33130	WEATHERSTRIP, ?			1.00	254.30	254.30
35	1	L64650-33040	CLOSER ASSY, LUGGAGE sc			1.00	1304.70	1304.70
36	2	L64714-33060	COVER, LUGGAGE ?			1.00	96.20	96.20
37	3	L64713-33070	COVER, LUGGAGE ?			1.00	96.20	96.20
38	4	L58387-33160 CO	PLATE, RR FLOOR ?			1.00	363.90	363.90
39	5	L75447-33200	PLATE, LUGGAGE COMPT m			1.00	68.90	68.90
40	6	L90975-02134	EMBLEM, SYMBOL m			1.00	166.30	166.30
41	7	L75442-33540	PLATE, LUGGAGE COMPT m			1.00	80.60	80.60
42	8	L81498-33030	COVER, RR ?			1.00	38.00	38.00
43	9	L81497-33030	COVER, RR ?			1.00	38.00	38.00
44	0	L52563-33050	RETAINER, RR BUMPER, ?			1.00	60.60	60.60
45	1	L52562-33070	RETAINER, RR BUMPER, ?			1.00	60.60	60.60
46	2	L81590-33470	LAMP ASSY, RR, LH ?			1.00	1070.10	1070.10
47	3	L81580-33471	LAMP ASSY, RR, RH ?			1.00	1070.10	1070.10
48	4	L81560-33592	LAMP ASSY, RR ?			1.00	1377.50	1377.50
49	5	L81550-33592	LAMP ASSY, RR ?			1.00	1377.50	1377.50
For and on behalf of		Customer's Signature		Charge Summary		Total		
Borneo Motors (Singapore) Pte Ltd		Please acknowledge receipt of vehicle		Parts Labour Sublet Lubrication/Fluid Others		Less		
						Amount Due		

No. : 196700086Z  
 No. : MR-8500000-9  
 andan Crescent  
 ore 128462, Tel no.: 6631 1388

## ESTIMATE

Account Details		Account No.		Customer Details			
Lonpac Insurance Berhad 100 Beach Road #19-00 Shaw Tower Singapore 189702 Attn: Ms Lily Koh/Mr Chia		S1000007 / ICLPI1		Mr Lim Puay Huat			
		Document No.		41 Lorong Marzuki			
		0		Singapore 417108			
		Document Date		Mobile: 96320319			
15/11/2021							

Year	Model	Variant	Reg. Date	Reg. No.	Kilometers	Wip No.	Order No. / Remarks
2019	AXZH10R	AEXGB S1	16/04/2019	SMK5738K	0	20323	61TP/SMK5738K/131121

Chassis No.	Engine No.	Terms	SA / Counter	Vehicle In	Collected On
JTHB21B1202041232	A25A5166348	60	Carine Yeo C L	--/--/----	0.00 --/--/---- 0.00

L	Cd	Job/Parts Description	Qty	Unit Price	Disc %	Amount
50	6	L81496-60010 GUIDE, RR <i>re</i>	2.00	3.50		7.00
51	7	L89348-58130 CLIP, ULTRASONIC <i>re</i>	4.00	12.30		49.20
52	8	L89341-33220 J2 SENSOR, ULTRASONIC, ?	4.00	490.80		1963.20
53	9	L81920-33030 REFLECTOR ASSY, ?	1.00	49.30		49.30
54	0	L81910-33040 REFLECTOR ASSY, ?	1.00	49.30		49.30
55	1	L58748-33100 PROTECTOR, QUARTER ?	1.00	28.80		28.80
56	2	L58747-33090 PROTECTOR, QUARTER ?	1.00	28.80		28.80

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer  
 Signature: \_\_\_\_\_

*Resue*  
*Hp 90010068*  
*7 or 9 days*  
*18/11/21 @ 1030*  
*Resurvey before print*

For & on behalf of	Date:	Customer's Signature	Charge Summary	Total	26,633.80
Borneo Motors (Singapore) Pte Ltd					
		Please acknowledge receipt of vehicle  _____	Parts	15,603.30	GST 7.00% 1,864.37 Less 0.00 Amount Due 28,498.17
			Labour	11,030.50	
			Sublet	0.00	
			Lubrication/Fluid	0.00	
			Others	0.00	



# SINGAPORE ACCIDENT STATEMENT

## IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

## ACCIDENT STATEMENT

Date of Submission	15/11/2021 15:16 (SGT)
Date of Accident	13/11/2021 17:30 (SGT)
Exact Location of Accident	Singapore
Additional Location Information	NEW BRIDGE ROAD CHINATOWN POINT LOADING BAY @UPPER HOKIEN ST
Country/State of Loss	Singapore

## DETAILS OF OWN VEHICLE

Vehicle Registration Number	SMK5738K
-----------------------------	----------

### INSURED/POLICYHOLDER

Is company?	No
Name Of Registered Owner	LIM PUAY HUAT
NRIC No	SXXXX156Z
Email Address	KELVIN.LIMPH@GMAIL.COM
Mobile Phone No	(Phone) +65-96320319
Alternative Phone No	(Home) +65-96320319

### VEHICLE PARTICULARS

Manufacturer	Lexus
Model	Es300h
Variant	-
Exact purpose for which vehicle was being used at time of accident	-
Are you claiming under your own insurance policy for repair to your vehicle?	No - Claiming third party
Vehicle Category	Private car
Transmission	Auto
CC	3000

### INSURANCE COMPANY

Name of Insurance Company	AXA Insurance Pte Ltd
Type of Coverage	Comprehensive
Fleet Policy	No
Policy Number	GA567522
Cover Note Number	-

### DRIVER

Name of Driver	LIM PUAY HUAT
----------------	---------------

Birth	SXXXX156Z
ation	02/10/1962
Of Driving Pass	Indoor
ing experience	29/05/1981
ender	40 YEARS AND 6 MONTHS
Mobile Number	Male
Alt. Phone Number	(Phone) +65-96320319
Email Address	(Home) +65-96320319
Address	KELVIN.LIMPH@GMAIL.COM
Address complement	41 LORONG MARZUKI
Postcode	-
Is the driver the policyholder?	417108
If No, Relationship of the Driver with the Insured	Yes
Does Driver Own Other Vehicles?	-
Vehicle Registration Number of Other Vehicle Owned by Driver	No
Insurance Company of Other Vehicle Owned by Driver	-

#### GENERAL INFORMATION OF THE ACCIDENT

Type of Accident	Collision - Head to Rear
Weather Conditions	Clear
Road Surface	Dry

#### OTHER INFORMATION

Was any foreign vehicle involved in the accident?	No
Number of vehicles involved in the accident	2
Was anybody injured in the Accident?	No
Was any injured conveyed to hospital by ambulance?	-
Was any other vehicle or property damaged?	Yes
Number of Passengers (Including Driver)	1
Has the driver been approached by unknown person(s) soliciting/offering accident claims assistance?	No

#### DETAILS OF POLICE ACTION

Was the accident reported to the police?	No
Was notice of intended Prosecution given?	No
If yes, against whom?	-

#### CIRCUMSTANCES OF ACCIDENT

PLEASE REFER TO ATTACHED SKETCH PLAN AND STATEMENT.

#### ATTACHMENT(S)

Are accident photos available for attachment?	Yes
Was there any video captured by Car Camera?	No
Was there any audio recorded?	No

#### DETAILS OF OTHER VEHICLE PROPERTY 1

Vehicle Registration Number	GBH6145K
Vehicle Manufacturer	-
Vehicle Model	-
Vehicle Variant	-
Vehicle Colour	-
Vehicle Category	Commercial vehicle
Name of Driver	LIM
Contact Number	(Phone) +65-85358416
Address	-



Complement  
Insurance Company Name  
Type Of Damage  
Details of property damaged in accident  
Of Passenger (Including Driver)

-  
-  
Lonpac Insurance Bhd  
-  
REAR PORTION  
-

## SKETCH PLAN

### IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. The report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.
8. **Consent under the Personal Data Protection Act (PDPA)**

I understand, acknowledge, agree and consent that :

(a) My insurer , my workshop and the General Insurance Association of Singapore ("GIA") may/are permitted to collect, use, disclose and/or process my personal data/personal information set out in this [form] and any other personal information provided by me or possessed by my insurer (collectively the "Personal Information") and disclose and transfer such Personal Information to all insurer(s) who have insured vehicle(s) involved in this accident (all insurer(s) who have insured vehicle(s) involved in this accident shall be collectively referred to as the "Insurers"), the Insurers' lawyers/law firms, the Monetary Authority of Singapore and any relevant government agency/authority (such as the police), for the purpose(s) of :

(i) processing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigations relating to the claims;

(ii) investigating the accident and/or my claims;

(iii) carrying out and/or dealing with my instructions or responding to any enquiries by me;


(iv) administering my claims (including the mailing of correspondence, statements, invoices, reports or notices to me, which could involve disclosure of certain personal data about me to bring about delivery of the same as well as on the external cover of envelopes/mail packages); and/or


(v) complying with applicable law in administering, processing, handling and/or dealing with my claims.

(collectively the "Purposes")

(b) all insurer(s) who have insured vehicle(s) involved in this accident and the Insurers' lawyers/law firms, may/are permitted to collect, use, disclose and/or process my Personal Information for one or more of the above Purposes; and


(c) my Personal Information may/can be disclosed by any of the Insurers and/or GIA to their third party service providers or agents (including their lawyers/law firms), which may be sited outside of Singapore, for one or more of the above Purposes.

  
Policyholder's Signature / Date &  
Time

  
Driver's Signature (If driver is not the policyholder) / Date  
& Time

Witnessed by Reporting Centre  
Personnel

### Sketch Plan





### Circumstances of the Accident


On 13 Nov 2021 (Saturday) at about 17:20 hr I arrived at Upper Hokien St. ~~New Bridge Rd~~, Chinatown Point loading bay to fetch a passenger. There wasn't any parking lot available, I made a U-Turn and move to the side open space. I notice the driver of truck GBH 6145K, unloading some stuff at the rear of his vehicle. He saw me making U-turn. I then stop my car and shut the engine, roughly 2m away from this truck. My rear was facing the rear of the truck. I waited for the passenger about 5 to 10 mins, while I already put the gear to 'park' position. (mean hand brake was effect).

Suddenly, my car jerk forward, I came down to have a look. the driver of GBH 6145K came forward too (see photos). He apologised to me for hitting my car bumper while he reversed his truck. He claimed that he could not see my car behind him.

### Declaration

We declare the foregoing particulars are true in every respect.

  
Policyholder's Signature / Date & Time

  
Driver's Signature (If driver is not the policyholder) / Date & Time

\_\_\_\_\_  
Witnessed by Reporting Centre Personnel



> Back to OneMotoring

## Enquire PARF/COE Rebate for Registered Vehicle

Owner ID Type:	Singapore NRIC
Owner ID:	156Z
Vehicle No.:	SMK5738K
Vehicle to be Exported:	No
Intended Deregistration Date:	19 Nov 2021
Vehicle Make:	TOYOTA
Vehicle Model:	LEXUS ES300H 4DR SEDAN (AUTO) EXECUTIVE
Primary Colour:	Blue
Manufacturing Year:	2019
Engine No.:	A25A5166348
Chassis No.:	JTHB21B1202041232
Maximum Power Output:	160.0 kW (214 bhp)
Open Market Value:	\$45,594.00
Original Registration Date:	16 Apr 2019
First Registration Date:	16 Apr 2019
Transfer Count:	0
Actual ARF Paid:	\$55,832.00

PARF Eligibility:	Yes
PARF Eligibility Expiry Date:	15 Apr 2029
PARF Rebate Amount:	\$41,874.00

COE Expiry Date:	15 Apr 2029
COE Category:	B - Car above 1600cc or 97kW (130bhp)
COE Period(Years):	10
QP Paid:	\$43,102.00
COE Rebate Amount:	\$31,926.00
Total Rebate Amount:	\$73,800.00

The information contained herein is correct as at 19 Nov 2021

OK