

(08/11/13) wef

ASS. REC. BY:

REF:

CS/EQ121011665/R19f3

636c

ASSIGNMENT

From:

Date:

Estimated Cost:

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No: SMR 15660

at Workshop m/s TRANSEUROKARS

of 27A, TAN JONAH PIN JUREN

Insured: EQ1

Policy No.

Claims No. DM21HO01698/JG


Sum Insured: Excess:

(Client's Record)

Make of Veh:

(Policy Condition)

Remark: The veh had commenced its repair at the time of inspection.



Bal. or Market Value:

122k

IDAC Accident Rpt:

Consistent? : Yes or No

GIA / PR Seen:

Consistent? : Yes or No

Est. Repairs:

3

days

Res.: Yes or No

Lum Sum:

%

3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Date:

Person Contacted:

Vehicle: IN / OUT

Date / Time Action / Instruction

REPAIR LIMIT - 67K

19/11/21@5.21pm revised to Jaime Tay by email.

19/01/22@4.07pm Rasul email Jess, We will be advising our Principal a cost of repair of P/P \$3,407.20 / with 3 days of repair, subject to their approval. (Red \$2936.10, 46%)

Veh No:

SMR 15660

Yr Regn: 2019 / D6C

Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make:

MAZDA 6 SEDAN 2.5 PREMIUM S/R 2488

Colour:

GREY

A/C: Insured / Std / NI / NA

Sp. Reading

23973

T/Radio: Insured / Std / NI / NA

Eng/No:

C/No:

JM 64L 1032K0306839

Gen. Cond: Good / Fair / Poor / Burnt

Steering: In order / Jammed / Leaked / Burnt or

Brake: In order / Jammed / Leaked / Burnt or

Modi: Nil / S/Rim / STD A/Rim or

Tyre Size: F:

F:

225/45R19

R:

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or

Front

Rear

R/Bal.

6

mm

R/Bal.

6

mm

L/Bal.

6

mm

L/Bal.

6

mm

D.O.A.

11/11/21

D.O.I.

18/11/21

Survey held at

TRANSEUROKARS

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

The U/C / Chassis frame / Body Structure affected due to collision.

Date/Time, File Pass to?

☐

: Preli. Report

1) 03/02 Typist

☐

: Final Report

Date/Time, File Return to?

2)

Days Of Repair:

3

Resurvey No. of Trip:

1

Survey Fee:

Transportation:

Report Format :

TP

Lump Sum / I.B.I: (\$ 3407.20)

Add Fee:

☐

: Site Insp (\$

☐

: Interview (\$

☐

: Tech. Invs (\$

☐

: Weekend (\$

) S + RS, SI

) Photos

) Others

TOTAL



TRANS EUROKARS PTE LTD

27A TANJONG PENJURU, SINGAPORE 609042

ESTIMATE COST OF REPAIRS

EUROKARS SERVICES

INSURANCE COMPANY LTD

Maxwell Road

#17-00 Tower Block

MND Complex, Singapore 069110

ATTN.: MOTOR CLAIMS

FAX:

NAME:

ADDRESS:

TEL:

WIP: 43562

EXCESS:

DATE: 15-Nov-21

VEH NO:	SMR1566D	DATE IN:		CONTACT PERSON:	JESS
CHASSIS NO:	JM6GL1032K0306839	MILEAGE:		TYPE OF CLAIM:	THIRD PARTY CLAIM
MODEL:	MAZDA 6	DATE REG:	21-Dec-19	POLICY NO.:	

NATURE OF WORKS

NO	DESCRIPTION	QTY	UNIT PRICE	DISC(%)	1st	Supp	PARTS NO	REVISED	PRICES
1	REAR BUMPER <i>de /</i>	1	1,099.00	-			MGSK1-50-221ABB		1,099.00
2	TAPE, PROTECTOR <i>u /</i>	4	8.60	-			MGS1D-50-EM1A		34.40
3	RETAINER S.S ULTRASONIC CENTER <i>X</i>	2	15.50	-			MKD45-67-UC5AE4		31.00
4	SENSOR, ULTRASONIC CENTER <i>X</i>	1	180.90	-			MGMK6-67-UC1 E4		180.90
5	TAPE SEAL <i>re /</i>	2	13.70	-			MGSH7-50-2G1		27.40
6	BRACKET CENTER REAR BUMPER <i>X</i>	1	5.40	-			MDFR5-50-251		5.40
7	REINFORCEMENT REAR <i>?</i>	1	538.30	-			MGHK1-50-260		538.30
8	RIVET <i>re /</i>	2	9.20	-			MTK21-50-355		18.40
9	FASTENER <i>re /</i>	6	8.00	-			MEA01-50-037		48.00
10	CLIP <i>re /</i>	6	3.00	-			MB45A-56-146A		18.00
11	COVER TOWING HOOK REAR LH <i>X</i>	1	48.90	-			MGSH7-50-EL1 BB		48.90
12	COVER TOWING HOOK REAR RH <i>X</i>	1	46.60	-			MGSH7-50-EK1 BB		46.60
13	GASKET RH TAIL LAMP <i>re /</i>	1	46.00	-			MGRF5-51-153		46.00
14	GASKET LH TAIL LAMP <i>re /</i>	1	46.00	-			MGRF5-51-163		46.00
							TOTAL PARTS		2,188.30
							TOTAL PARTS COST		2,188.30

SUPPLEMENTARY

NO	DESCRIPTION	QTY	UNIT PRICE	DISC(%)	1st	Supp	PARTS NO	REVISED	PRICES
1									
2									
3									
							TOTAL PARTS		-
							TOTAL PARTS COST		-

Labour Description

		REVISED	PRICES
1	TO REPLACE REAR BUMPER AND REPAIR ALL AREAS AFFECTED BY THE ACCIDENTS.	660	1,220.00
2	TO RESPRAY REAR BUMPER, REAR REINFORCEMENT AND ALL AREAS AFFECTED BY THE ACCIDENTS.	630	1,575.00
3	MZ-BR-REVSEN TO TRANSFER REVERSE SENSORS.	330	660.00

4	MZ-BR-ELECTR	TO CHECK ELECTRICAL SYSTEM FOR PROPER FUNCTIONING.	180	280.00	
5	MZ-BR-REPROG	TO REPROGRAMME AFTER THE ACCIDENT REPAIR WORKS.	250	300.00	
6	MZ-BR-SUNDRI	SUNDRIES.	20	50.00	
REMARKS: THIS IS ONLY AN ESTIMATE FROM VISUAL INSPECTION AND SHOULD THERE BE MORE DAMAGES FOUND DURING THE PROCESS OF REPAIRING, YOU WILL BE INFORMED BEFORE THE REPAIRS ARE BEING CARRIED OUT. TAKE NOTE THAT SHOULD YOU DECIDE NOT TO PROCEED WITH THE REPAIRS, A QUOTATION FEE OF \$400 WILL BE APPLIED ACCORDINGLY FOR MAN-HOURS INVOLVED IN SOURCING FOR PARTS PRICE AS WELL AS LABOUR CHARGES			TOTAL LABOUR	-	4,155.00
			TOTAL PARTS	-	2,188.30
			TOTAL	-	6,343.30
			LESS EXCESS	-	-
			TOTAL AFTER EXCESS	-	6,343.30
			GST 7%	-	444.03
			GRAND TOTAL	-	6,787.33
SUPPLEMENTARY LABOUR DESCRIPTION					
				REVISED	PRICES
1		#N/A			
2		#N/A			
REMARKS: THIS IS ONLY AN ESTIMATE FROM VISUAL INSPECTION AND SHOULD THERE BE MORE DAMAGES FOUND DURING THE PROCESS OF REPAIRING, YOU WILL BE INFORMED BEFORE THE REPAIRS ARE BEING CARRIED OUT. TAKE NOTE THAT SHOULD YOU DECIDE NOT TO PROCEED WITH THE REPAIRS, A QUOTATION FEE OF \$400 WILL BE APPLIED ACCORDINGLY FOR MAN-HOURS INVOLVED IN SOURCING FOR PARTS PRICE AS WELL AS LABOUR CHARGES			TOTAL LABOUR	-	-
			TOTAL PARTS	-	-
			TOTAL	-	-
			LESS EXCESS	-	-
			TOTAL AFTER EXCESS	-	
			GST 7%	-	-
			GRAND TOTAL	-	-

TRANS EUROKARS PTE LTD

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer
 Signature:
 Date:

Authorised Signature

Rasul
 Hp 90010068
 3 days
 18/11/21 @ 1120
 Resy before paint

SINGAPORE ACCIDENT STATEMENT

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

ACCIDENT STATEMENT

Date of Submission 15/11/2021 17:47 (SGT)
Date of Accident 11/11/2021 15:57 (SGT)
Exact Location of Accident Jalan Bukit Merah, Singapore
Additional Location Information -
Country/State of Loss Singapore

DETAILS OF OWN VEHICLE

Vehicle Registration Number SMR1566D

INSURED/POLICYHOLDER

Is company? Yes
Name Of Registered Owner Eurokars Leasing (William Tan)
Company Reg No 1XXXXX636C
Email Address williamkoh@kaiser.sgi.com.sg
Mobile Phone No (Phone) +65-63310655
Alternative Phone No (Home) +65-63310655

VEHICLE PARTICULARS

Manufacturer Mazda
Model 6
Variant -
Exact purpose for which vehicle was being used at time of accident Private use
Are you claiming under your own insurance policy for repair to your vehicle? No - Claiming third party
Vehicle Category Private car
Transmission Auto
CC 1998

INSURANCE COMPANY

Name of Insurance Company Liberty Insurance Pte Ltd
Type of Coverage Comprehensive
Fleet Policy Yes
Policy Number -
Cover Note Number -

DRIVER

Name of Driver Koh Tiam Huat
NRIC No SXXXX232D

Date Of Birth	18/05/1960
Occupation	Indoor
Date Of Driving Pass	16/10/1981
Driving experience	40 YEARS AND 1 MONTH
Gender	Male
Mobile Number	(Phone) +65-97678515
Alt. Phone Number	-
Email Address	williamkoh@kaiser.sgi.com.sg
Address	23 Jalan Raja Udang #33-08 The Arte
Address complement	-
Postcode	329216
Is the driver the policyholder?	No
If No, Relationship of the Driver with the Insured	Rental
Does Driver Own Other Vehicles?	No
Vehicle Registration Number of Other Vehicle Owned by Driver	-
Insurance Company of Other Vehicle Owned by Driver	-

GENERAL INFORMATION OF THE ACCIDENT

Type of Accident	Collision - Head to Rear
Weather Conditions	Clear
Road Surface	Dry

OTHER INFORMATION

Was any foreign vehicle involved in the accident?	No
Number of vehicles involved in the accident	2
Was anybody injured in the Accident?	No
Was any injured conveyed to hospital by ambulance?	-
Was any other vehicle or property damaged?	Yes
Number of Passengers (Including Driver)	1
Has the driver been approached by unknown person(s) soliciting/offering accident claims assistance?	No

DETAILS OF POLICE ACTION

Was the accident reported to the police?	No
Was notice of intended Prosecution given?	No
If yes, against whom?	-

CIRCUMSTANCES OF ACCIDENT

Please refer to attached sketch plan

ATTACHMENT(S)

Are accident photos available for attachment?	Yes
Was there any video captured by Car Camera?	Yes
Was there any audio recorded?	No

DETAILS OF OTHER VEHICLE PROPERTY 1

Vehicle Registration Number	SLM116P
Vehicle Manufacturer	Mercedes
Vehicle Model	-
Vehicle Variant	-
Vehicle Colour	-
Vehicle Category	Private car
Name of Driver	Prakash Mohan
Contact Number	(Phone) +65-92331977
Address	-
Address complement	-

Postcode	-
Insurance Company Name	-
Nature Of Damage	-
Details of property damaged in accident	-
No. Of Passenger (Including Driver)	-

SKETCH PLAN

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any willful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. The report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
7. By the lodging of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.
8. Consent under the Personal Data Protection Act (PDPA)

I understand, acknowledge, agree and consent that:


- (a) My insurer, my workshop and the General Insurance Association of Singapore ("GIA") may/are permitted to collect, use, disclose and/or process my personal data/personal information set out in this [form] and any other personal information provided by me or possessed by my insurer (collectively the "Personal Information") and disclose and transfer such Personal Information to all insurer(s) who have insured vehicle(s) involved in this accident (all insurer(s) who have insured vehicle(s) involved in this accident and the insurers' lawyers/law firms, the Monetary Authority of Singapore and any relevant government agency/authority (such as the police), for the purposes of:
 - (i) processing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigations relating to the claims;
 - (ii) investigating the accident and/or my claims;
 - (iii) carrying out and/or dealing with my instructions or responding to any enquiries by me;
 - (iv) administering my claims (including the making of correspondence, statements, invoices, reports or notices to me, which could involve disclosure of certain personal data about me to bring about delivery of the same as well as on the external cover of envelope/postal packages); and/or
 - (v) complying with applicable law in administering, processing, handling and/or dealing with my claims.
 (collectively the "Purposes")
- (b) all insurer(s) who have insured vehicle(s) involved in this accident and the insurers' law firms/law firms, may/are permitted to collect, use, disclose and/or process my Personal Information for one or more of the above Purposes; and
- (c) my Personal Information may/can be disclosed by any of the insurers and/or GIA to their third party service providers or agents (including their lawyers/law firms), which may be sited outside of Singapore, for one or more of the above Purposes.

Policyholder's Signature / Date & Time

Driver's Signature (if driver is not the policyholder) / Date & Time

Witnessed by Reporting Centre Personnel

Sketch Plan



Describe Circumstances of the Accident

Accident happened along Baker Street Road towards Overway
Direction. Weather was clear and road condition dry.

Traffic light was a red so all vehicles stopped while waiting for it
to turn green.

Just as I was about to move the car vehicle SMP116P seems to be
moving quickly and hit my car. Please refer to the sketch.

The driver, Mr. Prabodh Anand admitted that he was not alert and
was looking at his Google map on the his mobile that's why he accelerated
without seeing the vehicle (which is SMP116P) in front of him.

We exchanged contact details and took pictures of the driving
license. There was no injury too.

Declaration


We declare the foregoing particulars are true in every respect.

Policyholder's Signature / Date &
Time



Driver's Signature (if driver is not the policyholder) / Date
& Time

2
12/11/2021

WITNESSED BY REPORTING CENTRE
PERSONNEL

> Back to OneMotoring

Enquire PARF/COE Rebate for Registered Vehicle

Owner ID Type:	Company
Owner ID:	636C
Vehicle No.:	SMR1566D
Vehicle to be Exported:	No
Intended Deregistration Date:	19 Nov 2021
Vehicle Make:	MAZDA
Vehicle Model:	MAZDA6 SEDAN 2.5 AT PREMIUM 2WD
Primary Colour:	Silver
Manufacturing Year:	2018
Engine No.:	PY21230142
Chassis No.:	JM6GL1032K0306839
Maximum Power Output:	143.0 kW (191 bhp)
Open Market Value:	\$25,412.00
Original Registration Date:	21 Dec 2019
First Registration Date:	21 Dec 2019
Transfer Count:	0
Actual ARF Paid:	\$27,577.00
PARF Eligibility:	Yes
PARF Eligibility Expiry Date:	20 Dec 2029
PARF Rebate Amount:	\$20,682.00
COE Expiry Date:	20 Dec 2029
COE Category:	E - Open - all except motorcycle
COE Period(Years):	10
QP Paid:	\$42,020.00
COE Rebate Amount:	\$33,803.00
Total Rebate Amount:	\$54,485.00

The information contained herein is correct as at 19 Nov 2021

OK

Mazda 6 2.5A Premium

Overview

[Financial](#)[Accessories](#)[Similar](#)[Research](#)[Photos](#)[Map](#)**Price****\$102,000****Depreciation** ⓘ

\$13,740 /yr

[View models with similar depre](#)**Reg Date**

22-May-2018

(6yrs 6mths 2days COE left)

Mileage

52,000 km (14.9k /yr)

Manufactured ⓘ

2018

Road Tax ⓘ

\$1,786 /yr

Transmission

Auto

Dereg Value ⓘ\$44,159 as of today ([change](#))**OMV** ⓘ

\$23,748

COE ⓘ

\$38,801

ARF ⓘ

\$25,248

Engine Cap

2,488 cc

Power

141.0 kW (189 bhp)

Curb Weight ⓘ

1,515 kg

No. of Owners

1

Type of Vehicle[Luxury Sedan](#)