

Without Prejudice to our driver's Injury claims

OUR REF: 85008888/SLV1791K/DOA/16/11/2021/KD

YOUR REF: GBJ3275C/--

14 December 2021 To: MOTOR CLAIMS DEPARTMENT INDIA INTERNATIONAL INSURANCE 64 CECIL STREET #04/#05 IOB BUILDING SINGAPORE 049711

ACCIDENT INVOLVING: SLV1791K AND GBJ3275C ON 16/11/2021

LOCATION ALONG : ALONG 24 PENJURU ROAD OPEN SPACE CAR PARK

We refer to the above mentioned incident with cost of repair and losses outlined as follows:

	Rate Per Day	Repair/ Claims Day	Amount Before GST	GST 7%	Amount After GST
Cost of Repair	\$ -	11	\$ 5,501.76	\$ 385.12	\$ 5,886.88
Loss Of Rental	\$ 90.95	11	\$ 1,000.45	\$ -	\$ 1,000.45
Loss Of Income	\$ 80.00	11	\$ 880.00	\$ -	\$ 880,00
LTA/GIA Search Fee	\$ -	0	\$ 7.00		
Towing Fee	\$ -	0	\$ -	\$ 0.45	\$ 7.45 \$ -
Total	\$ 187.43	11	\$ 7,389.21	\$385.57	\$ 7,774.78

The accident was caused solely by the negligence of your insured/driver, which resulted in the above costs of repair and losses.

Enclosed herewith the relevant documents for your perusal:

0	Letter of Demand) ©	
0	Repair Bill		Mileage Record
0	Finalised Report		Rental Invoice
0			Letter of Authority
0	Repair Estimate		Satisfaction Voucher
	Accident Report / Police Report	0	Certificate of Insurance
©	3 rd Party Search Fee	0	Towing (if applicable)

DIGILIFE TECHNOLOGIES LIMITED has authorised DING AUTO PTE LTD to claim, correspond, and receive payment on behalf of our client against any Third Party pertaining to the total sum stated above.

Please look into our client's claim and revert with your Liability/Offer within 14 days upon receipt of this Letter of Demand.

Your Sincerely, MOTOR CLAIMS DEPT DING AUTO PTE LTD TEL: +65 9239 4128

DING AUTO PTE LTD

Business Reg No: 201619222G BLK 10, #01-20 SIN MING IND EST. SEC C, SINGAPORE 575645

Tel: 6452 1208 Fax: 6452 0614

REPAIR BILL

M/S: INDIA INTERNATIONAL INSURANCE

DOA: 16/11/2021

OUR REF:

SLV 1791K

REF: CC4/III21011696/Eea3

DATE:

2/12/2021

OIC: Mr Asher Sng

ITEM NO.	DESCRIPTION	III	VIT PRICE	Τ	
1	Cost of Repair - SLV 1791K	\$		1	AMOUNT
	1 52. 1, 31K	. 4	5,501.76	\$	5,501.76
				1	
	1				
			1		
	1				
	·				
			1		
			1		
EMARKS:	Job Card: 85008888	CUP	10 m a v	,	
	Part By Part Repair	ľ	i	\$	5,501.76
	Tare Repair	GST (\$	385.12
		GRAN	D TOTAL S	\$	5,886.88

Yours faithfully,

Authorised Signature of Ding Auto Pte Ltd

Kelly Ding

From:

Steve Chen (LKK Auto) <SteveChen@lkkauto.com>

Sent:

Wednesday, 1 December 2021 9:13 PM

To:

Cc:

Taxis Customer Service

kelly.ding@dingauto.sg; sarah@dingautomotive.com; claims@dingautomotive.com; Asher Sng (LKKAuto)

Subject:

Re: 85008888 / SLV1791K - Finalize Amount, Before Paint & After Repair Photo .

(DOA: 16/11/2021)

Attachments:

SLV 1791 estimate.pdf; SLV1791K Supplementary.pdf; workshop final ESTIMATE.pdf

Hi Loong,

We confirm the finalize \$5501.76 (P/P, before GST). 5 repair days.

Thanks.

Best Regards,

Steve Chen | Automotive Assessor

LKK Auto Consultants Pte Ltd

Phone: 81117723/6256-3561 | email: <u>stevenfoong@lkkauto.com</u>| fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: Taxis Customer Service <taxiscs@stengg.com>

Sent: Wednesday, 1 December 2021 7:54 pm

To: Steve Chen (LKK Auto) <SteveChen@lkkauto.com>

Cc: kelly.ding@dingauto.sg <kelly.ding@dingauto.sg>; sarah@dingautomotive.com <sarah@dingautomotive.com>;

claims@dingautomotive.com <claims@dingautomotive.com>

Subject: 85008888 / SLV1791K - Finalize Amount, Before Paint & After Repair Photo . (DOA: 16/11/2021)

Without Prejudice

Dear Steve,

Please refer below for the finalize according to our conversation to finalize for SLV1791K.

Please refer to the attached Estimate, Before Paint & After Paint for SLV1791K.

Part By Part Repair

TO :

ESTIMATE REPORT

1ST Quotation

FAX NO:

17/11/2021 10:41

JOB-NO:

85008888

OWNER'S PARTICULARS

NAME: DIGILIFE TECHNOLOGIES LIN

CONTACT:

Page 1 of 2

ADDRESS: 152 UBI AVENUE 4

SINGAPORE (408826)

rakshan-rai@sev.com.sg

VEHICLE DETAILS

LICENSE NO: SLV1791K

TRANS: AUTO

CHASSIS: LC0CE4DB3H1026329

MAKE / MODEL: BYD

/ e6

ENGINE:

BYDTYC90B117003106

JOB-CODE: TP

OWNER'S INSURER: ALLIANZ GLOBAL CORPORATE & SPECIAL1

SA: Ding Auto User 1

CLAIM DETAILS

-	DESCRIPTION	QTY		DISCOUNT	DISC PRICE	: IND	SUR.DISP	REV
	ABOUR							PRICE
	TO STRAIGHTEN AND PANEL BEAT OF ACCIDENT AFFECTED AREA	1.00	1,600.00	0.00	1,600.00	600	Υ	
	TO RUST PROOFING OF THE AFFECTED AREA	1.00	180.00	0.00	180.00	30	Υ	
	TO REMOVE AND REFIT OF NECESSARY ITEMS TO FACILITATE BODYWORK REPAIR	1.00	300.00	0.00	300.00	Χ̈́	Y	
4	TO DIAGNOSTIC, CHECK WIRING AND LIGHTING SYSTEM AND CLEAR FAULT CODE	1.00	280.00	0.00	280.00	100	Υ.	
5	TO TRANSFER OF BOTH FRONT AND REAR DOOR MECHANISM TO NEW DOOR AND PERFORM WATER SEEPAGE TEST	1.00	260.00	0.00	260.00	100	Υ _	
	TO CONDUCT TYRE BALANCING AND WHEEL ALIGNMENT	1.00	160.00	0.00	160.00	60	Y _	
	TO CHECK AND REPAIR WIRE HARNESS	1.00	170.00	0.00	170.00	X :		
	TO RESPRAY REAR BUMPER	1.00	250.00	0.00	250.00	200	Υ_	
	TO RESPRAY REAR END PANEL	1.00	250.00	0.00		X	Υ _	
	TO RESPRAY REAR QUARTER PANEL	1.00	250.00	0.00	250.00	200	Υ_	 .
	TO RESPRAY REAR DOOR PANEL	1.00	250.00	0.00	250.00	210	Υ _	
	TO RESPRAY FRONT DOOR PANEL	1.00	250.00	0.00	250.00	200	Υ _	
	TO RESPRAY SIDE SKIRT RH	1.00	250.00	0.00		200	Υ_	
14	TO RESPRAY FRONT RH SIDE MIRROR	1.00	250.00	0.00		/	Y _	
	TOTAL:		4,700.00	0.00	250.00	50	Υ _	
	TERIALS		(29)-3		4,700.00			
1	FRONT RH DOOR PANEL / 1	1.00	(27,103	-0.00	terror e	1162-2	.>	
2	FRONT RH SIDE MIRROR ASSY - SK	1.00	0.00. 52	5-31 0.00	n.00	472	7 8	
3	FRONT RH DOOR GLASS / Cu1	1.00	0.00 149-		0.00		Υ _	
4	FRONT RH OUTER DOOR HANDLE	1.00	0.00403		0.00/34	•	Υ _	
5	FRONT RH DOOR LOCK	1.00	0.00 60		0.0036	_	Y	<u>'</u> ₩
6	FRONT RH DOOR UPPER WINDOW FRAME	1.00	0.00 16.			4. L12	Υ	
7	BLACK FILM FRONT RH POWER WINDOW REGULATOR	1.00	0.00 269	•	0.00 7	-5-2 42L·6	Y I	
Ω	ASSY		•		0.00 1	72L "	Y. —	
a	FRONT RH DOOR B-PILLAR BLACK FILM / MC FRONT RH OUTER DOOR HANDLE BASE		0.00 16-	(3 _{0.00}	0.00 (4	ֈ.Տ _Լ 2	Υ	
		1.00	0.00	0.00	0.00	L	γ –	
	, N	1.00	0.00 92.	(6 0.00 ·	0.00 82	.94 [, –	
	FRONT RH OUTER DOOR WEATHERSTRIP X	1.00	0.00 145.	15 0.00	0.00 (3	o. L63	, _	
12	FRONT RH OUTER DOOR HANDLE COVER 🗶	1.00	0.00	0.00	0.00	L	Υ	

QUOTED DISCOUNT DISC PRICE	
DECOMPTION	REV
13 FRONT RH POWER WINDOW REGULATOR N. 100 000	PRICE
I MOTOR	
14 REAR RH DOOR PANEL / 1.00 0.00 (223 + 2 0.00 0.00)	
1.00 0.00 lb-13 0.00	
1.00 0.00 15-13 0.00 0.00 11-13	
1.00 0.00 47-23 0.00 0.00 42-51 1	
1.00 0.00 2 59.20 0.00 0.00 2 77.1 00	
19 REAR RH POWER WINDOW REGULATOR X 1.00 0.00 0.00 0.00 L Y	
20 BEAD BY DOOD SLAGE	
21 FRONT PH DOOP FRAME WEATHERD THE Y	
22 REAR RH DOOR ERAME WEATHERDOTHIN X	
23 REAR RH DOOR B-PILLAR BLACK FILM < 47 100 0.00 471 L 53 Y	
24 REAR RH DOOR LIPPER WINDOW EDAME	
BLACK FILM	
25 REAR RH DOOR REAR FRAME SECTION / 1/1 1.00 0.00 13-82 0.00 0.00 12- 144 Y	
26 REAR RH OUTER DOOR WEATHERSTRIP X 1.00 0.00 177-4 0.00 0.00 159 67	
27 REAR RH TYRE RIM X K 1.00 0.00 564-48 0.00 0.00 508:03 — 7	80.00 spray Pant
28 REAR RH DOOR GLASS RUN X 1.00 0.00 (05-44,000 0.00 95-80	(0000
29 REAR BUMPER COVER X 1.00 0.00 315 760 00 0.00 344 1.10	
30 KEAR RH BUMPER REFLECTOR \$ 1.00 0.00 27-650.00 0.00 24. L 88	
GUIDE CHANNEL 1.00 0.00 35-14 0.00 0.00 3(- L63 Y	
32 REAR BUMPER CLIP SET / 1.00 70.00 0.00 70 70.00 S Y	ł
33 REAR RH DOOR STICKER - 1.00 250.00 0.00 CO 250.00	
35 SIDE SKIDT OLD OFT 446	
36 DOOR MOULENING OUR DESTE V	
35.00 0.00 55.00 S Y	
TOTAL: 685.00 0.00 685.00	
TOTAL PARTS & LABOUR: 5,385.00 0.00 5,385.00	
EXCESS/LOADING:S\$ 0.00	
No. Of Day:	
RE-SURVEY: BEFORE/AFTER PAINTING CLKK) IM	01
PART-BY-PART OR LLIMP SUM: 9¢	~ 10
DATE OF SURVEY: / / 1.11/21, 11.19cm	P/P
SURVEYED BY:	n Rel c.
CONTACT NO: FAX NO:	
NOTE: LUMP SUM AMOUNT WOULD BE REVISED IF SUPPLEMENT REPAIR IS REQUIRED DAuto001 Ding Auto User 1	days
ESTIMATOR	
STA AUTOCENTRE	1
TEL: FAX:	

DING AUTO PTE LTD

Vehicle:	SLV1791K
Model:	BYD E6
Chassis:	LCOCE4DB3H1026329

PARTS SUPPLEMENTARY & QUOTATION FORM

- 1			AHOI	V FOR	VIVI			
1	10		QTY		LIST	DISC	PRICE	SURVEYORS
-	1	UPPER FRONT GLASS GUIDE CHANNEL ASSY, FRONT WINDOW, R	1	\$	35.14	10%	\$ 31.63	MARKING
L_						PARTS	\$ 31.63	

SINGAPORE ACCIDENT STATEMENT

IMPORTANT NOTICE

- 1. Please report correctly the details of the accident to speed up the claims process.
 2. This Form must be completed by the Policyholder and/or the Authorised Driver
 3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or witholding of material facts may allow insurance companies to repudiate

- policy liability.

 4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.

 5. Any false reporting may be referred to the Police for Investigation.

 6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.

 7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

ACCIDE	NT STATEMENT
Date of Submission Date of Accident Exact Location of Accident Additional Location Information Country/State of Loss	16/11/2021 09:30 (SGT) 24 Penjuru Rd, Singapore 609128 ALONG 24 PENJURU ROAD OPEN SPACE CAR PARK, INSIDE
DETAILS (OF OWN VEHICLE
Vehicle Registration Number	SLV1791K
INSURED/POLICYHOLDER	
Is company? Name Of Registered Owner Company Reg No Email Address Mobile Phone No Alternative Phone No	Yes DIGILIFE TECHNOLOGIES LIMITED 1XXXXX568R RAKSHAN-RAI@SEV.COM.SG (Phone) +65-81565506 (Home) +65-81565506
VEHICLE PARTICULARS	
Manufacturer Model Variant Exact purpose for which vehicle was being used at time of	Byd E6h
Are you claiming under your own insurance policy for repair to your vehicle? Vehicle Category Transmission CC	Private hire No - Claiming third party Private hire Auto 0
INSURANCE COMPANY	
Name of Insurance Company Type of Coverage	Allianz Insurance Singapore Pte. Ltd. Comprehensive

SPMF1000000478

YEOH SU ANG

Fleet Policy Policy Number

Cover Note Number

Name of Driver

Date Of Birth SXXXXXXXXXXXXXXXXXXXXXXXXXXXXXXXXXXXX	NRIC No	
Outdoor Date Of Driving Pass 12/12/2008 Driving experience 12 YEARS AND 11 MONTHS Mail Months Number	Date Of Birth	SXXXX340D
Diving operations 12/12/2008 Driving operations 12/24/2008 Driving operations 12/24/2008 Male Mobile Number (Phone) + 658-84990077 All. Phone Number (Phone) + 668-84990077 All. Phone Number (Phone) + 6	Occupation	26,66,1675
Sender March Mar	Date Of Driving Pass	
Mobile Number All. Phone Number CPhone Number CPhone Number CETHAI Address Address Address Address Address Address Address Address Complement Postode She driver the policyholder? No If No. Relationship of the Driver with the Insured Hird Does Driver Own Other Vehicles? No Vehicle Registration Number of Other Vehicle Owned by Driver Insurance Company of Other Vehicle Owned by Driver Cesierral, ineformation or the Accident Type of Accident Cesierral, ineformation or the Accident Type of Accident Company of Other Vehicle Owned by Driver Cesierral, ineformation or the Accident Type of Accident Company of Other Vehicle Owned by Driver Cesierral, ineformation or the Accident Type of Accident Company of Other Vehicle Owned by Driver Cesierral, ineformation of the Accident Type of Accident Company of Other Vehicle Owned by Driver Type of Accident Company of Other Vehicle Owned by Driver Type of Accident Type of Accident Company of Other Vehicle Owned by Driver Type of Accident Company of Other Vehicle Owned by Driver Type of Accident Type of Accident Type of Accident Company of Other Vehicle Owned by Driver Type of Accident Type of Acc	Driving experience	
ARL Phone Number CPhone) +65-84990077 ARL Phone Number CPhone) +65-84990077 ARL Phone Number CPhone SPASSEV.COM.SG Address SHX 980A JURONG WEST STREET 93, #12-717, SINGAPORE SEA divers SHX 980A JURONG WEST STREET 93, #12-717, SINGAPORE SEA divers SHX 980A JURONG WEST STREET 93, #12-717, SINGAPORE SEA divers SHX 980A JURONG WEST STREET 93, #12-717, SINGAPORE SEA divers SHX 980A JURONG WEST STREET 93, #12-717, SINGAPORE SEA divers SHX 980A JURONG WEST STREET 93, #12-717, SINGAPORE SEA divers SHX 980A JURONG WEST STREET 93, #12-717, SINGAPORE SEA DIVERS SHX 980A JURONG WEST STREET 93, #12-717, SINGAPORE SEA DIVERS SHX 980A JURONG WEST STREET 93, #12-717, SINGAPORE SEA DIVERS SHX 980A JURONG WEST STREET 93, #12-717, SINGAPORE SEA DIVERS SHX 980A JURONG WEST STREET 93, #12-717, SINGAPORE SEA DIVERS SHX 980A JURONG WEST STREET 93, #12-717, SINGAPORE SEA DIVERS SHX 980A JURONG WEST STREET 93, #12-717, SINGAPORE SEA DIVERS SHX 980A JURONG WEST STREET 93, #12-717, SINGAPORE SEA DIVERS SHX 980A JURONG WEST STREET 93, #12-717, SINGAPORE SEA DIVERS SHX 980A JURONG WEST STREET 93, #12-717, SINGAPORE SEA DIVERS SHX 980A JURONG WEST STREET 93, #12-717, SINGAPORE SEA DIVERS SHX 980A JURONG WEST STREET 93, #12-717, SINGAPORE SEA DIVERS SHX 980A JURONG WEST STREET 93, #12-717, SINGAPORE SEA DIVERS SHX 980A JURONG WEST STREET 93, #12-717, SINGAPORE SEA DIVERS SHX 980A JURONG WEST STREET 93, #12-717, SINGAPORE SEA DIVERS SHX 980A JURONG WEST STREET 93, #12-717, SINGAPORE SEA DIVERS SHX 980A JURONG WEST STREET 93, #12-717, SINGAPORE SEA DIVERS SHX 980A JURONG WEST STREET 93, #12-717, SINGAPORE SEA DIVERS SHX 980A JURONG WEST STREET 93, #12-717, SINGAPORE SEA DIVERS SHX 980A JURONG WEST STREET 93, #12-717, SINGAPORE SEA DIVERS SHX 980A JURONG WEST STREET 93, #12-717, SINGAPORE SEA DIVERS SHX 980A JURONG WEST STREET 93, #12-717, SINGAPORE SEA DIVERS SHX 980A JURONG WEST STREET 93, #12-717, SINGAPORE SEA DI	Gender	12 12/1/0 AND 11 MONTHS
Email Address Address Address Address Complement Postocode She May San JURONG WEST STREET 93, #12-717, SINGAPORE BLK 989A JURONG WEST STREET 93, #12-717, SINGAPORE Address complement Postocode She driver the policyholder? If No, Relationship of the Driver with the Insured Hifter No West High Complement Does Driver Own Other Vehicles? No	Mobile Number	**
Chein Address Address complement Postcode Is the driver the policyholder? If No, Relationship of the Driver with the Insured Does Driver Own Other Vehicles? No Vehicle Registration Number of Other Vehicle Owned by Driver Insurance Company of Other Vehicle Owned by Driver Insurance Company of Other Vehicle Owned by Driver GENERAL INFORMATION OF THE ACCIDENT Type of Accident Weather Conditions Clear Dry OTHER INFORMATION Was any foreign vehicle involved in the accident? Was any other vehicle or property demaged? No PASSENCER I Name UNIKNOWN PETRILS OF POLICE ACTION Was the accident reported to the police? Was the accident reported to the police? No OPECALS OF POLICE ACTION Was notice of intended Prosecution given? OF If yes, against whom? OF If yes, against whom? OF IT YES TO NO ON 15.11.2021 AT ABOULT 0030 HOURS I WAS TRAVELLING STRAIGHT ALONG 24 PENJURU ROAD OPEN SPACE CAR PARK WITH ONE Fethal E PASSENGER ONES OARD, VEHICLE SI GEBUSZTSC) WHICH WAS TRAVELLING IN FRONT OF ME MADE A RIGHT TURN TO PARK HIS WHICLE AT ONE OF THE ERICE WAS INCOME. SUBDENLY, VEHICLE B MOVE FOR WAS INCOME. SUBDENLY, VEHICLE B MOVE F	Alt. Phone Number	(Phone) +65-84990077
Address complement Postsodde Stries of the Driver the policyholder? Address complement Postsodde Stries of the Driver with the Insured If No. Relationship of the Driver with the Insured Obes Driver (Own Other Vehicles) No. Weithold Registration Number of Other Vehicle Owned by Driver Insurance Compeny of Other Vehicle Owned by Driver SENERAL INFORMATION OF THE ACCIDENT Type of Accident Weather Conditions Clear Collision - Major/Minor Rd Clear Character Was any foreign vehicle involved in the accident? Was any foreign vehicle involved in the accident? Was any injured conveyed to hespital by ambulance? O'THER INFORMATION Was any injured conveyed to hespital by ambulance? - Vas any injured conveyed to hespital by ambulance? - Vas any injured conveyed to hespital by ambulance? - Vas any injured conveyed to hespital by ambulance? - Vas any injured conveyed to hespital by ambulance? - Vas any injured conveyed to hespital by ambulance? - Vas any injured conveyed to hespital by ambulance? - Vas any injured conveyed to hespital by ambulance? - Vas any injured conveyed to hespital by ambulance? - Vas any injured conveyed to hespital by ambulance? - Vas any injured conveyed to hespital by ambulance? - Vas any injured conveyed to hespital by ambulance? No No No No PASSENGER 1 Was arbs accident dalms assistance? No Was notice of intended Prosecution given? No Was the accident reported to the police? No	Email Address	-
Address complement Postcode St the driver the policyholder? If No, Relationship of the Driver with the Insured Does Driver Own Other Vehicles? Who Publice Registration Number of Other Vehicle Owned by Driver Insurance Compeny of Other Vehicle Owned by Driver Insurance Compeny of Other Vehicle Owned by Driver GENERAL INFORMATION OF THE ACCIDENT Type of Accident Weather Conditions Clear Road Surface Dry OTHER INFORMATION Was any foreign vehicle involved in the accident? No Number of vehicles involved in the accident 2 Was any hipured or the Accident Was any hipured or the Accident? No Was any hipured or the Accident? No Name or vehicle or properly damaged? No	Address	OPS@SEV.COM.SG
Postode Stroke Stroke Hoppicyholder? And Stroke Hoppicyholder? No If No, Relationship of the Driver with the Insured Hirer No Obes Driver Own Other Vehicles? No Hirer No No Hirer Hoppicy Hoppicy Hirer No No Hirer Hoppicy Hoppicy Hirer Hoppicy Hoppicy Hirer No No Hirer Hoppicy Hoppicy Hirer Hirer Hoppicy Hirer	Address complement	BLK 989A JURONG WEST STREET 93, #12-717, SINGAPORE
IS the driver the policyholder? If No, Relationship of the Driver with the Insured Does Driver Own Other Vehicles? Wehicle Registration Number of Other Vehicle Owned by Driver Insurance Company of Other Vehicle Owned by Driver GENERAL INFORMATION OF THE ACCIDENT Type of Accident Weather Conditions Clear Dry OTHER INFORMATION OTHER INFORMATION Was any foreign vehicle involved in the accident? No Number of vehicles involved in the accident 2 Was any injured on the Accident Was any injured on the Accident? No Was any injured conveyed to hospital by ambulance? No Was any injured by the Accident? No Number of Passengers (Including Driver) 12 Has the driver bene approached by unknown person(s) soliciting/offering accident claims assistance? No No Name Gender DETAILS OF POLICE ACTION Was the accident reported to the police? Was the accident reported to the police? Was the accident reported to the police? No Was notice of intended Prosecution given? If yes, against whom? CIRCUMSTANCES OF ACCIDENT ON 16.11.2021 AT ABOUT 930 HOURS, I WAS TRAVELLING STRAIGHT ALONG 24 PENJURU ROAD OPEN SPACE CAR PARK WITH ONE FEMALE PASSENGER ONBOARD, VEHICLE B (GBI327SC) WHICH WAS TRAVELLING IN STRAVELLING IN STRAVEL IN STRAVEL IN STRAVEL IN STRAVEL IN STRAVEL IN STR	Postcode	-
DOES DIVER Own Other Vehicles? Vehicle Registration Number of Other Vehicle Owned by Driver Insurance Company of Other Vehicle Owned by Driver Insurance Company of Other Vehicle Owned by Driver GENERAL INFORMATION OF THE ACCIDENT Type of Accident Weather Conditions Clear Dry OTHER INFORMATION Was any foreign vehicle involved in the accident? Was any foreign vehicle involved in the accident? Was any foreign vehicle involved in the accident 2 Was any proving the Accident 2 Was any proving the Accident? No Was any other vehicle or property damaged? Was not of the driver been approached by unknown person(s) soliciting/offering accident claims assistance? No PASSENGER 1 Name UNKNOWN Femalo DETAILS OF POLICE ACTION Was the accident reported to the police? Was the accident reported to the police? No No 16.11.2021 AT ABOUT 0930 HOURS, I WAS TRAVELLING STRAIGHT ALONG 24 PENJURU ROAD OPEN SPACE CAR PARK WITH ONE FEMALE PASSENGER ONBOARD. VEHICLE B (GBJ327SC) WHICH WAS TRAVELLING IN FRONT OF ME MADE A ONLY HURN TO PARK HIS VEHICLE AT ONE OF THE EMPTY PARKING LOT WITHOUT TURNING THE SIGNAL LIGHT ON 16.11.2021 AT ABOUT 0930 HOURS, I WAS TRAVELLING STRAIGHT ALONG 24 PENJURU ROAD OPEN SPACE CAR PARK WITH ONE FEMALE PASSENGER ONBOARD. VEHICLE B (GBJ327SC) WHICH WAS TRAVELLING IN FRONT OF ME MADE A ONLY HURN TO PARK HIS VEHICLE AT ONE OF THE EMPTY PARKING LOT WITHOUT TURNING THE SIGNAL LIGHT ON 16.11.2021 AT ABOUT 0930 HOURS, I WAS TRAVELLING STRAIGHT ALONG 24 PENJURU ROAD OPEN SPACE CAR PARK WITH ONE FEMALE PASSENGER ONBOAR	is the driver the policyholder?	
Vehicle Registration Number of Other Vehicle Owned by Driver Insurance Company of Other Vehicle Owned by Driver GENERAL INFORMATION OF THE ACCIDENT Type of Accident Weather Conditions Clear Upen of Accident Weather Conditions Clear On TER INFORMATION Was any foreign vehicle involved in the accident? Was any foreign vehicle involved in the accident? Was any foreign vehicle involved in the accident? Was any injured conveyed to hospital by ambulance? Vas any vinjured conveyed to hospital by ambulance? Vas any vinjured conveyed to hospital by ambulance? Vas any vinjured revelicle or property damaged? Vas any vinjured conveyed to hospital by ambulance? Vas any vinjured conveyed to hospital by ambulance? Vas any vinjured vehicle or property damaged? Vas any vinjured conveyed to hospital by ambulance? Vas Conveyed to hospital by ambulance? Vas the accident reported to the police? No No No No No No No No No N	If No, Relationship of the Driver with the Insured	-
This program of Other Vehicle Owned by Driver Insurance Company of Other Vehicle Owned by Driver GENERAL INFORMATION OF THE ACCIDENT Type of Accident Weather Conditions Clear Dry OTHER INFORMATION Was any foreign vehicle involved in the accident? Was any foreign vehicle involved in the accident? Was any foreign vehicle involved in the accident? Was any injured conveyed to hospital by ambulance? Was any other vehicle or properly damaged? Yes Number of Passengers (Including Driver) 2 Has the driver been approached by unknown person(s) soliciting/offering accident claims assistance? No Name UNKNOWN Femala DETAILS OF POLICE ACTICN Was the accident reported to the police? Was notice of intended Prosecution given? No If yes, against whom? CIRCUMSTANCES OF ACCIDENT ON 16.11.2021 AT ABOUT 0930 HOURS, I WAS TRAVELLING STRAIGHT ALONG 24 PENJURU ROAD OPEN SPACE CAR PARK WITH DNE FEMALE PASSENGER ONBOARD. VEHICLE B (GBL3275C) WHICH WAS TRAVELLING IN FRONT OF ME MADE A RIGHT TURN TO PARK HIS VEHICLE AT ION OF THE EMPTY PARKING LOTH WAS TRAVELLING IN FRONT OF ME MADE A RIGHT TURN TO PARK HIS VEHICLE AT ION OF THE EMPTY PARKING LOTH UNINEN THE SIGNAL LIGHT ON, THUS, I PROCEED TO DRIVE OFF MY VEHICLE WITHIN MY OWN LANE. SUDDENT, VEHICLE AND HIT ONTO MY VEHICLE RHOM THE CAR PARK LOT WITHOUT CHECKING FOR ONCOMING VEHICLE AND HIT ONTO MY VEHICLE RHOM THE CAR PARK LOT WITHOUT CHECKING FOR ONCOMING VEHICLE AND HIT ONTO MY VEHICLE RHOM THE CAR PARK LOT WITHOUT CHECKING FOR ONCOMING VEHICLE AND HIT ONTO MY VEHICLE RHOM THE CAR PARK LOT WITHOUT CHECKING FOR ONCOMING VEHICLE AND HIT ONTO MY VEHICLE RHOM THE CAR PARK LOT WITHOUT CHECKING FOR ONCOMING VEHICLE AND HIT ONTO MY VEHICLE RHOM THE CAR PARK LOT WITHOUT CHECKING FOR ONCOMING VEHICLE AND HIT ONTO MY VEHICLE RHOM THE CARE PARK LOT WITHOUT CHECKING FOR ONCOMING VEHICLE AND HIT ONTO MY VEHICLE RHOM THE	Does Driver Own Other Vehicles?	
Insurance Company of Other Vehicle Owned by Driver GENERAL INFORMATION OF THE ACCIDENT Type of Accident Weather Conditions Clear Dry OTHER INFORMATION Was any foreign vehicle involved in the accident? No Number of vehicles involved in the accident 2 No Was any injured to the Accident? Was any injured conveyed to hospital by ambulance? Ves any other vehicle or property damaged? Ves Aurober of Passengers (including Driver) 2 last the drive rehicle or property damaged? Ves Number of Passengers (including Driver) 2 last the drive approached by unknown parson(s) soliciting/offering accident claims assistance? No PASSENGER 1 Name UNKNOWN Gender DETAILS OF POLICE ACTION! Was the accident reported to the police? No If yes, against whom? ON 16.11.2021 AT ABOUT 0930 HOURS, I WAS TRAVELLING STRAIGHT ALONG 24 PENJURU ROAD OPEN SPACE CAR PARK WITH OWN FERMALE PASSENGER ON SUBCARDAN VEHICLE BY GOB STRAIGHT ALONG 24 PENJURU ROAD OPEN SPACE CAR PARK WITH OWN FERMALE PASSENGER ON SUBCARDAN VEHICLE BY GOB STRAIGHT ALONG 24 PENJURU ROAD OPEN SPACE CAR PARK WITH OWN FERMALE PASSENGER ON SUBCARDA VEHICLE BY GOB STRAIGHT ALONG 24 PENJURU ROAD OPEN SPACE CAR PARK WITH OWN FERMALE PASSENGER ON SUBCARDA VEHICLE BY GOB STRAIGHT ALONG 24 PENJURU ROAD OPEN SPACE CAR PARK WITH OWN FERMALE PASSENGER ON SUBCARDA VEHICLE BY GOB STRAIGHT ALONG 24 PENJURU ROAD OPEN SPACE CAR PARK WITH OWN FERMALE PASSENGER ON SUBCARDA VEHICLE BY GOB STRAIGHT ALONG 24 PENJURU ROAD OPEN SPACE CAR PARK WITH OWN FERMALE PASSENGER ON SUBCARDA VEHICLE BY GOB STRAIGHT ALONG 24 PENJURU ROAD OPEN SPACE CAR PARK WITH OWN FERMALE PASSENGER ON SUBCARDA VEHICLE BY GOB STRAIGHT ALONG 24 PENJURU ROAD OPEN SPACE CAR PARK WITH OWN FERMALE PASSENGER ON SUBCARDA VEHICLE BY CORPORATION FINE SUBCARDA VEHICLE BY CORPORAT	Vehicle Registration Number of Other Vehicle Owned by Driver	No
GENERAL INFORMATION OF THE ACCIDENT Type of Accident Weather Conditions Clear Road Surface Dry OTHER INFORMATION Was any foreign vehicle involved in the accident? Was any foreign vehicle involved in the accident? Was any foreign vehicle involved in the accident? Was any injured on veryed to hospital by ambulance? - Was any injured conveyed to hospital by ambulance? - Was any injured conveyed to hospital by ambulance? - Was any injured conveyed to hospital by ambulance? - Was any other vehicle or property damaged? - Yes Number of Passengers (Including Driver) - Soliciting/offering accident claims assistance? No PASSENGER 1 Name UNKNOWN Gender DETAILS OF POLICE ACTION Was the accident reported to the police? Was notice of intended Prosecution given? - CIRCUMSTANCES OF ACCIDENT ON 16.11.2021 AT ABOUT 0930 HOURS, I WAS TRAVELLING STRAIGHT ALONG 24 PENJURU ROAD OPEN SPACE CAR PARK WITH ONE FEMALE PASSENGER ONBOARD. VEHICLE E (GBJ327SC) WHICH WAS TRAVELLING IN FRONT OF ME MADE A RIGHT TURN TO PARK HIS VEHICLE E NO NE OF THE EMPTY PARKING OT WITHOUT TURNING THE SIGNAL LIGHT ON TO PARK HIS VEHICLE E NO NE OF THE EMPTY PARKING OT WITHOUT TURNING THE SIGNAL LIGHT ON THE CAR PARK LOT WITHOUT CHECKING FOR ONCOMING VEHICLE AND HIT ONTO MY VEHICLE RH SIDE PORTION. ATTACHMENT(S) Are accident photos available for attachment? Yes Was there any video captured by Car Camera? Yes Was there any video captured by Car Camera? Yes Was there any video captured by Car Camera? Yes Was there any video captured by Car Camera? Yes Was there any video captured by Car Camera? Yes	***************************************	
GENERAL INFORMATION OF THE ACCIDENT Type of Accident Weather Conditions Collear Conditions Road Surface Dry OTHER INFORMATION Was any foreign vehicle involved in the accident? No Number of vehicles involved in the accident 2 Was any foreign vehicle involved in the accident 2 Was any injured conveyed to hospital by ambulance? Was any injured conveyed to hospital by ambulance? Was any other vehicle or property damaged? Was the driver been approached by unknown person(s) soliciting/offering accident claims assistance? No PASSENGER 1 Name UNKNOWN Gender DETAILS OF POLICE ACTION Was the accident reported to the police? Was notice of intended Prosecution given? No If yes, against whom? CHICLUMSTANCES OF ACCIDENT ON 16.11.2021 AT ABOUT 0830 HOURS, I WAS TRAVELLING STRAIGHT ALONG 24 PENJURU ROAD OPEN SPACE CAR PARK WITH OME FEMALE PASSENGER ON DROARD. VEHICLE E B (GBJ327SC) WHICH WAS TRAVELLING IN FRONT OF ME MADE A RIGHT TURN ID PARK HIS VEHICLE AT ONE OF THE BERTY PARKING LOT WITHOUT TURNING IT PESIGNAL LIGHT ON, IT HUS, I PROCEED TO DRIVE OFF MY VEHICLE WITHIN MY OWN LANE. SUDDENLY, VEHICLE B MOVE FORWARD HIS PORTION. ATTACHMENT(S) Are accident photos available for attachment? Yes Was there any video captured by Car Camera? Yes Was there any video captured by Car Camera? Yes Was there any video captured by Car Camera? Yes Was there any video captured by Car Camera? Yes Was there any video captured by Car Camera? Yes Was there any video captured by Car Camera? Yes	Insurance Company of Other Vehicle Owned by Driver	_
Type of Accident Weather Conditions Collair Clear Dry OTHER INFORMATION Was any foreign vehicle involved in the accident? No Number of vehicles involved in the accident 2 Was any shody injured in the Accident? No No Number of vehicles involved in the accident 2 Was any shody injured on the Accident? No No No Nasa any injured conveyed to hospital by ambulance? Vas any other vehicle or property demaged? Yes Number of Passengers (Including Driver) 2 Has the driver been approached by unknown person(s) soliciting/offering accident claims assistance? No PASSENGER 1 Name Gender DETAILS OF POLICE ACTION Was notice of intended Prosecution given? No Was notice of intended Prosecution given? No CIRCUMSTANCES OF ACCIDENT ON 16.11.2021 AT ABOUT 0930 HOURS, I WAS TRAVELLING STRAIGHT ALONG 24 PENJURU ROAD OPEN SPACE CAR PARK WITH ONE FEMALE PASSENGER ONBOARD. VEHICLE B (GBJ327SC) WHICH WAS TRAVELLING IN FRONT OF ME MADE A RIGHT TURN TO PARK HIS VEHICLE AT ONE OF THE EMPTY PARKING LOT WITHOUT TURNING THE SIGNAL LIGHT ON, THUS, I PROCEED TO DRIVE OFF MY VEHICLE WITHIN MY OWN LANE. SUDDENLY, VEHICLE B MOVE FORWARD HIS VEHICLE FROM THE CAR PARK LOT WITHOUT CHECKING FOR ONCOMING VEHICLE AND HIT ONTO MY VEHICLE RH SIDE PORTION. ATTACHMENT(S) Are accident photos available for attachment? Yes Was there any video captured by Car Camera? Yes Was there any video captured by Car Camera? Yes Was there any video captured by Car Camera? Yes Was there any video captured by Car Camera? Yes	2890 - 280 - 100 -	-
Was any foreign vehicle involved in the accident? OTHER INFORMATION Was any foreign vehicle involved in the accident? No Number of vehicles involved in the accident 2 Was any jointed on the Accident? Was any jointed on the Accident? Was any injured conveyed to hospital by ambulance? Was any other vehicle or property damaged? Ves No No No Saray other vehicle or property damaged? Ves No Soliciting/offering accident claims assistance? No PASSENGER 1 Name UNKNOWN Gender UNKNOWN Female DETAILS OF POLICE ACTION Was the accident reported to the police? Was anotice of intended Prosecution given? No CIRCUMSTANCES OF ACCIDENT ON 16.11.2021 AT ABOUT 0830 HOURS, I WAS TRAVELLING STRAIGHT ALONG 24 PENJURU ROAD OPEN SPACE CAR PARK WITH ONLE FEMALE PASSENGER ON SOARD. VEHICLE B (GBJ3275C) WHICH WAS TRAVELLING IN FROM THE CAR PARK HIS VEHICLE AT ONLE OF HEICLE B (GBJ3275C) WHICH WAS TRAVELLING IN FROM TO OF ME MADE A RIGHT TURN TO PARK HIS VEHICLE ONLO OF THE METHY PARKING LOT WITHOUT TURNING THE SIGNAL LIGHT ON 11HUS, I PROCEED TO DRIVE OFF MY VEHICLE WITHIN MY OWN LANE. SUDDENLY, VEHICLE B MOVE FORWARD HIS VEHICLE FROM THE CAR PARK LOT WITHOUT CHECKING FOR ONCOMING VEHICLE AND HIT ONTO MY VEHICLE RH SIDE PORTION. ATTACHMENT(S) ATTACHMENT(S) Are accident photos available for attachment? Yes Was there any video captured by Car Camera? Yes Was there any video captured by Car Camera? Yes Was there any video captured by Car Camera? Yes Was there any video captured by Car Camera? Yes	는 사용하는 것이다. 기계는 경상에 대표하는 경상에 가장하는 것이 있는 것이 없는 것이 없는 것이 되었다. 	
Road Surface Dry OTHER INFORMATION Was any foreign vehicle involved in the accident? No No Number of vehicles involved in the accident 2 Was anybody injured in the Accident? No No Was any injured conveyed to hospital by ambulance? - Was any injured conveyed to hospital by ambulance? - Was any injured rehicle or property damaged? Yes Number of Passengers (Including Driver) 2 Has the driver been approached by unknown person(s) soliciting/offering accident claims assistance? No No PASSENGER 1 Name UNKNOWN Female DETAILS OF POLICE ACTION Was the accident reported to the police? No No Was notice of intended Prosecution given? No If yes, against whom? - CIRCUMSTANCES OF ACCIDENT ON 16.11.2021 AT ABOUT 0930 HOURS, I WAS TRAVELLING STRAIGHT ALONG 24 PENJURU ROAD OPEN SPACE CAR PARK WITH ONE FEMALE PASSENGER ONSOARD, VEHICLE B (GBJ3275C) WHICH WAS TRAVELLING IN FRONT OF ME MADE A RIGHT TURN TO PARK HIS VEHICLE AT ONE OF THE EMPTY PARKING LOT WITHOUT TURNING THE SIGNAL LIGHT NO. 1.11U.S. I PROCEED TO DRIVE OFF MY VEHICLE WITHIN MY OWN LANE. SUDDENLY, VEHICLE B MOVE FORWARD HIS VEHICLE FROM THE CAR PARK LOT WITHOUT CHECKING FOR ONCOMING VEHICLE AND HIT ONTO MY VEHICLE RH SIDE PORTION. ATTACHMENT(S) Are accident photos available for attachment? Yes Was there any video captured by Car Camera? Yes Was there any video captured by Car Camera? Yes	Weather Conditions	Collision - Major/Minor Rd
OTHER INFORMATION Was any foreign vehicle involved in the accident? No Number of vehicles involved in the accident 2 Was anybody injured in the Accident? No Was anybody injured in the Accident? Was any injured conveyed to hospital by ambulance? Yes Number of Passengers (including Driver) 2 Has the driver been approached by unknown person(s) soliciting/offering accident claims assistance? No PASSENGER 1 Name UNKNOWN Gender DETAILS OF POLICE ACTION Was notice of intended Prosecution given? No Uryes, against whom? CIRCUMSTANCES OF ACCIDENT ON 16.11.2021 AT ABOUT 0930 HOURS, I WAS TRAVELLING STRAIGHT ALONG 24 PENJURU ROAD OPEN SPACE CAR PARK WITH ONE FEMALE PASSENGER ONBOARD. VEHICLE B (GBJ3275C) WHICH WAS TRAVELLING IN FRONT OF ME MADE A RIGHT TURN TO PARK HIS VEHICLE AT ONE OF THE EMPTY PARKING LOT WITHOUT TURNING THE SIGNAL LIGHT ON. THUS, I PROCEED TO DRIVE OFF MY VEHICLE WITHIN MY OWN LANE. SUDDENLY, VEHICLE B MOVE FORWARD HIS VEHICLE FROM THE CAR PARK LOT WITHOUT CHECKING FOR ONCOMING VEHICLE AND HIT ONTO MY VEHICLE RH SIDE PORTION. ATTACHMENT(S) Are accident photos available for attachment? Yes Was there any video captured by Car Camera? Yes Was there any video captured by Car Camera? Yes Was there any audio recorded? No	Road Surface	Clear
Was any foreign vehicle involved in the accident? Was any foreign vehicles involved in the accident 2 Was anybody injured in the Accident? Was any other vehicles property damaged? Was any other vehicle or property damaged? Was the driver been approached by unknown person(s) Soliciting/offering accident claims assistance? No PASSENGER 1 UNKNOWN Female DETAILS OF POLICE ACTION Was the accident reported to the police? No Was notice of intended Prosecution given? No If yes, against whom? CIRCUMSTANCES OF ACCIDENT CIRCUMSTANCES OF ACCIDENT ON 16.11.2021 AT ABOUT 0930 HOURS, I WAS TRAVELLING STRAIGHT ALONG 24 PENJURU ROAD OPEN SPACE CAR PARK WITH ONE FEMALE PASSENGER ONBOARD. VEHICLE B (GBJ327SC) WHICH WAS TRAVELLING IN FRONT OF ME MADE A ROIGHT TURN TO PARK HIS VEHICLE AT ONE OF THE EMPTY PARKING LOT WITHOUT TURNING THE SIGNAL LIGHT ON, THUS, I PROCEED TO DRIVE OFF MY VEHICLE WITHIN MY OWN LANE. SUDDENLY, VEHICLE B MOVE FORWARD HIS VEHICLE FROM THE CAR PARK LOT WITHOUT CHECKING FOR ONCOMING VEHICLE AND HIT ONTO MY VEHICLE RH SIDE PORTION. ATTACHMENT(S) ATTACHMENT(S) Are accident photos available for attachment? Yes Was there any video captured by Car Camera? Yes Was there any video captured by Car Camera? Yes Was there any sudio recorded? No	Hodd Guilace	Dry
Was any obly oilpured in the Accident 2 Was any body injured in the Accident? No Was any injured conveyed to hospital by ambulance? - Was any other vehicle or property damaged? Yes Wumber of Passengers (including Driver) 2 Has the driver been approached by unknown person(s) soliciting/offering accident claims assistance? No PASSENGER 1 Name UNKNOWN Gender Pemale DETAILS OF POLICE ACTION Was the accident reported to the police? No Was notice of intended Prosecution given? No If yes, against whom? - CIRCUMSTANCES OF ACCIDENT CIRCUMSTANCES OF ACCIDENT ON 16.11.2021 AT ABOUT 0930 HOURS, I WAS TRAVELLING STRAIGHT ALONG 24 PENJURU ROAD OPEN SPACE CAR PARK WITH ONE FEMALE PASSENGER ONBOARD VEHICLE B (GBJ3275C) WHICH WAS TRAVELLING IN FRONT OF ME MADE A RIGHT TURN TO PARK HIS VEHICLE AT ONE OF THE EMPTY PARKING LOT WITHOUT TURNING THE SIGNAL LIGHT ON.THUS, I PROCEED TO DRIVE OFF MY VEHICLE WITHIN MY OWN LANE. SUDDENLY, VEHICLE B MOVE FORWARD HIS PORTION. ATTACHMENT(S) ATTACHMENT(S) Are accident photos available for attachment? Yes Was there any video captured by Car Camera? Yes Was there any video captured by Car Camera? Yes Was there any video captured by Car Camera? Yes Was there any video captured by Car Camera? Yes	OTHER INFORMATION	
Was any obly oilpured in the Accident 2 Was any body injured in the Accident? No Was any injured conveyed to hospital by ambulance? - Was any other vehicle or property damaged? Yes Wumber of Passengers (including Driver) 2 Has the driver been approached by unknown person(s) soliciting/offering accident claims assistance? No PASSENGER 1 Name UNKNOWN Gender Pemale DETAILS OF POLICE ACTION Was the accident reported to the police? No Was notice of intended Prosecution given? No If yes, against whom? - CIRCUMSTANCES OF ACCIDENT CIRCUMSTANCES OF ACCIDENT ON 16.11.2021 AT ABOUT 0930 HOURS, I WAS TRAVELLING STRAIGHT ALONG 24 PENJURU ROAD OPEN SPACE CAR PARK WITH ONE FEMALE PASSENGER ONBOARD VEHICLE B (GBJ3275C) WHICH WAS TRAVELLING IN FRONT OF ME MADE A RIGHT TURN TO PARK HIS VEHICLE AT ONE OF THE EMPTY PARKING LOT WITHOUT TURNING THE SIGNAL LIGHT ON.THUS, I PROCEED TO DRIVE OFF MY VEHICLE WITHIN MY OWN LANE. SUDDENLY, VEHICLE B MOVE FORWARD HIS PORTION. ATTACHMENT(S) ATTACHMENT(S) Are accident photos available for attachment? Yes Was there any video captured by Car Camera? Yes Was there any video captured by Car Camera? Yes Was there any video captured by Car Camera? Yes Was there any video captured by Car Camera? Yes	Was any foreign vehicle involved in the assistance	· · · · · · · · · · · · · · · · · · ·
Was any other vehicle or property damaged? Ves No PASSENGER 1 Name UNKNOWN Gender DETAILS OF POLICE ACTION Was the accident reported to the police? No Was notice of intended Prosecution given? No If yes, against whom? CIRCUMSTANCES OF ACCIDENT ON 16.11.2021 AT ABOUT 0930 HOURS, I WAS TRAVELLING STRAIGHT ALONG 24 PENJURU ROAD OPEN SPACE CAR PARK WITH ONE FEMALE PASSENGER ONBOARD. VEHICLE B (GBJ3275C) WHICH WAS TRAVELLING IN FRONT OF ME MADE A RIGHT TURN TO PARK HIS VEHICLE AT ONE OF THE EMPTY PARKING LOT WITHOUT TURNING THE SIGNAL LIGHT ON. THUS, I PROCEED TO DRIVE OFF MY VEHICLE WITHIN MY OWN LANE. SUDDENLY, VEHICLE B MOVE FORWARD HIS PORTION. ATTACHMENT(S) Are accident photos available for attachment? Yes Was there any video captured by Car Camera? Yes Was there any video captured by Car Camera? Yes Was there any video captured by Car Camera? Yes Was there any video captured by Car Camera? Yes Was there any video captured by Car Camera? Yes Was there any video captured by Car Camera? Yes	Number of vehicles involved in the accident?	No
Was any injured conveyed to hospital by ambulance? Was any other vehicle or property damaged? Number of Passengers (Including Driver) 2 Has the driver been approached by unknown person(s) soliciting/offering accident claims assistance? No PASSENGER 1 Name UNKNOWN Gender DETAILS OF POLICE ACTION Was the accident reported to the police? Was notice of intended Prosecution given? No If yes, against whom? CIRCUMSTANCES OF ACCIDENT ON 16.11.2021 AT ABOUT 0930 HOURS, I WAS TRAVELLING STRAIGHT ALONG 24 PENJURU ROAD OPEN SPACE CAR PARK WITH ONE FEMALE PASSENGER ONBOARD. VEHICLE B (GBJ3275C) WHICH WAS TRAVELLING IN FRONT OF ME MADE A RIGHT TURN TO PARK HIS VEHICLE AT ONE OF THE EMPTY PARKING LOT WITHOUT TURNING THE SIGNAL LIGHT ON. THUS, I PROCEED TO DRIVE OFF MY VEHICLE WITHIN MY OWN LANE. SUDDENLY, VEHICLE B MOVE FORWARD HIS VEHICLE FROM THE CAR PARK LOT WITHOUT CHECKING FOR ONCOMING VEHICLE AND HIT ONTO MY VEHICLE RH SIDE PORTION. ATTACHMENT(S) Are accident photos available for attachment? Yes Was there any video captured by Car Camera? Yes Was there any audio recorded? No	Was anyhody injured in the Accident	2
Was the accident reported to the police? ON 16.11.2021 AT ABOUT 0930 HOURS, I WAS TRAVELLING STRAIGHT ALONG 24 PENJURU ROAD OPEN SPACE CAR PARK WITH ONE FEMALE PASSENGER ONBOARD. VEHICLE B (GBJ3275C) WHICH WAS TRAVELLING IN FRONT OF ME MADE A RIGHT TURN TO PARK HIS VEHICLE AT ONE OF THE EMPTY PARKING LOT WITHOUT CHECKING FOR ONCOMING VEHICLE AND HIT ONTO MY VEHICLE RH SIDE PORTION. ATTACHMENT(S) Are accident photos available for attachment? Are accident photos available for attachment? Was there any video captured by Car Camera? Yes Was there any video captured by Car Camera? Yes Was there any video captured by Car Camera? Yes Was there any video captured by Car Camera? Yes Was there any video captured by Car Camera? Yes Was there any video captured by Car Camera? Yes Was there any video captured by Car Camera? Yes Was there any video captured by Car Camera? Yes Was there any video captured by Car Camera? Yes Was there any video captured by Car Camera? Yes Was there any video captured by Car Camera? Yes Was there any video captured by Car Camera? Yes	Was any injured on yeard to begin to be a but to be a	No
Hutinber of Passengers (Including Driver) Has the driver been approached by unknown person(s) soliciting/offering accident claims assistance? No PASSENGER 1 Name Gender DETAILS OF POLICE ACTION Was the accident reported to the police? Was notice of intended Prosecution given? If yes, against whom? CIRCUMSTANCES OF ACCIDENT ON 16.11.2021 AT ABOUT 0930 HOURS, I WAS TRAVELLING STRAIGHT ALONG 24 PENJURU ROAD OPEN SPACE CAR PARK WITH ONE FEMALE PASSENGER ONBOARD. VEHICLE B (GBJ3275C) WHICH WAS TRAVELLING IN FRONT OF ME MADE A RIGHT TURN TO PARK HIS VEHICLE AT ONE OF THE EMPTY PARKING LOT WITHOUT TURNING THE SIGNAL LIGHT ON. THUS, I PROCEED TO DRIVE OFF MY VEHICLE WITHIN MY OWN LANE. SUDDENLY, VEHICLE B MOVE FORWARD HIS VEHICLE FROM THE CAR PARK LOT WITHOUT CHECKING FOR ONCOMING VEHICLE AND HIT ONTO MY VEHICLE RH SIDE PORTION. ATTACHMENT(S) Are accident photos available for attachment? Was there any video captured by Car Camera? Yes Was there any video captured by Car Camera? Yes Was there any video captured by Car Camera? Yes Was there any video captured by Car Camera? Yes	Was any other vehicle or property demograd?	•
rias the driver been approached by unknown person(s) soliciting/fering accident claims assistance? PASSENGER 1 Name Gender DETAILS OF POLICE ACTION Was the accident reported to the police? Was notice of intended Prosecution given? No If yes, against whom? CIRCUMSTANCES OF ACCIDENT ON 16.11.2021 AT ABOUT 0930 HOURS, I WAS TRAVELLING STRAIGHT ALONG 24 PENJURU ROAD OPEN SPACE CAR PARK WITH ONE FEMALE PASSENGER ONBOARD. VEHICLE B (GBJ3275C) WHICH WAS TRAVELLING IN FRONT OF ME MADE A RIGHT TURN TO PARK HIS VEHICLE AT ONE OF THE EMPTY PARKING LOT WITHOUT TURNING THE SIGNAL LIGHT ON. THUS, I PROCEED TO DRIVE OFF MY VEHICLE WITHIN MY OWN LANE. SUDDENLY, VEHICLE B MOVE FORWARD HIS VEHICLE FROM THE CAR PARK LOT WITHOUT CHECKING FOR ONCOMING VEHICLE AND HIT ONTO MY VEHICLE RH SIDE PORTION. ATTACHMENT(S) Are accident photos available for attachment? Yes Was there any video captured by Car Camera? Yes Was there any video captured by Car Camera? Yes Was there any video captured by Car Camera? Yes	Number of Passengers (Including Driver)	· -
PASSENGER 1 Name UNKNOWN Gender Female DETAILS OF POLICE ACTION Was the accident reported to the police? No No No If yes, against whom? No If yes, against whom? - CIRCUMSTANCES OF ACCIDENT ON 16.11.2021 AT ABOUT 0930 HOURS, I WAS TRAVELLING STRAIGHT ALONG 24 PENJURU ROAD OPEN SPACE CAR PARK WITH ONE FEMALE PASSENGER ONBOARD. VEHICLE B (GBJ3275C) WHICH WAS TRAVELLING IN FRONT OF ME MADE A RIGHT TURN TO PARK HIS VEHICLE AT ONE OF THE EMPTY PARKING LOT WITHOUT TURNING THE SIGNAL LIGHT ON. THUS, I PROCEED TO DRIVE OFF MY VEHICLE WITHIN MY OWN LANE. SUDDENLY, VEHICLE B MOVE FORWARD HIS VEHICLE FROM THE CAR PARK LOT WITHOUT CHECKING FOR ONCOMING VEHICLE AND HIT ONTO MY VEHICLE RH SIDE PORTION. ATTACHMENT(S) Are accident photos available for attachment? Yes Was there any video captured by Car Camera? Yes Was there any audio recorded? No	Has the driver heen approached by unknown page (2)	2
PASSENGER 1 Name UNKNOWN Gender Female DETAILS OF POLICE ACTION Was the accident reported to the police? No Was notice of intended Prosecution given? No If yes, against whom? - CIRCUMSTANCES OF ACCIDENT ON 16.11.2021 AT ABOUT 0930 HOURS, I WAS TRAVELLING STRAIGHT ALONG 24 PENJURU ROAD OPEN SPACE CAR PARK WITH ONE FEMALE PASSENGER ONBOARD, VEHICLE B (GBJ3275C) WHICH WAS TRAVELLING IN FRONT OF ME MADE A RIGHT TURN TO PARK HIS VEHICLE AT ONE OF THE EMPTY PARKING LOT WITHOUT TURNING THE SIGNAL LIGHT ON.THUS, I PROCEED TO DRIVE OFF MY VEHICLE WITHIN MY OWN LANE. SUDDENLY, VEHICLE B MOVE FORWARD HIS VEHICLE FROM THE CAR PARK LOT WITHOUT CHECKING FOR ONCOMING VEHICLE AND HIT ONTO MY VEHICLE RH SIDE PORTION. ATTACHMENT(S) Are accident photos available for attachment? Yes Was there any video captured by Car Camera? Yes Was there any audio recorded? No	soliciting/offering accident claims assistance?	NI.
Name Gender Gender DETAILS OF POLICE ACTION Was the accident reported to the police? Was notice of intended Prosecution given? No If yes, against whom? CIRCUMSTANCES OF ACCIDENT ON 16.11.2021 AT ABOUT 0930 HOURS, I WAS TRAVELLING STRAIGHT ALONG 24 PENJURU ROAD OPEN SPACE CAR PARK WITH ONE FEMALE PASSENGER ONBOARD. VEHICLE B (GBJ3275C) WHICH WAS TRAVELLING IN FRONT OF ME MADE A RIGHT TURN TO PARK HIS VEHICLE AT ONE OF THE EMPTY PARKING LOT WITHOUT TURNING THE SIGNAL LIGHT ON.THUS, I PROCEED TO DRIVE OFF MY VEHICLE WITHIN MY OWN LANE. SUDDENLY, VEHICLE B MOVE FORWARD HIS VEHICLE FROM THE CAR PARK LOT WITHOUT CHECKING FOR ONCOMING VEHICLE AND HIT ONTO MY VEHICLE RH SIDE PORTION. ATTACHMENT(S) Are accident photos available for attachment? Yes Was there any video captured by Car Camera? Yes Was there any audio recorded? No		No .
Gender Female DETAILS OF POLICE ACTION Was the accident reported to the police? No Was notice of intended Prosecution given? No If yes, against whom? No CIRCUMSTANCES OF ACCIDENT ON 16.11.2021 AT ABOUT 0930 HOURS, I WAS TRAVELLING STRAIGHT ALONG 24 PENJURU ROAD OPEN SPACE CAR PARK WITH ONE FEMALE PASSENGER ONBOARD. VEHICLE B (GBJ3275C) WHICH WAS TRAVELLING IN FRONT OF ME MADE A RIGHT TURN TO PARK HIS VEHICLE AT ONE OF THE EMPTY PARKING LOT WITHOUT TURNING THE SIGNAL LIGHT ON.THUS, I PROCEED TO DRIVE OFF MY VEHICLE WITHIN MY OWN LANE. SUDDENLY, VEHICLE B MOVE FORWARD HIS VEHICLE FROM THE CAR PARK LOT WITHOUT CHECKING FOR ONCOMING VEHICLE AND HIT ONTO MY VEHICLE RH SIDE ATTACHMENT(S) Are accident photos available for attachment? Yes Was there any video captured by Car Camera? Yes Was there any audio recorded? No	PASSENGER 1	
Gender Female DETAILS OF POLICE ACTION Was the accident reported to the police? No Was notice of intended Prosecution given? No If yes, against whom? No CIRCUMSTANCES OF ACCIDENT ON 16.11.2021 AT ABOUT 0930 HOURS, I WAS TRAVELLING STRAIGHT ALONG 24 PENJURU ROAD OPEN SPACE CAR PARK WITH ONE FEMALE PASSENGER ONBOARD. VEHICLE B (GBJ3275C) WHICH WAS TRAVELLING IN FRONT OF ME MADE A RIGHT TURN TO PARK HIS VEHICLE AT ONE OF THE EMPTY PARKING LOT WITHOUT TURNING THE SIGNAL LIGHT ON.THUS, I PROCEED TO DRIVE OFF MY VEHICLE WITHIN MY OWN LANE. SUDDENLY, VEHICLE B MOVE FORWARD HIS VEHICLE FROM THE CAR PARK LOT WITHOUT CHECKING FOR ONCOMING VEHICLE AND HIT ONTO MY VEHICLE RH SIDE ATTACHMENT(S) Are accident photos available for attachment? Yes Was there any video captured by Car Camera? Yes Was there any audio recorded? No	Name	LINIZALOVAL
Was the accident reported to the police? Was notice of intended Prosecution given? No If yes, against whom? CIRCUMSTANCES OF ACCIDENT ON 16.11.2021 AT ABOUT 0930 HOURS, I WAS TRAVELLING STRAIGHT ALONG 24 PENJURU ROAD OPEN SPACE CAR PARK WITH ONE FEMALE PASSENGER ONBOARD. VEHICLE B (GBJ3275C) WHICH WAS TRAVELLING IN FRONT OF ME MADE A ON.THUS, I PROCEED TO DRIVE OFF MY VEHICLE WITHIN MY OWN LANE. SUDDENLY, VEHICLE B MOVE FORWARD HIS VEHICLE FROM THE CAR PARK LOT WITHOUT CHECKING FOR ONCOMING VEHICLE AND HIT ONTO MY VEHICLE RH SIDE PORTION. ATTACHMENT(S) Are accident photos available for attachment? Yes Was there any video captured by Car Camera? Yes Was there any audio recorded? No	Gender	
Was the accident reported to the police? Was notice of intended Prosecution given? No If yes, against whom? CIRCUMSTANCES OF ACCIDENT ON 16.11.2021 AT ABOUT 0930 HOURS, I WAS TRAVELLING STRAIGHT ALONG 24 PENJURU ROAD OPEN SPACE CAR PARK WITH ONE FEMALE PASSENGER ONBOARD. VEHICLE B (GBJ3275C) WHICH WAS TRAVELLING IN FRONT OF ME MADE A RIGHT TURN TO PARK HIS VEHICLE AT ONE OF THE EMPTY PARKING LOT WITHOUT TURNING THE SIGNAL LIGHT ON. THUS, I PROCEED TO DRIVE OFF MY VEHICLE WITHIN MY OWN LANE. SUDDENLY, VEHICLE B MOVE FORWARD HIS VEHICLE FROM THE CAR PARK LOT WITHOUT CHECKING FOR ONCOMING VEHICLE AND HIT ONTO MY VEHICLE RH SIDE PORTION. ATTACHMENT(S) Are accident photos available for attachment? Yes Was there any video captured by Car Camera? Yes Was there any audio recorded? No		remale
Was notice of intended Prosecution given? If yes, against whom? CIRCUMSTANCES OF ACCIDENT ON 16.11.2021 AT ABOUT 0930 HOURS, I WAS TRAVELLING STRAIGHT ALONG 24 PENJURU ROAD OPEN SPACE CAR PARK WITH ONE FEMALE PASSENGER ONBOARD. VEHICLE B (GBJ3275C) WHICH WAS TRAVELLING IN FRONT OF ME MADE A RIGHT TURN TO PARK HIS VEHICLE AT ONE OF THE EMPTY PARKING LOT WITHOUT TURNING THE SIGNAL LIGHT ON.THUS, I PROCEED TO DRIVE OFF MY VEHICLE WITHIN MY OWN LANE. SUDDENLY, VEHICLE B MOVE FORWARD HIS VEHICLE FROM THE CAR PARK LOT WITHOUT CHECKING FOR ONCOMING VEHICLE AND HIT ONTO MY VEHICLE RH SIDE PORTION. ATTACHMENT(S) Are accident photos available for attachment? Yes Was there any video captured by Car Camera? Yes Was there any audio recorded? No		
Was notice of intended Prosecution given? If yes, against whom? CIRCUMSTANCES OF ACCIDENT ON 16.11.2021 AT ABOUT 0930 HOURS, I WAS TRAVELLING STRAIGHT ALONG 24 PENJURU ROAD OPEN SPACE CAR PARK WITH ONE FEMALE PASSENGER ONBOARD. VEHICLE B (GBJ3275C) WHICH WAS TRAVELLING IN FRONT OF ME MADE A RIGHT TURN TO PARK HIS VEHICLE AT ONE OF THE EMPTY PARKING LOT WITHOUT TURNING THE SIGNAL LIGHT ON.THUS, I PROCEED TO DRIVE OFF MY VEHICLE WITHIN MY OWN LANE. SUDDENLY, VEHICLE B MOVE FORWARD HIS VEHICLE FROM THE CAR PARK LOT WITHOUT CHECKING FOR ONCOMING VEHICLE AND HIT ONTO MY VEHICLE RH SIDE PORTION. ATTACHMENT(S) Are accident photos available for attachment? Yes Was there any video captured by Car Camera? Yes Was there any audio recorded? No	Was the accident reported to the police?	No
CIRCUMSTANCES OF ACCIDENT ON 16.11.2021 AT ABOUT 0930 HOURS, I WAS TRAVELLING STRAIGHT ALONG 24 PENJURU ROAD OPEN SPACE CAR PARK WITH ONE FEMALE PASSENGER ONBOARD. VEHICLE B (GBJ3275C) WHICH WAS TRAVELLING IN FRONT OF ME MADE A RIGHT TURN TO PARK HIS VEHICLE AT ONE OF THE EMPTY PARKING LOT WITHOUT TURNING THE SIGNAL LIGHT ON.THUS, I PROCEED TO DRIVE OFF MY VEHICLE WITHIN MY OWN LANE. SUDDENLY, VEHICLE B MOVE FORWARD HIS VEHICLE FROM THE CAR PARK LOT WITHOUT CHECKING FOR ONCOMING VEHICLE AND HIT ONTO MY VEHICLE RH SIDE ATTACHMENT(S) Are accident photos available for attachment? Yes Was there any video captured by Car Camera? Yes Was there any audio recorded? No	Was notice of intended Prosecution given?	
ON 16.11.2021 AT ABOUT 0930 HOURS, I WAS TRAVELLING STRAIGHT ALONG 24 PENJURU ROAD OPEN SPACE CAR PARK WITH ONE FEMALE PASSENGER ONBOARD. VEHICLE B (GBJ3275C) WHICH WAS TRAVELLING IN FRONT OF ME MADE A RIGHT TURN TO PARK HIS VEHICLE AT ONE OF THE EMPTY PARKING LOT WITHOUT TURNING THE SIGNAL LIGHT ON.THUS, I PROCEED TO DRIVE OFF MY VEHICLE WITHIN MY OWN LANE. SUDDENLY, VEHICLE B MOVE FORWARD HIS VEHICLE FROM THE CAR PARK LOT WITHOUT CHECKING FOR ONCOMING VEHICLE AND HIT ONTO MY VEHICLE RH SIDE PORTION. ATTACHMENT(S) Are accident photos available for attachment? Yes Was there any video captured by Car Camera? Yes Was there any audio recorded? No	If yes, against whom?	7
ON 16.11.2021 AT ABOUT 0930 HOURS, I WAS TRAVELLING STRAIGHT ALONG 24 PENJURU ROAD OPEN SPACE CAR PARK WITH ONE FEMALE PASSENGER ONBOARD. VEHICLE B (GBJ3275C) WHICH WAS TRAVELLING IN FRONT OF ME MADE A RIGHT TURN TO PARK HIS VEHICLE AT ONE OF THE EMPTY PARKING LOT WITHOUT TURNING THE SIGNAL LIGHT ON.THUS, I PROCEED TO DRIVE OFF MY VEHICLE WITHIN MY OWN LANE. SUDDENLY, VEHICLE B MOVE FORWARD HIS VEHICLE FROM THE CAR PARK LOT WITHOUT CHECKING FOR ONCOMING VEHICLE AND HIT ONTO MY VEHICLE RH SIDE PORTION. ATTACHMENT(S) Are accident photos available for attachment? Yes Was there any video captured by Car Camera? Yes Was there any audio recorded? No	diagram was a segretaria	
RIGHT TURN TO PARK HIS VEHICLE AT ONE OF THE EMPTY PARKING LOT WITHOUT TURNING THE SIGNAL LIGHT ON.THUS, I PROCEED TO DRIVE OFF MY VEHICLE WITHIN MY OWN LANE. SUDDENLY, VEHICLE B MOVE FORWARD HIS VEHICLE FROM THE CAR PARK LOT WITHOUT CHECKING FOR ONCOMING VEHICLE AND HIT ONTO MY VEHICLE RH SIDE ATTACHMENT(S) Are accident photos available for attachment? Yes Was there any video captured by Car Camera? Yes Was there any audio recorded? No	CIRCUMSTANCES OF ACCIDENT	
Are accident photos available for attachment? Was there any video captured by Car Camera? Was there any audio recorded? Yes Yes No	RIGHT TURN TO PARK HIS VEHICLE AT ONE OF THE EMPTY FOR ON. THUS, I PROCEED TO DRIVE OFF MY VEHICLE WITHIN AN	PARKING LOT WITHOUT TURNING THE SIGNAL LIGHT
Was there any video captured by Car Camera? Yes Was there any audio recorded? No		
Was there any video captured by Car Camera? Yes Was there any audio recorded? No	Are accident photos available for attachment?	Yes
Was there any audio recorded? No	Was there any video captured by Car Camera?	
	Was there any audio recorded?	
DETAILS OF OTHER VEHICLE PROPERTY 1		
	DETAILS OF OTHER A	/FHICLE PRODUCTY 1

GBJ3275C

Vehicle Manufacturer	Tourst
Vehicle Model	Toyota
Vehicle Variant	Hiace
Vehicle Colour	-
	-
Name of Driver	Commercial vehicle
Contact Number	-
Address	-
Address complement	-
Postcode	-
Insurance Company Namo	-
Insurance Company Name Nature Of Damage	India International Insurance Pte Ltd
Datails of property demand in a state	-
Details of property damaged in accident	-
No. Of Passenger (Including Driver)	2

SKETCH PLAN

IMPORTANT NOTICE

- 1. Please report correctly the details of the accident to speed up the claims process.
- 2. This Form must be completed by the Policyholder and/or the Authorised Driver.
- 3. Information provided must be as <u>truthful and accurate as possible</u>. Any wilful misrepresentation or withholding of material facts may allow insurance companies to <u>repudiate policy liability</u>.
- 4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
- 5. Any false reporting may be referred to the Police for investigation.
- The report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
- By the lodgment of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.
- 8. Consent under the Personal Data Protection Act (PDPA)

l understand, acknowledge, agree and consent that:

- (a) My insurer, my workshop and the General Insurance Association of Singapore ("GIA") may/are permitted to collect, use, disclose and/or process my personal data/personal information set out in this [form] and any other personal information provided by me or possessed by my insurer (collectively the "Personal Information") and disclose and transfer such Personal Information to all insurer(s) who have insured vehicle(s) involved in this accident (all insurer(s) who have insured vehicle(s) involved in this accident shall be collectively referred to as the "Insurers"), the Insurers' lawyers/law firms, the Monetary Authority of Singapore and any relevant government agency/authority (such as the police), for the purpose(s) of :
 - processing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigations relating to the claims;
 - (ii) investigating the accident and/or my claims;
 - (lii) carrying out and/or dealing with my instructions or responding to any enquiries by me;
 - (iv) administering my claims (including the malling of correspondence, statements, invoices, reports or notices to me, which could involve disclosure of certain personal data about me to bring about delivery of the same as well as on the external cover of envelopes/mail packages); and/or
 - (v) complying with applicable law in administering, processing, handling and/or dealing with my claims.(collectively the "Purposes")
- (b) all insurer(s) who have insured vehicle(s) involved in this accident and the insurers' lawyers/law firms, may/are permitted to collect, use, disclose and/or process my Personal Information for one or more of the above Purposes; and
- (c) my Personal Information may/can be disclosed by any of the Insurers and/or GIA to their third party service providers or agents(including their lawyers/law firms), which may be sited outside of Singapore, for one or more of the above Purposes.
- (d) my Personal Information will also be collected and used to compile claims history for the purpose of fraud detection, investigation and management in present and all future claims.
- (e) the information so collected under (d) above may be shared / disclosed:
 - to all insurers and/or any other third parties that assist in evaluating, investigating, controlling or managing froud, regulators, law enforcement and government agencies as reasonably required for the purposes stated, or
 - (ii) for complying with requirements under any regulations, laws or court orders.

Policyholder's Signature Date & Time:

Driver's Signature (If driver is not the policyholder)
Date & Time:

Reporting Centre Personnel's Signature Name:

NRIC/FIN No.:

Distlate, Set difficult out, Mi

SKETCH PLAN			
SKE CH PIAN			iono 24 Perjum Road open space cor pork pelicle A: SLV17911K zhiole B: G873:75c
DESCRIBE CIRCUMSTANCES OF	THE ACCIDENT	ministrisem i a ಪಟ್ಟರ್ ಗೀವರ್ ಅಪಾರೀ ಪ್ರಜೆಯ ಪ್ರಜೆಯ ಪ್ರಚೇಜ ಕ್ರಾಕ್ತಾ	ra Procedenta de la Standa de Ballondon de La Agustina (1).
on th	Infrom at about	o'Be has, I w	4. T. A. A. A. A.
	The work		ous topvelling stought
along 24 Person	Road open space	car fork with	n one dample passage
	At turn to pork turning the signal	his yelide of a	elling in food of one of the empty
drive off my relicle	within my own lune.	Suddenly, weh	icle B moved
formed his vehicle	from the cor	pork let withe	t checking for
encoming wehicle	and hit ento	my vehicle	f.H side portion
DECLARATION I/We declare the foregoing particula Policyholder's Signature	rs are true in every respect. \(\sumset \tau \cdot \t		
Date & Time:	(If driver is not the policyholde Date & Time:	Reporting C r) Name: NRIC/FIN N	Centre Personnel's Signature

Gallaic Stairbhankann As

SKETCH PLAN

IMPORTANT NOTICE

- 1. Please report correctly the details of the accident to speed up the claims process.
- 2. This Form must be completed by the Policyholder and/or the Authorised Driver.
- 3. Information provided must be as <u>truthful and accurate as possible</u>. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
- 4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
- 5. Any false reporting may be referred to the Police for investigation.
- 6. The report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
- 7. By the lodgment of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.
- 8. Consent under the Personal Data Protection Act (PDPA)

I understand, acknowledge, agree and consent that:

- My insurer, my workshop and the General Insurance Association of Singapore ("GIA") may/are permitted to collect, use, disclose and/or process my personal data/personal information set out in this [form] and any other personal information provided by me or possessed by my insurer (collectively the "Personal Information") and disclose and transfer such Personal Information to all insurer(s) who have insured vehicle(s) involved in this accident (all insurer(s) who have insured vehicle(s) involved in this accident shall be collectively referred to as the "Insurers"), the Insurers' lawyers/law firms, the Monetary Authority of Singapore and any relevant government agency/authority (such as the police), for the purpose(s) of:
 - (i) processing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigations relating to the claims;
 - (ii) investigating the accident and/or my claims;
 - (iii) carrying out and/or dealing with my instructions or responding to any enquiries by me;
 - (iv) administering my claims (including the mailing of correspondence, statements, invoices, reports or notices to me, which could involve disclosure of certain personal data about me to bring about delivery of the same as well as on the external cover of envelopes/mail packages); and/or
 - (v) complying with applicable law in administering, processing, handling and/or dealing with my claims.(collectively the "Purposes")
- all insurer(s) who have insured vehicle(s) involved in this accident and the Insurers' lawyers/law firms, may/are permitted to collect, use, disclose and/or process my Personal Information for one or more of the above Purposes; and
- my Personal Information may/can be disclosed by any of the Insurers and/or GIA to their third party service providers or agents(including their lawyers/law firms), which may be sited outside of Singapore, for one or more of the above Purposes.
- my Personal Information will also be collected and used to compile claims history for the purpose of fraud detection, investigation and management in present and all future claims.
- the information so collected under (d) above may be shared / disclosed: (e)
 - (i) to all insurers and/or any other third parties that assist in evaluating, investigating, controlling or managing fraud, regulators, law enforcement and government agencies as reasonably required for the purposes stated, or
 - (ii) for complying with requirements under any regulations, laws or court orders.

Policyholder's Signature Date & Time:


Driver's Signature (If driver is not the policyholder)

Date & Time:

Reporting Centre Personnel's Signature Name:

NRIC/FIN No .:

SKETCH PLAN



DESCRIBE CIRCUMSTANCES OF THE ACCIDENT

The Accident	*
on 16/11/2021 at about 0930 hrs, I was travelling	straight
along 24 Persum Road open space car park with one female	passage
onboard. Vehicle B (GBJ 3275C) which was travelling in from	, ,
me made a right turn to park his vehicle at one of the	empty
parking lot nithant turning the signal lights on. Thus, I price	d to
drive off my rehicle within my own lane. Suddenly, yehicle B more	red
forward his vehicle from the cor park lot without checking	for
oncoming vehicle and hit onto my vehicle RH side p	portion.
	:

DECLARATION

I/We declare the foregoing particulars are true in every respect.

Policyholder's Signature Date & Time:

Driver's Signature (If driver is not the policyholder) Date & Time: Reporting Centre Personnel's Signature Name:

NRIC/FIN No.:

> Back to OneMotoring

Land Transport Authority

Land Transport Authority 10 Sin Ming Drive Singapore 575701

GST Registration No.: M4-0006529-2

Print Date/Time:

16 Nov 2021 / 13:42:48

Receipt Date/Time: 16 Nov 2021 / 13:42:48

Tax Invoice/Receipt

Receipt No.: ITNET-00000-211116-002053

Previous Receipt No.:

S/N Item Description/ Business Transaction Reference No. Result of Insurance Enquiry - GBJ3275C As at 16 Nov 2021/09:30:00 Insurance Co: INDIA INT'L INS PTE LTD Insurance Enquiry - GBJ3275C		Amount Before GST (S\$)	GST Amount (S\$)	Amount After GST (S\$)
Enquiry Fee 20211116134136530003		7.00	0.49	7.49
	Sub-Total	7.00	0.49	7.49
	Total Before Rounding	7.00	0.49	7.49
	Rounding Difference			0.04
	Total Amount Payable			7.45
•	Paid By			
	462845XXXXXX4726	eNETS (Credit Card	7.45
	Total			7.45
	Cash Change			0.00
	Tendered Amount			7.45
	Excess Refundable Amount			0.00

THANK YOU AND HAVE A NICE DAY!

Please ensure that all payments to the Authority are good and promptly settled by the payment service provider / financial institution. Otherwise, the transaction and receipt is considered void and late fee may apply.

DATE	DESCRIPTION	MILLEAGE ODOMETER READING	MILLEAGE TRAVELLED	HOURS OPERATED (TIME)	ATED (TIME)
16/11/21	VEHICLE ACCIDENT (IN)	206169	,	[[30h/s	
26/11/21	(OUT)	206170			1300hs
VEHICLE NUMBER:	BER: SU 179/K	HIRER/DRIVER	SIGN:	X tox	
REMARKS:					
1)					
2)					
3)					
4)					
5)					

DIGILIFE TECHNOLOGIES LIMITED

Singapore

Co. UEN: 199304568R

Date: 5 December 2021

TO WHOM IT MAY CONCERN

Dear Sir/Madam

ACCIDENT ON	16/11/2021 09:30 (SGT)
ALONG INVOLVING	ALONG 24 PENJURU ROAD OPEN SPACE CAR PARK GBJ 3275C

We refer to the above-mentioned accident and wish to inform that **Digilife Technologies Limited** is the registered owner of the BYD bearing vehicle registration number <u>SLV 1791K</u> (the "BYD"). The BYD was hired to <u>Mr Yeoh Su Ang</u> NRIC <u>SXXXX340D</u> a registered hirer-operator of **Singapore Electric Vehicles Pte Ltd** at the time of occurrence of the aforementioned accident at a rental <u>\$ 90.95</u> per day.

Please be advised that the BYD was insured with **Allianz Insurance Singapore Pte Ltd** on a third party basis at the material time of the accident.

We wish to confirm that the aforesaid hirer-operator had obtained our permission to undertake repairs for damage on the BYD arising from the said accident with **Ding Auto Pte Ltd**.

Please liase with **Ding Auto Pte Ltd** directly for settlement of claims with third party's insurance company in respect of the said accident.

Yours faithfully

Eric Tay

Fleet Supervisor

Digilife Technologies Limited

LETTER OF AUTHORITY

Accident involving SLY 1791K along 24 Penjum Road open	&GB	3275	ሪ m	16/11/21
along 24 Penjum Road open	space	cor por	<u> </u>	
I/We, <u>Digilife</u> Technologies Limiter registered owner of vehicle No Hire / Driver, Mr/Msyeoh hereby authorize Ding Auto Pte Li	ed _NRIC/Co.I _SLV1791k suAng	Reg Num	ber ch wa	
hereby authorize Ding Auto Pte Lt correspond, negotiate and settle m losses arising from the above accid claim.	my/our claim	- C		to submit,
I/We further authorize that agreed Auto Pte Ltd should be made in fav payment be forwarded to them as f	/OUT OT DIING	r Amto D	ta I ad	. 1.1
Owner Signature/Co.Chop		Auth	orize	d Workshop
Hirer/Driver Signature		·		THIS ALL OF THE PARTY OF THE PA
NEOX				

Satisfaction Voucher

Date: 30/11/2021	
ALLIANZ GLOBAL CORPORATE & SPECIALTY AG	30 NOV'21 3 9:25
All and the second seco	
Attention: MOTOR CLAIMS DEPT	26 NOU'21 13 00
Dear Sir/Madam Yech su Ang	4
	Actual collectory date actions
I/We hereby acknowledge having received from Singapore Technologies Kinetics	date Stine
Ltd.,249 Jalan Boon Lay,Singapore 619523, my/our vehicle number SLV1791K	
which has been repaired to my/our satisfaction and acceptance. I/We admit that	-
the payment of SGD account for such repairs is in full discharge	
of my/our claim upon the corporation under the policy number SPMF1000000478	
reference claim number 85008888 in respect of the damage caused to the	
said vehicle in an accident that occurred thereto or about the 16/11/2021	
at ALONG 24 PENJURU RD OPEN SPAC	·
2-11121	
Dated this day of 30 11 21 ,201 . Company Stamp if applicable	
Signature:	
NRIC No: SXXXX 340 D	
Name: DIGILIFE TECHNOLOGIES	
LIMITED (Fleet) Address: 152 UBI AVENUE 4	
SINGAPORE (408826)	3

Form G-STAR-WI-FC-005-01- Rev00



Allianz Insurance Singapore Pte. Ltd.

CERTIFICATE OF INSURANCE

ROAD TRANSPORT ACT 1987 (MALAYSIA) MOTOR VEHICLES (THIRD-PARTY RISKS) RULES 1959 (FEDERATION OF MALAYSIA) MOTOR VEHICLES (THIRD-PARTY RISKS AND COMPENSATION) ACT (CAP.189 OF THE REVISED EDITION) (REPUBLIC OF SINGAPORE) MOTOR VEHICLES (THIRD-PARTY RISKS AND COMPENSATION) RULES 1996 (REPUBLIC OF SINGAPORE) MOTOR VEHICLES (THIRD-PARTY RISKS AND COMPENSATION) RULES, 1960 OR ANY AMENDMENT, ACT OR ACTS PASSED IN SUBSTITUTION THEREOF

Certificate Number

SPMF1000000478

Date of Issue

09 September 2021

Coverage

COMPREHENSIVE

Policyholder

DIGILIFE TECHNOLOGIES LIMITED

Finance Company

Period of Insurance

14 September 2021 To 13 September 2022 (both dates inclusive)

Registration Number

SLV1791K

Chassis Number of Vehicle

LC0CE4DB3H1026329

Persons or Classes of Persons Entitled to Drive*:

(a) The Policyholder.

- (b) Any other person who is driving on the Policyholder's order or with the his/her permission or to whom the vehicle is hired.
- Provided that the person driving is permitted in accordance with the licensing or other laws or regulation to drive the Motor Vehicle or has been permitted and is not disqualified by order of Court of Law or by reason of any enactment or regulations in that behalf from driving the Motor Vehicle. And provided further that the Motor Vehicle is registered under the Road Traffic Act (Cap 276) (Republic of Singapore) and such registration has not been cancelled at the time of accident loss or damage.

Limitation as to Use^:

- (a) Use for carriage of passengers or goods in connection with the Policyholder's business.
- (b) Use for social, domestic and pleasure purposes and business purposes of any person to whom the vehicle is hired.
- (c) Use for the carriage of passengers for hire or reward under Private Hire Vehicle (PHV) by any person to whom the vehicle is hired and for use within Singapore only.
- ^ Limitation rendered inoperative by Section 8 of Motor Vehicles (Third-Party Risks and Compensation) Act (Chapter 189) and Section 95 of the Road Transport Act, 1987 (Malaysia), are not to be included under these headings.

Policy does not cover:

- (a) Use for racing, pace-making, reliability trials or speed-testing.
- (b) Use whilst drawing a trailer except the towing (other than for reward) of any one disabled mechanically propelled vehicle.

I/We hereby certify that the Policy to which this Certificate relates is issued in accordance with the provisions of the Motor Vehicles (Third Party Risks and Compensation) Act (Chapter 189) and Part IV of the Road Transport Act, 1987 (Malaysia).

09 September 2021

Issue Date

Hicham Raissi Chief Executive Officer Allianz Insurance Singapore Pte. Ltd.

Intermediary Code

: 0000180 ALL INS MARKETING PTE LTD

Excess

Section 1: Own Damage Section 1: Windscreen

Section 2: Liabilities to Third Parties

SGD SGD 2,000.00 100.00

SGD

1,500.00