

INSPECTION CHECKLIST

Reference no: CS5/TP21011709/Cq

Section A: Vehicle Check

Applicant	VENTURE CARS PTE LTD
Date of Inspection	17/11/2021
Time of Inspection	13:30 HRS
Vehicle Make	TOYOTA
Vehicle Model	SIENTA 1.5X
Vehicle Model Code	5BA-NSP170G-MWXNB
Engine Number	2NR1206817
Chassis Number	NSP1707259506
Motor Number (if any)	-
Odometer Reading	129 KM

Wheels	
Front Tyre Size	185/60R15
Rear Tyre Size	185/60R15


Lighting	Yes	No	Remarks
Auto Levelling System		X	
Front Fog Lamp		X	
Rear Fog Lamp		X	
Type of Low Beam	☒	Halogen ☐ LED ☐ HID	
Type of High Beam	☒	Halogen ☐ LED ☐ HID	

Others	Yes	No	Remarks
Sunroof / Moonroof (if any)		X	
Transmission Type	☐ Manual	☒ Automatic	


Vehicle Identification (VIN) Chassis Plate




Chassis Number Stamping



Engine Number Stamping



Front View



Rear View



Right View



Left View



Engine Compartment



Front Tyre Size




Rear Tyre Size




Instrument Panel



Exhaust System




Exhaust System




Exhaust System



Speedometer



Odometer



Vehicle Light Transmittance (VLT)

Windscreen VLT Reading: 83% (front)



Windscreen VLT Reading: 25% (rear)



Front Windows VLT Reading: 79% (left)



Front Windows VLT Reading: 78% (right)



Rear Windows VLT Reading: 32% (left)



Rear Windows VLT Reading: 31% (right)



Front Quarter Glass VLT Reading: 79 % (Left)



Front Quarter Glass VLT Reading: 79% (Right)



Rear Quarter Glass VLT Reading: 31% (Left)



Rear Quarter Glass VLT Reading: 33% (Right)



Section B: Observation

--

Section C: Undertaking by Authorised Inspectors

We, hereby, verify that we have checked the above-mentioned vehicle on 17/11/21 (date)
and correctly recorded the technical information on this form.

1) Inspector's Name & Signature: Ho Leong Chuan

(with company endorsement)




2) Inspector's Name & Signature: K.K.Lau

MSc,B.ENG(HONS),PE(USA)

(with company endorsement)