

INSPECTION CHECKLIST

Reference no: CS5/TP21011712/Cq

Section A: Vehicle Check


Applicant	VENTURE CARS PTE LTD
Date of Inspection	17/11/2021
Time of Inspection	10:30 HRS
Vehicle Make	TOYOTA
Vehicle Model	SIENTA 1.5X
Vehicle Model Code	5BA-NSP170G-MWXNB
Engine Number	2NR1200694
Chassis Number	NSP1707259106
Motor Number (if any)	-
Odometer Reading	80 KM

Wheels	
Front Tyre Size	185/60R15
Rear Tyre Size	185/60R15

Lighting	Yes	No	Remarks
Auto Levelling System		X	
Front Fog Lamp		X	
Rear Fog Lamp		X	
Type of Low Beam	☒	Halogen ☐ LED ☐ HID	
Type of High Beam	☒	Halogen ☐ LED ☐ HID	

Others	Yes	No	Remarks
Sunroof / Moonroof (if any)		X	
Transmission Type	☐	Manual ☒ Automatic	

Vehicle Identification (VIN) Chassis Plate




Chassis Number Stamping




Engine Number Stamping



Front View



Rear View




Right View




Left View



Engine Compartment



Front Tyre Size



Rear Tyre Size



Instrument Panel



Exhaust System




Exhaust System




Exhaust System



Speedometer



Odometer



Vehicle Light Transmittance (VLT)

Windscreen VLT Reading: 84% (front)



Windscreen VLT Reading: 25% (rear)



Front Windows VLT Reading: 78% (left)



Front Windows VLT Reading: 78% (right)



Rear Windows VLT Reading: 31% (left)



Rear Windows VLT Reading: 31% (right)



Front Quarter Glass VLT Reading: 78 % (Left)



Front Quarter Glass VLT Reading: 79% (Right)



Rear Quarter Glass VLT Reading: 31% (Left)



Rear Quarter Glass VLT Reading: 31% (Right)





Section B: Observation

Section C: Undertaking by Authorised Inspectors

We, hereby, verify that we have checked the above-mentioned vehicle on 17/11/21 (date)
and correctly recorded the technical information on this form.

1) Inspector's Name & Signature: Ho Leong Chuan

(with company endorsement)




2) Inspector's Name & Signature: K.K.Lau
MSc,B.ENG(HONS),PE(USA)

(with company endorsement)