REF:

CC6/A1621011718/Uea3

ASSIGNMENT	
From: Date:	Veh No: 56 x 5927 Yr Regn: 10/8/07
Estimated Cost:	Type: M. Car / M. Cycle / Bus / Van / Lorry / Taxi / Prime Mover /
OD (TP) WS / TP RES / OD RES / EVA / INV / MV	Truck / Trailer or
To Inspect Vehicle No: S6 X S927	Make: VOLVO VSD TS c.c 252/
at Workshop m/s Jen Ands Ipan	Colour 3 MJ A/C: Insured / Std / NI / NA
of	Sp.Reading / £204£ T/Radio: Insured / Std / NI / NA
of Insured: S 4246CD	Eng/No:
Policy No.	CNO: YVIMW675982370389
Claims No.	Gen. Cond: Good Fair / Poor / Burnt
Sum Insured: Excess:	Steering: Ingreder / Jammed / Leaked / Burnt or
(Client's Record)	Brake: Inorder Jammed / Leaked / Burnt or
Make of Veh:	Modi: Nil SIRim / STD A/Rim or
	Tyre Size: F:
(Policy Condition)	R: 225/45-117
Remark: The veh had commenced its N/S O/S	BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /
repair at the time of inspection.	TOYO/YOKO or Continental
Bal. or Market Value:	Front Rear
IDAC Accident Rport: Consistent? : Yes or No	R/Bal. 6 mm R/Bal. 6 mm
GIA / PR Seen: Consistent?: Yes or No	L/Bal. 6 mm L/Bal. 6 mm
Est. Repairs: days Res.: Yes or No	D.O.A. 16/11/2/
Lum Sum: % 3 Val.: Yes or No	Survey held at
CA / REV / REP. / 24 HRS Vehicle: IN / OUT	Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or
Date: Person Contacted:	The U/C / Chassis frame / Body Structure affected due to collision.
Date / Time Action / Instruction COR WAT. (09-08-2022 Bol fmth plus L74 & 3699	
Date/Time, File Pass to? Preli. Report	Down Of Panaire
· - · ·	Days Of Repair:
1) Final Report Date/Time, File Return to?	Resurvey No. of Trip: Survey Fee: Transportation:
Add Fee	
	:Interview (\$) Photos
Report Format :	: Tech. Invs (\$) Others
Lump Sum / I.B.I: (\$	
)	: Weekend (\$

> Back to OneMotoring

Enquire PARF/COE Rebate for Registered Vehicle

BS AIRBAG TURBO
4
2370389
bhp)
& above)

vehicle reaches its statutory lifespan (if applicable), whiches The information contained herein is correct as at 18 Nov 2021