



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile				
INDIA INTERNATIONAL INSURANCE PL 64 CECIL STREET #05-02 IOB BUILDING SINGAPORE 049711			Ref: CS3/GRB21010004/Vuf3e2-1	
			Date: 27/12/2021	
			Code: GRB	
1. Policy Particulars :- THIRD PARTY CLAIM				
Insured Veh.	SMY 4631S	Veh. Inspected	GBG 5331B	
Policy No.	D21MFL0000447	Coverage (\$)	0.00	
Claim No.	MFL2021D0004176	Excess (\$)	0.00	
Assign From	CARINE KEK PHER SER	Assign Date	17/11/2021	
2. Vehicle Particulars & Condition				
Make & Model	NISSAN NV200 1.5MT	c.c	1461	
Engine No.	HIDDEN	Year of Reg.	2017	
Chassis No.	VSKYBAM20Z0145916	Colour	SILVER	
Odometer	168457 KM	Steering	IN ORDER	
Brakes	IN ORDER	Modification	SPORTS RIM	
General	GOOD			
3. Conditions of Tyres				
	Size	Make	Balance	
R/H Front Tyre	165/70 R14	FALKEN	5 mm	
L/H Front Tyre	165/70 R14	FALKEN	5 mm	
R/H Rear Tyre	165/70 R14	FALKEN	5 mm	
L/H Rear Tyre	165/70 R14	FALKEN	5 mm	
4. Description of Damages				
THE VEHICLE SUSTAINED DAMAGES AT THE REAR PORTION. DAMAGES SEE DETAILS.				
5. General Information				
Accident Date	25/09/2021	Inspection Date	27/09/2021	
Survey held at	ALPHA CAR SERVICES PTE LTD BLK C, KAKI BUKIT AVE 6 #01-59 KAKI BUKIT AUTOBAY SINGAPORE 417883			
5a. Remarks				
A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.				
5b. Estimate Days of Repair				
ESTIMATED NORMAL PERIOD FOR REPAIR:			5 Working Days	