

Lump Sum
@ \$ 3150
3 days

ETHOZ

Date : 17/12/2021
To : **CHINA TAIPING INSURANCE (SINGAPORE) PTE. LTD.**
Attn : **Motor Claim Department** FAX :

Owner : KOH CHIN HENG
Insured By : AXA INSURANCE PTE LTD
Certificate No : GA540408/1 Accident Date : 03/11/2021
Vehicle No : SCW-8777-H Make & Model : VOLKSWAGEN SHARAN 2.0 TSI AT 7N14H3

FINAL ESTIMATED REPAIR COST DETAIL Excess : 0.00 Add Excess : 0.00

QTY	DESCRIPTION	REPAIRER AMT (\$)	SURVEYOR AMT (\$)
List Item			
1	FRONT DOOR LH	1890.00	1890.00
1	FRONT DOOR WEATHERSTRIP LH	392.00	392.00
20	FRONT DOOR RIVET PIN	150.00	150.00
1	WING MIRROR ASSY LH	784.00	784.00
1	WING MIRROR COVER LH	144.00	144.00
1	WING MIRROR SIGNAL LENS LH	203.00	203.00
Sub Total		3563.00	3563.00
Discount 10% On Parts		(0.00)	(356.30)
Labour & Misc			
	LABOUR TO FACILITATE REPAIR	600.00	300.00
	TO RESPRAY AFFECTED AREAS	600.00	350.00
	TO REMOVE AND TRANSFER DOOR COMPONENTS	150.00	60.00

PAGE : 1



Date : 17/12/2021
To : CHINA TAIPING INSURANCE (SINGAPORE) PTE. LTD.

Attn : Motor Claim Department FAX :

Owner : KOH CHIN HENG
Insured By : AXA INSURANCE PTE LTD
Certificate No : GA540408/1 Accident Date : 03/11/2021
Vehicle No : SCW-8777-H Make & Model : VOLKSWAGEN SHARAN 2.0 TSI AT 7N14H3

FINAL ESTIMATED REPAIR COST DETAILS Excess : 0.00 Add Excess : 0.00

QTY	DESCRIPTION	REPAIRER AMT (\$)	SURVEYOR AMT (\$)
	TO CHECK AND RECONNECT ALL NECESSARY WIRINGS	30.00	30.00
	Sub Total	1380.00	740.00
	Sub Total	4,586.70	3,946.70
	GST 7.0 %	321.07	276.27
	Total	4,907.77	4,222.97

Surveyor Name : RASUL - LKK

Date & Time : 19/11/2021 11:50:00 AM

Salamatshahh

PAGE : 2

CLAIM DEPARTMENT

DID : 66547519

FAX :