



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile				
AUTO & GENERAL INSURANCE (S) PL (BUDGET DIRECT INSURANCE) 190 CLEMENCEAU AVENUE #03-01 SINGAPORE SHOPPING CENTRESINGAPORE 239924			Ref: CS/AGI21011722/Gqf3n2	Date: 23/03/2022
			Code: AGI	
1. Policy Particulars :- THIRD PARTY CLAIM				
Insured Veh.	SJW 7931C	Veh. Inspected	SNA 8145S	
Policy No.		Coverage (\$)	0.00	
Claim No.	C10012513/EE	Excess (\$)	0.00	
Assign From	IVY RATILLA	Assign Date	17/11/2021	
2. Vehicle Particulars & Condition				
Make & Model	HONDA FIT 1.3	c.c	1317	
Engine No.	HIDDEN	Year of Reg.	2021	
Chassis No.	GR11033416	Colour	BLUE	
Odometer	8192 KM	Steering	IN ORDER	
Brakes	IN ORDER	Modification	STANDARD ALLOY RIM	
General	GOOD			
3. Conditions of Tyres				
	Size	Make	Balance	
R/H Front Tyre	185/60 R15	BRIDGESTONE	8 mm	
L/H Front Tyre	185/60 R15	BRIDGESTONE	8 mm	
R/H Rear Tyre	185/60 R15	BRIDGESTONE	8 mm	
L/H Rear Tyre	185/60 R15	BRIDGESTONE	8 mm	
4. Description of Damages				
THE VEHICLE SUSTAINED DAMAGES AT THE REAR PORTION. DAMAGES SEE DETAILS.				
5. General Information				
Accident Date	16/11/2021	Inspection Date	17/11/2021	
Survey held at	VIN'S MOTOR PTE LTD 160 SIN MING DRIVE #03-03 SIN MING AUTO CITY SINGAPORE 575722			
5a. Remarks				
A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.				
5b. Estimate Days of Repair				
ESTIMATED NORMAL PERIOD FOR REPAIR:		3 Working Days		