

ASS. REC. BY:

REF:

13/TM/240/1727/11453

ASSIGNMENT

From: _____ Date: _____

Estimated Cost: _____

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No: **SHC 2741X**

at Workshop m/s _____

of _____

Insured: **SLQ 4876G**Policy No. **MM000074**Claims No. **M2105333**

Sum Insured: _____ Excess: _____

(Client's Record)

Make of Veh: _____

(Policy Condition)

Remark: The veh had commenced its
repair at the time of inspection.

Bal. or Market Value: _____

IDAC Accident Rpt: _____ Consistent? : Yes or No

GIA / PR Seen: _____ Consistent? : Yes or No

Est. Repairs: **2** days Res.: Yes or NoLum Sum: **20** % 3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Date: _____ Person Contacted: _____

Vehicle: IN / OUT

Veh No: **SHC 2741X**Yr Regn: **2017, Sep**

Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make: **Toyota Prius**c.c. **1798**Colour **Blue**

A/C: Insured / Std / NI / NA

Sp. Reading **565932**

T/Radio: Insured / Std / NI / NA

Eng/No: _____

C/No: **STD KB 3F4 303 564934**

Gen. Cond: Good / Fair / Poor / Burnt

Steering: Inorder / Jammed / Leaked / Burnt or

Brake: Inorder / Jammed / Leaked / Burnt or

Modl: Nil / S/Rim / STD A/Rim or

Tyre Size: **F: 195/65 R15**R: **17/4/21**

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or **Wentlike**

Front

Rear

R/Bal. **6** mmR/Bal. **6** mmL/Bal. **6** mmL/Bal. **6** mm

D.O.A. _____

D.O.I. **17/4/21**Survey held at **Comfort Lodge**

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time Action / Instruction

Confirmed L/S \$850, 2 repair days

(RED \$941.60; 53%)

Date/Time, File Pass to?

☐

: Prel. Report

1) 26/11 TYPIST

☐

: Final Report

Date/Time, File Return to?

2) _____

Rep. Format: **TP**Lump Sum / ~~1841~~ **\$850**Days Of Repair: **2**Resurvey No. of Trip: **1**

Survey Fee:

Transportation:

S + RS \$

Photos

Others

TOTAL

Add Fee:

☐

: Site Insp (\$

☐

: Interview (\$

☐

: Tech. Invs (\$

☐

: Wash and (\$

ComfortDelGro Engineering Pte Ltd (Co.Reg.No:199506048W)

59 Loyang Drive
Singapore 508969
Tel: 6214 8300TP INSURER:
CTPL

Tokio Marine Insurance Singapore Ltd (HQ)

Singapore

PARTICULARS OF CLAIM

Claim Type:	THIRD PARTY	Ref. No:	
Policy No:		Date of Loss:	14/11/2021
Vehicle Reg. No.:	SHC2741X	Driveable?	NO
Party At Fault:	UNKNOWN		
Make/Model:	TOYOTA PRIUS HYBRID, 1.8 CVT TAXI (A)	Vehicle Reg. Date:	28/09/2017
Vehicle Colour:	BLUE	Gen Condition:	GOOD
Engine No:	2ZRS065756	Chassis No:	JTDKB3FU303564934
Odometer:	0 KM		
Paint Type:			
List Item Discount:	25.00 %		
Total Loss?	NO		
Est. Duration of Repair (day)	3		
Present Location:	COMFORTDELGRO ENGINEERING PTE LTD (LOYANG)		

COST OF CLAIMS

	Amount
Parts	960.60
Miscellaneous Items	11.00
Labour	820.00
Paintwork Labour	0.00
Towing	0.00
Gross Total (S\$)	1,791.60
+ GST 7.00% (S\$)	125.41
Nett Amount (S\$)	1,917.01

This claim is handled by: LIM TIEN SIONG

Generated using Merimen e-Claims Internet Estimation & Adjusting System

REPAIR DETAILS**Reference**

Part Source: MRM-SG Version: 1.0 (Last Synchronised: 15 Nov 2021)
Parts: 144 TOYOTA PRIUS HYBRID 1.8 CVT TAXI (A) (Catalogue:Merimen Singapore 1.0)
Labour: Repairer's (Price-denominated Standard List)
Print Code: ComfortDelGro Engineering Pte Ltd/SHC2741X/15/11/2021 14:16
Validity: These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page
Further Info: Items/values not in reference catalogue are prefixed with an asterisk *.

Estimates on Parts

No.	Qty	Part No.	Particulars	%Disc	%Depr	Amount
1	1		*REAR BUMPER	25.00	0.00	*458.60 FL <i>Ry</i>
2	1		*REAR BUMPER CENTRE MOULDING	25.00	0.00	*552.60 FL <i>de</i>
3	10		*REAR BUMPER CLIPS	25.00	0.00	*22.00 FL <i>ner</i>
4	1		*REAR BUMPER MAT	0.00	0.00	*50.00 F <i>K</i>
5	1		*REVERSE SENSORS	0.00	0.00	*135.70 F <i>?</i>
Sub Total (S\$)						1,218.90
- List Item Discount on L Items (S\$)						258.30
Total Parts (S\$)						960.60

F=Franchise part. L=ListItemDisc.

ComfortDelGro Engineering Pte Ltd/SHC2741X/15/11/2021 14:16. Not valid without Reference section.
 Generated using Merimen e-Claims IEAS

Estimates on Miscellaneous Items

No	Qty	Particulars	Amount
Miscellaneous Items			
1	1	OD/TP Case (Insurer)	11.00
Sub Total (S\$)			11.00

Estimates on Labour

No	Particulars	Lab.Type	Amount
Labour Items			
1	PANEL BEATING	New	400.00
2	SPRAY PAINTING	New	300.00
3	R/I REVERSE SENSORS	New	120.00
Gross Labour Cost (S\$)			820.00

ComfortDelGro Engineering Pte Ltd/SHC2741X/15/11/2021 14:16. Not valid without Reference section.
Generated using Merimen e-Claims IEAS

< END OF ESTIMATES >

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer
Signature:
Date:

Tarifkin 97495749
'in' 17/11/2021 @ 3:30 pm
x 2 days
4b rising after repair
tarifkin@lkkauto.com

Date/Time: 15.11.2021 13:36

Page : 1

am: ARC Repair TP(CLSO)1

JOB CARD

Sales Order: 4140876

JC NO 305494560

OMER

S COMFORT TRANSPORTATION PTE LTD

OMER NO. 7010045

ESS 383 SIN MING DRIVE
Singapore SINGAPORE 575717

(R) 65508755

(O)

(P)

OUNT CARD NO.

REGN NO.:

SHC2741X

MILEAGE

MAKE :

TOYOTA

FUEL

E.....1/2.....F

MODEL

PRIUS HYBRID(G4)15.11.2021 10:20

DATE/TIME IN

YR OF MANU.

28.09.2017

TARGET DATE

CHASSIS CODE

JTDKB3FU303564934


COMPLETION DATE/TIME:

JOB DESCRIPTION

cident Date: 14.11.2021
TURE: 3P 14.11.2021

NO LABOR CODE
0010 PB
0020 20-05

DESCRIPTION
PANEL BEATING-SHC2741X
TP MERIMEN



ED & PASSED OUT BY:

SERVICE ADVISOR

CUSTOMER'S SIGNATURE

dgement Slip

Exit Pass

o: SHC2741X

LIMITS

Vehicle No..

SHC2741X

Service Advisor

Signature/Date

Name of Service Advisor

Date

med to Service Reception upon collection

To be kept by Security Guard