

ASSIGNMENT

From: Date:

Estimated Cost:

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No: GBE 371ST

at Workshop m/s: lee brother

of

Insured: SHA 4406L

Policy No.

Claims No.

Sum Insured: Excess:

(Client's Record)

Make of Veh:

(Policy Condition)

Remark: The veh had commenced its repair at the time of inspection.



Bal. or Market Value: \$40k.

IDAC Accident Report: Consistent? : Yes or No

GIA / PR Seen: Consistent? : Yes or No

Est. Repairs: 5 days Res.: Yes or No

Lum Sum: 20 % 3 Val.: Yes or No

CA / REV / REP. / 24 HRS

C 020E
Vehicle: IN / OUT

Date: Person Contacted: LIA 46794

Date / Time Action / Instruction Dep risk.

29/11/13 Confirmed L/S \$7800 w/h MR Lee

Veh No: GBE 371ST Yr Regn: 18/11/15

Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or (M)

Make: Toyota Dyna c.c 2982

Colour: Silver A/C: Insured / Std / NI / NA

Sp. Reading: 197982 T/Radio: Insured / Std / NI / NA

Eng/No:

C/No: KD42318021631

Gen. Cond: Good / Fair / Poor / Burnt

Steering: In order / Jammed / Leaked / Burnt or

Brake: In order / Jammed / Leaked / Burnt or

Modi: Nit / S/Rim / STD A/Rim or

Tyre Size: F: 195 R15

R: 155 R13 Duran

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or Kapsen

Front

Rear

R/Bal. 6 mm R/Bal. 8/6 mm

L/Bal. 6 mm L/Bal. 8/6 mm

D.O.A. 15/11/13 D.O.I. 17/11/13

Survey held at

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

Rat n/s
The U/C / Chassis frame / Body Structure affected due to collision.

Date/Time, File Pass to?

☐ : Preli. Report

1)

☐ : Final Report

Date/Time, File Return to?

2)

Days Of Repair:

Resurvey No. of Trip:

Survey Fee:

Transportation:

) ___ S + RS ___ SI

) Photos

) Others

TOTAL

Report Format :

Lump Sum / I.B.I.: (\$)

Add Fee:

☐ : Site Insp (\$)☐ : Interview (\$)☐ : Tech. Invs (\$)☐ : Weekend (\$)

NO 1 KAKI BUKIT AVE 6 #02-47

AUTOBAY SINGAPORE 417883

Tel : 6509 5521 / 65095524 Fax : 6509 5523

not Authorised
when
17/11/21
1/5 \$ 7800
the photo attached
5 days

The Motor Claims Dept.

AXA INSURANCE SINGAPORE PTE LTD

8 SHENTON WAY

#27-01 AXA TOWER

SINGAPORE 068811

SHA4406L

ESTIMATE

DATE : 18/11/2021

VEHICLE NO : GBE3718T

MAKE/MODEL : TOYOTA DYNA

ACC DATE : 15/11/2021

PARTICULAR		UNIT PRICE	AMOUNT
QTY		SS	SS
<u>LIST PRICE</u>			
1	1 FRONT BUMPER DO 683.90	727.10	727.10 /
2	1 FRONT BUMPER FOG LAMP LH CNE 281.50	371.10	371.10 /
3	1 FRONT BUMPER FOG LAMP COVER TWI 145.00	174.42	174.42 /
4	1 FRONT BUMPER BRACKET LH Bnf 211.60	361.90	361.90 /
5	1 FRONT CORNER PANEL LH R 272.10	272.10	272.10 X
6	1 FRONT CAB PANEL ASSY Body DO 1326.60	1,712.45	1,712.45 /
7	1 FRONT DOOR LH R 1,559.60	1,559.60	1,559.60 X
8	1 FRONT GRILLE ASSY CNE 573.15	573.15	573.15 /
9	1 FRONT HEADLAMP ASSY LH CNE 975.50	1,145.80	1,145.80 /
10	1 FRONT CAB PANEL MOULDING CTR Cuf 299.75	299.75	299.75 /
11	1 FRONT CAB PANEL MOULDING LH Cuf 199.62	199.62	199.62 /
12	1 FRONT WIPER PANEL DO 581.60	581.60	581.60 /
13	1 FRONT WIPER TANK 11 311.50	311.50	311.50 X
14	1 FRONT WINDSCREEN RUBBER 11 299.00	381.25	381.25 /
15	1 AIR CON CONDENSER Bnf/mi 1,011.80	1,011.80	1,011.80 /
16	1 AIR CON CONDENSER BRACKET Bnf 310.50	310.50	310.50 /
17	1 AIR CON CONDENSER ELECTRIC FAN ASSY CNE/11m 861.95	861.95	861.95 /
18	1 AIR CON BLOWER ASSY CNE 1025.30	1,245.90	1,245.90 /
19	1 AIR CON COOLING COIL ASSY 11 1,389.55	1,389.55	1,389.55 X
20	1 AIR CON HEATER ASSY CNE 1,410.50	1,410.50	1,410.50 /
21	1 STEP GARNISH LH Svc 281.60	281.60	281.60 X
		15,183.14	
LESS - 25%		3,795.79	
TOTAL		11,387.36	

SPECIAL NETTS ITEM

1	1 (SET) FRONT BUMPER CLIP 11	45.00	X
2	1 FRONT DOOR R.O.V STICKER 11	45.00	35
		90.00	

PARTICULAR		UNIT PRICE	AMOUNT
QTY		SS	SS
<u>LABOUR CHARGES :</u>			
1	TO CHECK FRONT ELECTRICAL WIRING		80.00 20
2	TO REMOVE & REFIX AIR CON COOLING SYSTEMS & TOP UP GAS	250.00	100
3	TO REMOVE & REFIX DASHBOARD TO ASSIST REPAIR	300.00	180
4	TO RESPRAY UNDERCOATING	150.00	40
5	TO REMOVE, REFIX FRONT WINDSCREEN	120.00	80
6	TO PUTTY, SPRAY PAINT & POLISH AFFECTED PARTS	1,200.00	900
7	TO PANEL BEAT, CUT, WELD, REMOVE & REPLACE DAMAGED PARTS	1,500.00	800
		TOTAL	3,600.00

ESTIMATE PARTS AND LABOUR GRAND TOTAL : \$ 15,077.36

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer
Signature:
Date:

10197-27
252
7647.95
7642 35
80295 2120