

LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 1

PRE-REPAIR INSPECTION REPORT					
	AXA INSURANCE	PTE LTD		Ref:	CS3/ASM21011730/Gvy3e2
	8 SHENTON WAY SINGAPORE 0688		Date:	24/12/2021	
	ATTN: LOH CYNTH	AIA		Code:	ASM
1.	Policy Particulars :- (THIRD PARTY CLAIM)				
	Insured Veh.	SHD 8869S	Veh. Inspected		XD 3548L
	Policy No.		Coverage (\$)		0.00
	Claim No.	S1M03M9M	Excess (\$)		0.00
	Assign From	LOH CYNTHIA	Assign Date		17/11/2021
2. Vehicle Particulars & Condition					
	Make & Model	MITSUBISHI FV51JP4RDEA	c.c		12882
	Engine No.	HIDDEN	Year of Reg.		2009
	Chassis No.	FV51JPA00419	Colour		WHITE
	Odometer	-	Steering		IN ORDER
	Brakes	IN ORDER	Modification		NIL
	General	GOOD			
3. Conditions of Tyres					
		Size	Make		Balance
	R/H Front Tyre	315/80 R22.5	GOLDSHIELD		6 mm
	L/H Front Tyre	315/80 R22.5	GOLDSHIELD		6 mm
	R/H Rear Tyre	315/80 R22.5 (D/D)	GOLDSHIELD		6/6/6/6 mm
	L/H Rear Tyre	315/80 R22.5 (D/D)	GOLDSHIELD		6/6/6/6 mm
4.	Description of Damages				
	THE VEHICLE SUSTAINED DAMAGES AT THE N/S FRONT PORTION.			N.	
5.	General Information				
	Accident Date	02/11/2021	Inspect Date /	Time	21/12/2021 (11:30 AM)
	Survey held at	KUM CHEW MOTOR WORKSHOP			
	160 SIN MING DRIVE #05-08 SIN MING AUTOCITY SINGAPORE 575722				
5a.	Remarks				
	A) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS. B) THE REPAIR ESTIMATE WAS NOT PRESENTED AT THE TIME OF INSPECTION. THE REPAIRER WAS TOLD TO PREPARE THE ESTIMATE. C) ENCLOSED PLEASE FIND DAMAGED VEHICLE PHOTOGRAPHS. D) THE ESTIMATED REPAIR COST OF THE DAMAGED VEHICLE IS IN THE REGION OF \$2,000-\$3,000				
5b.	Estimate Days of Repair				
	ESTIMATED NORMAL PERIOD FOR REPAIR: 3 Working Days				
			01404044700/0		

Report Ref No. CS3/ASM21011730/Gvy3e2

Inspected By

XING GUO QIANG

K.K.LAU CPT(RET)

M.MATAI, AMSAE-A

 $BEng(Hons), B. Bus, MBA, PEng, PE, \, MInstAEA, MASME, MIRTE$

REGD Auto Consultant-SAE, Licensed Appraiser

Automotive Assessor