



Exceptional Journeys

Surveyor : STEVE LKK
Claim : AIG OD
DOA : 18.11.2021
Emailed : 06.12.2021, 5.10pm
Date Survey : 19.11.2021

VEHICLE NO : SMY 9439 Z
MODEL : KIA CERATO 1.6 A GT
WIP : 42700

Material	:	\$	<u>5,356.78</u>
Labour	:	\$	<u>2,830.00</u>
Sub-Total	:	\$	<u>8,186.78</u>
	:	\$	<u>-</u>
Less Excess	:	\$	<u>300.00</u>
Total	:	\$	<u>7,886.78</u>
GST 7%	:	\$	<u>552.07</u>
Grand Total	:	\$	<u>8,438.85</u>
Finalise By/Date	:		<u>LOI / 06/12/2021</u>

5,356.78
2,780.00
8,136.78
-
300.00
7,836.78
548.57
8,385.35
Re-finalise on 7/12/21

☒ REVERT BACK WITHIN 7 DAYS,
OTHERWISE WILL PROCEED WITH INVOICING

☐ SURVEYOR'S REPORT REQUIRED

☐ REPAIR TOOK 0 WORKING DAYS + 0 Days (0) Weekends
+ 0 Days (0) Public Holiday
TOTAL DAYS REPAIR TOOK = 0

☐ TP claim

☐ Claim GIA / LTA fee

☐ Claim Loss of ☐ Use / ☐ Rental

☐ Claim Medical Fee / Others

☐ Third Party Report -

PRO-FORMA INVOICE

Co Reg No : 199405410K

THIS IS NOT AN OFFICIAL TAX INVOICE

GST Reg No : MR-8500111-X

Invoice Name & Address	Owner Name & Vehicle Info	
AIG Asia Pacific Insurance Pte. Ltd. MOTOR CLAIM DEPARTMENT 78 SHENTON WAY #09-16 AIG BUILDING SINGAPORE 079120 Contact No 64191000 19/11/2021	Cust No/Name	LCV14007/THYE POH CHIN WILLIAM @JOHAN BI
	Reg No/Reg Date	SMY9439Z / 31/03/2021
	Date In/Mileage	19/11/2021/ 9393
	Chassis/Package	KNAF5416MM510306C /#
	Engine No	G4FGLH712926
	Make/Model	KIA/CERATO 1.6 A GT LINE H370
	Colour/Trim	KLG STEEL GREY / WK SATURN BLACK

Account No	Terms	Date/Time Printed	CSE	Operator	WIP No			
LAX00000	Credit	07/12/2021/ 10:19	BLE	260 / AiTing	42700			
Description of Goods / Services					Qty	Unit Price	Disc%	Amount
E PNT88000 REPLACE DAMAGED PARTS, REPLACE FRONT BUMPER, BONNET, REPAIR LH FRONT FENDER, AND ALL OTHER AFFECTED AREAS, ADJUST AND ALIGN BODY GAPS ALIGNMENT TO THE SAME								✓ 800.00
E PNT98000 RESPRAY ON FRONT BUMPER, BONNET, LH FRONT FENDER, AND ALL OTHER AFFECTED AREAS TO THE SAME								✓ 1050.00
E PNT88000 REMOVE & REINSTALL A/COND CONDENSOR, & RADIATOR TO FACILITATE REPAIR								? 100.00
A 54900099 CHECK WIRING & ELECTRICAL SYSTEM & ADJUST HEADLAMP AIM								✓ 30.00
A 10028901 CONDUCT DIAGNOSTIC CHECK USING HI-SCAN PRO TEST AND CLEAR TROUBLE CODE								✓ 120.00
M SUNDRY APPLY ANTI CORROSION ON AFFECTED AREAS								✓ 40.00
M SUNDRY SUPPLY BODY PANEL SEALANT								✓ 40.00
M SUNDRY SUNDRIES								✓ 20.00
E PNT88000 MOUNTED ONTO FLOOR BENCH TO STRAIGHTEN FRONT CHASSIS → Supp.								500.00
S SPECIALISTJOB VACUUM & TOP UP A/COND GAS								? 80.00
X EXC EXCESS								-300.00
X LAMP ASSY-HEAD,LH					1.00	✓ 2210.00	20.00	1768.00
X PANEL ASSY-HOOD					1.00	✓ 1502.00	20.00	1201.60
X CLIP-HOOD INSULATING PAD MTG					13.00	✓ 1.00	20.00	10.40
X COVER-FR BUMPER					1.00	✓ 633.00	20.00	506.40
X GRILLE-FRONT BUMPER					1.00	✓ 485.00	20.00	388.00
X MOULDING-FRONT BUMPER,LH					1.00	✓ 216.00	20.00	172.80
X LAMP ASSY-SIDE REPEATER,LH					1.00	✓ 143.00	20.00	114.40
X ABSORBER-FRONT BUMPER ENERGY					1.00	✓ 84.00	20.00	67.20

PRO-FORMA INVOICE

Co Reg No : 199405410K

THIS IS NOT AN OFFICIAL TAX INVOICE

GST Reg No : MR-8500111-X

Invoice Name & Address	Owner Name & Vehicle Info	
AIG Asia Pacific Insurance Pte. Ltd. MOTOR CLAIM DEPARTMENT 78 SHENTON WAY #09-16 AIG BUILDING SINGAPORE 079120 Contact No 64191000 19/11/2021	Cust No/Name	LCV14007/THYE POH CHIN WILLIAM @JOHAN BI
	Reg No/Reg Date	SMY9439Z / 31/03/2021
	Date In/Mileage	19/11/2021/ 9393
	Chassis/Package	KNAF5416MM510306C /#
	Engine No	G4FGLH712926
	Make/Model	KIA/CERATO 1.6 A GT LINE H370
	Colour/Trim	KLG STEEL GREY / WK SATURN BLACK

Account No	Terms	Date/Time Printed	CSE	Operator	WIP No			
LAX00000	Credit	07/12/2021/ 10:19	BLE	260 / AiTing	42700			
Description of Goods / Services					Qty	Unit Price	Disc%	Amount
X	BEAM COMPLETE-FR BUMPER				1.00	✓ 497.00	20.00	397.60
X	CARRIER ASSY-FRONT END MODULE				1.00	675.00	20.00	540.00
X	AIR DUCT-FR BUMPER,LH				1.00	14.00	20.00	11.20
X	COVER-FR BUMPER FOG LAMP,LH				1.00	15.00	20.00	12.00
X	ORNAMENT-KIA NO.115				1.00	32.00	20.00	25.60
X	CLIP				10.00	1.00	20.00	8.00
X	BUZZER ASSY-PIEZO				1.00	58.00	20.00	46.40
X	ANTIFREEZER				1.00	108.98	20.00	87.18
Z	TEXT							
	AIG OD CLAIM							
	DOA : 18.11.21							
	SURVEYOR STEVE LKK 19.11.21							
	POLICY NO : 7210031872 REPAIR 05 DAYS							

Pro Forma

Guarantee Your Warranty, Maintain with Cycle & Carriage!

Parts	5,356.78	Nett	7,836.78
Labour	2,600.00	7% GST on	548.57
Standard Menu	0.00		
Specialist Job	80.00	Total Payable	8,385.35
Diagnostics Job	0.00		
Sundry/Others	-200.00		
Total(w/o GST)	7,836.78		

This is not an official tax invoice.
 This is a computer generated document, no signature is required.



Exceptional Journeys

INSURANCE CO. : **AIG**

Supplementary Parts For Registration No.: **SMY 9439 Z**

<u>Materials</u>		<u>Cost (\$)</u>
1	Cover-fr bumper fog lamp, LH	15.00
2	Ornament-Kia No.115	32.00
3	Clip (x10)	10.00
4	Buzzer assy-Piezo	58.00
5	Antifreezer	108.98
Total		223.98
Less 20% discount		44.80
Total after discount		179.18

<u>Labour</u>		<u>Cost (\$)</u>
1	Mounted onto floor bench to straighten front chassis	500.00
Total Labour		500.00
Taxable amount		679.18
7% GST		47.54
Grand total		<u>\$ 726.73</u>

Thank You.

Yours faithfully

LOI AI TING
Senior Officer - Admin
KIA SERVICE CENTRE
DID : 6568 4556 / 6568 4501
FAX : 6567 5258 / 6565 1240

CAR NO: SMY9439ZWIP: 42700

(ADDITIONAL PARTS CHANGE)

SNO	PARTS NAME	? / SUPP	CSA SIGN	PHOTO TAKEN	REMARKS
1	Air duct - F&T Bumper LH	? / SUPP		✓ PR	86541 M6000
2	Cover - FR Bumper Footump LH	? / SUPP		✓ CM	86563 M6010
3	Beamer complete 1st type	? / SUPP			64100 M6000
4	Carrier Assy	? / SUPP		✓ PR	64101 M6001
5	Ornament - (KID)	? / SUPP		✓ MC	86318 3R500
6	Clips bumper 10ps	? / SUPP		✓ MC	14206 08250B 10ps
7	Bumper Assy Piezo	? / SUPP		✓ PR	95710 R2000
8	COOLANT	? / SUPP		✓ MC	Stem 9411/21 07/0000421
9		? / SUPP			
10	Swivel for chassis \$500	? / SUPP			
11	RT gas can condenser & radiator \$102	? / SUPP			
12	Top up for car gas \$80	? / SUPP			
13		? / SUPP			
14		? / SUPP			
15	+ 3dmg	? / SUPP			
16		? / SUPP			
17		? / SUPP			
18		? / SUPP			
19		? / SUPP			
20		? / SUPP			


PHOTO BEFORE PAINT	DATE	TAKEN BY
PHOTO AFTER PAINT	26/11/21	ch
PHOTO OF MOUNT TO CELLETE BENCH		
REMOVE AND INSTALL ENGINE		
REMOVE AND INSTALL DASHBAORD		
REMOVE & INSTALL FUEL TANK		
PHOTO UNDERCARRIAGE PARTS		

MODEL: CERATOSURVEYOR: STEVE

Fault Code Searching

Rescan

Save



System	Status	Result
ENGINE	No Current DTC	Good
AT	No Current DTC	Good
ABSESC	No Current DTC	Good
AIRBAG	No Current DTC	Good
AIRCON	No Current DTC	Good
EPS	No Current DTC	Good

System	DTC	Description	State
--------	-----	-------------	-------

No History or Pending DTC

S/W Ver.

M-E-K-01-00-0259

VCI Ver.

02.63

ECU Ver.

M-E-K-01-00-0199

OS Ver.

Android 10