



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile				
SOMPO INSURANCE SINGAPORE PL 50 RAFFLES PLACE #03-03 SINGAPORE LAND TOWERSINGAPORE 048623			Ref: CS/SMO21011801/Ktf3n2	
			Date: 20/12/2021	
			Code: SMO	
1. Policy Particulars :- THIRD PARTY CLAIM				
	Insured Veh.	SJP 3947X	Veh. Inspected	SMV 4054Z
	Policy No.		Coverage (\$)	0.00
	Claim No.	CMTD2103417/GPL	Excess (\$)	0.00
	Assign From	MELVIN YE YONG KANG	Assign Date	19/11/2021
2. Vehicle Particulars & Condition				
	Make & Model	HONDA VEZEL (A)	c.c	1496
	Engine No.	HIDDEN	Year of Reg.	2016
	Chassis No.	RU11204556	Colour	METALLIC SILVER
	Odometer	76619 KM	Steering	IN ORDER
	Brakes	IN ORDER	Modification	STANDARD ALLOY RIM
	General	GOOD		
3. Conditions of Tyres				
		Size	Make	Balance
	R/H Front Tyre	215/60 R16	YOKOHAMA	9 mm
	L/H Front Tyre	215/60 R16	YOKOHAMA	9 mm
	R/H Rear Tyre	215/60 R16	YOKOHAMA	9 mm
	L/H Rear Tyre	215/60 R16	YOKOHAMA	9 mm
4. Description of Damages				
	THE VEHICLE SUSTAINED DAMAGES AT THE REAR PORTION. DAMAGES SEE DETAILS.			
5. General Information				
	Accident Date	18/11/2021	Inspection Date	19/11/2021
	Survey held at	FALCON-AIR AUTO SERVICES PTE LTD (HQ) 176 SIN MING DRIVE #01-06/07/13, SIN MING AUTOCARE SINGAPORE 575721		
5a. Remarks				
	A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.			
5b. Estimate Days of Repair				
	ESTIMATED NORMAL PERIOD FOR REPAIR:		9 Working Days	