

From: CS/SMR21011853/Etf3
 Estimated Cost: 12000
 To inspect Vehicle No. of Workshop m/s
 Policy No. 12000
 Claim No.
 Sum Insured: Excess
 Make of Veh.
 (Policy Condition)
 Remarks: The vehicle exhibited no signs of repair at the time of inspection.
 Dist. or Major Vols.
 IDAC Accident Report: Consistent? Yes or No
 SIA / PR Sect: Consistent? Yes or No
 Est. Repairs: days Rep. Yes or No
 Cum Sum: % Vol. Yes or No
 GA / REV / REP. / 24 HRS
 Date: Person Contacted:



Veh No: SFE 23L YR Reg: 5/6/13
 Type: M. Car / M. Cycle / Bus / Van / Lorry / Truck / Trailer or
 Make: BMW 3 Series YR 1997
 Colour: Brown A/G: Insured / Stolen / H
 Sp. Reading: 69213 YR Reg: Insured / Stolen / H
 Eng/No:
 O/Nos: WBAB816060NP55139
 Gen. Condi: Good (V) / Poor / Buzpt
 Steering: In Op / Jammed / Locked / Burnt or
 Brake: In Op / Jammed / Locked / Burnt or
 Mod: Nil / 13 / 14 / 15 / 16 / 17 or
 Tyre Size: P1 225/50R17 RI
 BY / DUN / EX / NOVA / OY / FS / LIZA / MIC / OHTU / PIA / SUBA /
 TOYO / YOKO or B
 Front R/Wal: 5 mm R/Wal: 5 mm
 U/Wal: 5 mm U/Wal: 5 mm
 O.A.: 17/11/21 Performance Mats
 Survey hold of
 Des. of Damages: P1 / P2 / P3 / P4 / P5 / P6 / P7 / P8 / P9 / P10 / P11 / P12 / P13 / P14 / P15 / P16 / P17 / P18 / P19 / P20
 The V/L or B/Wal from / Body Structure affected due to collision

Date / Time	Action / Instruction
	MV-44K
	COR 4.629.85 3DAYS
	RED: 1966.15 ; 29%

Days of Repair: 3
 Resurvey No. of Trips:
 Add Fee: Site Insp (\$)
 Interview (\$)
 Tech. Insp (\$)
 Witness (\$)
 Survey Fee: Transportation
 S & RS
 Parks
 Other
 Rental

Performance Motors Limited

A Sime Darby Motors Company
Co. Reg. No. 197401859N GST Reg. No M2-0020081-X
Toll-Free Number (1800-2285269)



303, Alexandra Road
Sime Darby Performance Centre
Singapore 159941
Fax: 64747270

280, Kampong Arang Road
East Coast Centre
Singapore 438180
Fax: 63449773

115, Alexandra Road
Sime Darby Business Centre
Singapore 159944
Fax: 64796601 (AfterSales)
64796624 (Motorrad)

GST REG. NO : M2 - 0020081 - X

ESTIMATE

Estimate No. : b1 60067	Page No. : 1 of 5
Date Estimated : 19/11/2021	
Prepared By : Foong Shiuh Jye	

- ESTIMATE REPAIR FOR - Ong Wei-Wei 20 Pine Grove #01-01 Cavendish Park Singapore 597595	- ACCOUNT - 303 MS First Capital Insurance Limited 6 Raffles Quay #21-00 Singapore 048580
---	--

REGN. NO.	CHASSIS NO.	REGN. DATE	MODEL	MILEAGE
SFE23L	WBA3B16060NP55139	05/06/2013	320iA/4	65837

DESCRIPTION	VALUE
To replace rear bumper including to knock out dented area caused by the accident	850 1,275.00
To respray rear bumper	986 1,038.00
To remove old PDC assembly, replace damaged parts and reconnect to new bumper including conduct check for proper function.	168 177.00
To check electrical wiring system and lighting at the rear section for proper function.	168 177.00
To replace rear exhaust silencer including alignment system and conduct check for leak.	531.00
Sundries.	80.00
Total Labour 1:	3,278.00

DESCRIPTION	QTY	PRIC	VALUE
RR SILENCER CLAMPING BUSH ? x nn	1	60.90	60.90
TAILPIPE TRIM CHROME ? x nn	1	125.25	125.25
REAR MUFFLER ? x nn	1	1,025.30	1,025.30
RR BUMPER BOTTOM REINFORCEMENT ? - BR	1	62.60	62.60
REAR BUMPER CENTRE GUIDE ? x nn	1	153.50	153.50
REAR BUMPER CARRIER (ECE) ? - BT	1	470.25	470.25
DECORATIVE STRIP (LUXURY LINE) - mis	1	82.85	82.85
# RR BUMPER TRIM PANEL PRIMED - DO	1	1,058.30	1184.75 - 1,058.30
RR BUMPER FLAP TOWING EYE PRIMED x nn	1	43.70	43.70
REAR PDC HOLDER SET - ACC nn	1	25.75	25.75
GROMMET - ACC	2	0.80	1.60
REAR SILENCER HEAT SHIELD ? - BT	1	73.60	73.60
PLAQUE 82MM ? x nn	1	71.95	71.95
PLUG BLACK D=5MM - ACC x nn	10	0.95	9.50
(DG/SL) ADHESIVE SET K6 - ACC	1	53.05	53.05

Performance Motors Limited

A Sime Darby Motors Company
 Co. Reg. No. 197401559W GST Reg. No M2-0020081-X
 Toll-Free Number (1800-2255269)



303, Alexandra Road
 Sime Darby Performance Centre
 Singapore 159941
 Fax: 64747770

280, Kampong Arang Road
 East Coast Centre
 Singapore 438186
 Fax: 63449773

115, Alexandra Road
 Sime Darby Business Centre
 Singapore 159944
 Fax: 64786601 (AfterSales)
 64786624 (Motorrad)

GST REG. NO : M2 - 0020081 - X

ESTIMATE

Page No. : 2 of 5

Estimate No. : b1 60067
 Date Estimated : 19/11/2021
 Prepared By : Foong Shiuh Jye

REGN. NO.	CHASSIS NO.	REGN. DATE	MODEL	MILEAGE
SFE23L	WBA3B16060NP55139	05/06/2013	3201A/4	65837

Total Parts : 3,318.10

*Steve (LKK)
 7/12/21, 11.00am*

*ML PL
 3 yrs
 PIP
 M Bel SJ*

- LKK Auto Consultants hence notify the Repairer of the following:
- To resurvey before/after spray painting
 - To display damaged part(s) during resurvey
 - Parts prices are subject to confirmation
 - Third party survey is on a "Without Prejudice" basis
 - No illegal modification(s) is allowed
 - Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer
 Signature:
 Date:

6596



Labour 1	:	3,278.00
Parts	:	3,318.10
Labour 2	:	0.00
Excess	:	0.00
Total GST @ 7%	:	461.73
Grand Total	:	7,057.83

** THIS ESTIMATE IS VALID FOR A PERIOD OF 30 DAYS ONLY**
 ** PRICE FOR PARTS ARE SUBJECTED TO CHANGE WITHOUT PRIOR NOTICE **

SINGAPORE ACCIDENT STATEMENT

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver
3. Information provided must be as truthful and accurate as possible. Any willful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. **Any false reporting may be referred to the Police for investigation.**
6. This report will be forwarded by the Insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

ACCIDENT STATEMENT

Date of Submission	17/11/2021 18:53 (SGT)
Date of Accident	17/11/2021 11:20 (SGT)
Exact Location of Accident	Stevens Rd, Singapore
Additional Location Information	-
Country/State of Loss	Singapore

DETAILS OF OWN VEHICLE

Vehicle Registration Number	SFE23L
-----------------------------	--------

INSURED/POLICYHOLDER

Is company?	No
Name Of Registered Owner	ONG WEI WEI
NRIC No	SXXXX502A
Email Address	W2ONG@YAHOO.COM
Mobile Phone No	(Phone) +65-97650800
Alternative Phone No	(Home) +--

VEHICLE PARTICULARS

Manufacturer	BMW
Model	320i
Variant	-
Exact purpose for which vehicle was being used at time of accident	-
Are you claiming under your own insurance policy for repair to your vehicle?	No - Claiming third party
Vehicle Category	Private car
Transmission	Auto
CC	1998

INSURANCE COMPANY

Name of Insurance Company	MSIG Insurance (Singapore) Pte. Ltd.
Type of Coverage	Comprehensive
Fleet Policy	No
Policy Number	-
Cover Note Number	-

DRIVER

Name of Driver	ONG WEI WEI
NRIC No	SXXXX502A

Date Of Birth	07/10/1969
Occupation	Indoor
Date Of Driving Pass	05/01/1994
Driving experience	27 YEARS AND 10 MONTHS
Gender	Female
Mobile Number	(Phone) +65-97650800
Alt. Phone Number	(Home) +--
Email Address	W2ONG@YAHOO.COM
Address	20 PINE GROVE
Address complement	#01-01
Postcode	597595
Is the driver the policyholder?	Yes
If No, Relationship of the Driver with the Insured	-
Does Driver Own Other Vehicles?	No
Vehicle Registration Number of Other Vehicle Owned by Driver	-
Insurance Company of Other Vehicle Owned by Driver	-

GENERAL INFORMATION OF THE ACCIDENT

Type of Accident	Collision - Head to Rear
Weather Conditions	Raining
Road Surface	Wet

OTHER INFORMATION

Was any foreign vehicle involved in the accident?	No
Number of vehicles involved in the accident	2
Was anybody injured in the Accident?	No
Was any injured conveyed to hospital by ambulance?	-
Was any other vehicle or property damaged?	Yes
Number of Passengers (Including Driver)	1
Has the driver been approached by unknown person(s) soliciting/offering accident claims assistance?	No

DETAILS OF POLICE ACTION

Was the accident reported to the police?	No
Was notice of intended Prosecution given?	No
If yes, against whom?	-

CIRCUMSTANCES OF ACCIDENT

SEE ATTACHED SKETCH

ATTACHMENT(S)

Are accident photos available for attachment?	Yes
Was there any video captured by Car Camera?	No
Was there any audio recorded?	No

DETAILS OF OTHER VEHICLE PROPERTY 1

Vehicle Registration Number	SHD6130C
Vehicle Manufacturer	Toyota
Vehicle Model	Prius
Vehicle Variant	-
Vehicle Colour	-
Vehicle Category	Taxi
Name of Driver	ONG SOON LEE
NRIC No	SXXXX048H
Contact Number	-
Address	BLOCK 176B EDGEFIELD PLAINS

Address complement
Postcode
Insurance Company Name
Nature Of Damage
Details of property damaged in accident
No. Of Passenger (Including Driver)

#08-168

822176

-

-

-

-

SKETCH PLAN

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. The report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
7. By the lodgment of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.
8. **Consent under the Personal Data Protection Act (PDPA)**

I understand, acknowledge, agree and consent that:

- (a) My insurer, my workshop and the General Insurance Association of Singapore ("GIA") may/are permitted to collect, use, disclose and/or process my personal data/personal information set out in this [form] and any other personal information provided by me or possessed by my insurer (collectively the "Personal Information") and disclose and transfer such Personal Information to all insurer(s) who have insured vehicle(s) involved in this accident (all insurer(s) who have insured vehicle(s) involved in this accident shall be collectively referred to as the "Insurers"), the Insurers' lawyers/law firms, the Monetary Authority of Singapore and any relevant government agency/authority (such as the police), for the purpose(s) of:
 - (i) processing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigations relating to the claims;
 - (ii) investigating the accident and/or my claims;
 - (iii) carrying out and/or dealing with my instructions or responding to any enquiries by me;
 - (iv) administering my claims (including the mailing of correspondence, statements, invoices, reports or notices to me, which could involve disclosure of certain personal data about me to bring about delivery of the same as well as on the external cover of envelopes/mail packages); and/or
 - (v) complying with applicable law in administering, processing, handling and/or dealing with my claims. (collectively the "Purposes")
- (b) all insurer(s) who have insured vehicle(s) involved in this accident and the Insurers' lawyers/law firms, may/are permitted to collect, use, disclose and/or process my Personal Information for one or more of the above Purposes; and
- (c) my Personal Information may/can be disclosed by any of the Insurers and/or GIA to their third party service providers or agents (including their lawyers/law firms), which may be sited outside of Singapore, for one or more of the above Purposes.
- (d) my Personal Information will also be collected and used to compile claims history for the purpose of fraud detection, investigation and management in present and all future claims.
- (e) the information so collected under (d) above may be shared / disclosed:
 - (i) to all insurers and/or any other third parties that assist in evaluating, investigating, controlling or managing fraud, regulators, law enforcement and government agencies as reasonably required for the purposes stated, or
 - (ii) for complying with requirements under any regulations, laws or court orders.



Policyholder's Signature

Date & Time: 17/11/21 2PM

Driver's Signature

(If driver is not the policyholder)

Date & Time:




Reporting Centre Personnel's Signature

Name:

NRIC/FIN No.:

SKETCH PLAN



DESCRIBE CIRCUMSTANCES OF THE ACCIDENT

- Incident occurred on 17/11/21 Wed at 11:20AM.
- I (SFE 23L) was stationary, queuing to U-turn at Stevens Road (outside Taylor's Club service entrance) on the Right lane, to U-turn to Scotts Road.
- The taxi 'SHD 6130C' was driving very fast, approaching my car and banged into my stationary vehicle.
- My car was stationary as I was in the queue to U-turn. There was a line of cars ahead of me.
- Taxi collided into my car, damaged my rear bumper. A piece of my bumper detached and dropped on the road.

DECLARATION

I/We declare the foregoing particulars are true in every respect.

[Signature]
 Policyholder's Signature
 Date & Time: 17/11/21
 2pm

 Driver's Signature
 (If driver is not the policyholder)
 Date & Time:

[Signature]
 Reporting Centre Personnel's Signature
 Name:
 NRIC/FIN No.: