

(08/11/13) Wef

ASS. REC. BY: AM

REF:

CC4/GRB2101/1859/Ries

1069

CAG XPRM. 22/22/APR

ASSIGNMENT

From:

Date:

Estimated Cost:

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No: SKF 1551Hat Workshop m/s PERFORMANCEof 303, ALGAMARA RDInsured: 111

Policy No.

Claims No.


Sum Insured:

Excess:

(Client's Record)

Make of Veh:

(Policy Condition)

Remark: The veh had commenced its
repair at the time of inspection.Bal. or Market Value: 18K

IDAC Accident Rpt:

Consistent?: Yes or No

GIA / PR Seen:

Consistent?: Yes or No

Est. Repairs:

days

Res.: Yes or No

Lum Sum:

%

3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Vehicle: IN / OUT

Date:

Person Contacted:

Date / Time

Action / Instruction

REPAIR LIMIT - 1K

Veh No:

SKF 1551H

Yr Regn:

2012 / APR

Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make:

B.M.W 116I AT

C.C

1598

Colour

BLUE

A/C:

Insured / Std / NI / NA

Sp.Reading

75868

T/Radio:

Insured / Std / NI / NA

Eng/No:

C/No:

WDA1A12020EG51157

Gen. Cond: Good / Fair / Poor / Burnt

Steering: In order / Jammed / Leaked / Burnt or

Brake: In order / Jammed / Leaked / Burnt or

Modi: Nil / S/Rim / STD A/Rim or

Tyre Size:

F:

205/50R17

R:

B8 / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or

Front

Rear

R/Bal.

6

mm

R/Bal.

6

mm

L/Bal.

6

mm

L/Bal.

6

mm

D.O.A.

04/09/21

D.O.I.

23/11/21

Survey held at

PERFORMANCE

Des. of Damages: Frt / Rear / O/S / (N/S) / UIC / Rooftop or

The UIC / Chassis frame / Body Structure affected due to collision.

Date/Time, File Pass to?



Prel. Report



Final Report

1)

Date/Time, File Return to?

2)

Days Of Repair:

Resurvey No. of Trip:

Survey Fee:

Transportation:

Add Fee:



Site Insp (\$

), S + RS, SI



Interview (\$

) Photos



Tech. Invs (\$

) Others



Weekend (\$

)

Report Format :

Lump Sum / I.B.I. (\$

> Back to OneMotoring

Enquire PARF/COE Rebate for Registered Vehicle

Owner ID Type:	Singapore NRIC
Owner ID:	106G
Vehicle No.:	SKF1551H
Vehicle to be Exported:	No
Intended Deregistration Date:	24 Nov 2021
Vehicle Make:	B.M.W.
Vehicle Model:	116i AT ABS D/AIRBAG 2WD HID 5DR
Primary Colour:	Blue
Manufacturing Year:	2012
Engine No.:	A529J168N13B16A
Chassis No.:	WBA1A12020E951157
Maximum Power Output:	100.0 kW (134 bhp)
Open Market Value:	\$27,818.00
Original Registration Date:	30 Apr 2012
First Registration Date:	30 Apr 2012
Transfer Count:	0
Actual ARF Paid:	\$27,818.00
PARF Eligibility:	Yes
PARF Eligibility Expiry Date:	29 Apr 2022
PARF Rebate Amount:	\$13,909.00
COE Expiry Date:	29 Apr 2022
COE Category:	A - Car (1600cc & below)
COE Period(Years):	10
QP Paid:	\$64,201.00
COE Rebate Amount:	\$2,764.00
Total Rebate Amount:	\$16,673.00

The information contained herein is correct as at 24 Nov 2021

OK

BMW 1 Series 116i

[Overview](#)

[Financial](#)


[Accessories](#)

[Similar](#)

[Research](#)

[Photos](#)

[Map](#)



Price

\$35,800

Depreciation

\$21,570 /yr

[View models with similar depreciation](#)

Reg Date

27-Feb-2013

(1yr 3mths 2days COE left)

Mileage

118,124 km (13.5k/yr)

Manufactured

2012

Road Tax

\$742 /yr

Transmission

Auto

Dereg Value

\$20,114 as of today (change)

OMV

\$27,342

COE

\$84,097

ARF

\$17,342

Engine Cap

1,598 cc

Power

100.0 kW (134 bhp)

Curb Weight

1,310 kg

No. of Owners

3