

# COMFORTDELGRO ENGINEERING

ComfortDelGro Engineering Pte Ltd  
59 Loyang Drive Singapore 508969

Our Ref : 3052915204 Via Fax : Email  
Date : 22-11-21 Your Insured : SKJ 2477E  
Time of Fax : \_\_\_\_\_ Date of Acc : 21-11-21

Attn: Motor Claims Department BLG

Dear Sirs

**SURVEY OF CLIENT'S DAMAGED VEHICLE REG NO. SH** D-4777A

Our client has engaged us to repair the above vehicle and submit claims against the other party/parties involved in the accident.

In accordance to the motor claims framework, we hereby request your presence at 59 Loyang Drive, Singapore 508969 to survey our client's damaged vehicle.

Enclosed, please find:

- i) Our initial estimate of repairs of the damaged vehicle;
- ii) Accident report made by our client.

I would appreciate it if you could call us to arrange for the survey of the vehicle:

◆ Lim Kwok Eng	Tel: 6214 8355 or HP: 9824 0811
◆ <b>Jumani Bin Masudin</b>	<b>Tel: 6214 8315 or HP: 9635 5305</b>
◆ Lim Tien Siong	Tel: 6214 8398 or HP: 9635 8546
◆ Chiang Liat Choon	Tel: 6214 8314 or HP: 9296 6006

} **jumanibm@cdge.com.sg**  
**Fax no. 6546 8156**

→ If we do not hear from you within the next 48 hours, we shall deem that you have waived your rights to survey our client's vehicle and we shall proceed to engage independent surveyor without further reference to you. We henceforth reserve our rights to claim for Loss of Use and Loss of Rental during any delayed period of this survey arrangement.

This is an initial estimate based on a visual inspection of the above vehicle. The final repair quantum will be prepared after the vehicle is surveyed by a Motor Surveyor appointed by the Insurance company.

Thank you.

Yours faithfully

  
For Vice President  
Taxi Accident Repair

## INSURER ENQUIRY

**Find  
insurer**

Vehicle reg. no.

SKJ2477L

Date of Accident

21/11/2021 📅

Reset

% **RESULT & RECEIPT**

## TP Insurer Enquiry

Insurance ..... **AIG Asia Pacific Insurance Pte....**Period of Insurance ..... **07/03/2021 - 06/03/2022**Requested By ..... **Janet Lim Siang Gek (COMFOR...**Requested Date ..... **22/11/2021 13:53****Payment details**Request Amount: **S\$1.87**GST Amount: **S\$0.13**Total Amount Due (GST Inclusive): **S\$2****General Insurance Association**

Records Management Centre

GST Registration No: **M400017735**

Date/Time: 22.11.2021 14:17

Page : 1

am: ARC Repair TP(CLSO)1

**JOB CARD** Sales Order: 4143088

JC NO305495204

OMER

S COMFORT TRANSPORTATION PTE LTD  
OMER NO. 7010045  
ESS 383 SIN MING DRIVE  
Singapore SINGAPORE 575717  
(R) 65508755 (O)  
(P)

JUNT CARD NO.

REGN NO.:

**SHD4777A**

MILEAGE

MAKE:

**HYUNDAI**

FUEL

E.....1/2.....F

MODEL

**IONIQ(G3)**

22.11.2021 11:00

DATE/TIME IN

YR OF MANU.

**07.11.2019**

TARGET DATE

CHASSIS CODE


**KMHC851CVLU188340**

COMPLETION DATE/TIME:

JOB DESCRIPTION

Accident Date: 21.11.2021  
NATURE: 3P.21.11.2021

NO LABOR CODE DESCRIPTION



KED & PASSED OUT BY:

SERVICE ADVISOR

CUSTOMER'S SIGNATURE

edgement Slip

Exit Pass

Io.: **SHD4777A**

**JU AIG**

Vehicle No.:

**SHD4777A**

Service Advisor

Signature/Date

Name of Service Advisor

Date

urned to Service Reception upon collection

To be kept by Security Guard

### REPAIR ESTIMATE\*

**AIG**

Qty	Parts Description/ Labour	Type	Unit Price	Amount
1	REAR BUMPER ASSY			\$459.40
1	REAR BUMPER UNDER COVER			\$451.25
1	REAR BUMPER CLIPS			\$22.00
1	REAR BUMPER BEAM			\$394.80
1	REAR FOG LAMP			\$201.50
1	ANTENNA – SMARTKEY			\$40.50
				\$1,569.45
	SUB TOTAL			\$1,569.45
	LESS 20%			\$313.89
	DISCOUNTED TOTAL			\$1,255.56
	REVERSE SENSOR			\$137.50 NET
	REAR NUMBER PLATE			\$50.00 NET
				\$187.50
	Labour Charge			
	PANEL BEATING			\$400.00
	SPRAY PAINT			\$300.00
	REMOVE / REFIX REVERSE SENSOR			\$80.00
				\$780.00
	TOTAL LABOUR			\$780.00
	ESTIMATE TOTAL			\$2,223.06
This is an initial estimate based on a visual inspection of the above vehicle. The final repair quantum will be prepared after the vehicle is surveyed by a motor Surveyor appointed by the insurance company.				