

File No. BY: Thevan


File No. CS/FCI21011866/VU13

# ASSIGNMENT

From: \_\_\_\_\_ Date: \_\_\_\_\_  
 Estimated Cost: \_\_\_\_\_  
OD/TP/WS/TP RES/OD RES/EVA/INV/MV  
 To Inspect Vehicle No: \_\_\_\_\_  
 at Workshop m/s \_\_\_\_\_  
 of \_\_\_\_\_  
 Insured: \_\_\_\_\_  
 Policy No. \_\_\_\_\_  
 Claims No. D21003218 MFCE  
 Sum Insured: \_\_\_\_\_ Excess: 1500  
 (Client's Record)  
 Make of Veh: \_\_\_\_\_

(Policy Condition)

Remark: The veh had commenced its repair at the time of inspection.



Bal. or Market Value: \_\_\_\_\_  
 IDAC Accident Rpt: \_\_\_\_\_ Consistent? : Yes or No  
 GIA / PR Seen: \_\_\_\_\_ Consistent? : Yes or No  
 Est. Repairs. 4 days Res.: Yes or No  
 Lum Sum: \_\_\_\_\_ % 3 Val.: Yes or No  
 CA / REV / REP. / 24 HRS  
 Date: \_\_\_\_\_ Person Contacted: \_\_\_\_\_ Vehicle: IN / OUT

Veh No: FBS41593 Yr Regn: 19/4/21  
 Type: M/Car / M/Cycle / Bus / Van / Lorry / Taxi / Prime Mover /  
 Truck / Trailer or  
 Make: Honda CRB 400 XA c.c. 399  
 Colour: white A/C: \_\_\_\_\_ Insured / Std / NI / NA  
 Sp. Reading: 13189 T/Radio: Insured / Std / NI / NA  
 Eng/No: \_\_\_\_\_  
 C/No: SH2we569dtk000319  
 Gen. Cond: Good / Fair / Poor / Burnt  
 Steering: In order / Jammed / Leaked / Burnt or  
 Brake: In order / Jammed / Leaked / Burnt or  
 Mod: Nil / S/Rim / STD A/Rim or  
 Tyre Size: F: 110/80R19  
 R: 110/80R19  
BS/DUN/EXNOVA/GY/FS/LIZA/MIC/OHTSU/PIR/SUMI/  
 TOYO/YOKO or

Front Rear  
 R/Bal. 7 mm R/Bal. 7 mm  
 L/Bal. 7 mm L/Bal. 7 mm  
 D.O.A. 15/11/21 D.O.I. 21/11/21 1200  
 Survey held at Ban Hock Hin  
 Des. of Damages: Fr Rear / O/S / N/S U/C / Rooftop or

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time	Action / Instruction
	rebate: 7288 F: 4793.7
	excess: 1500 DOR: 4
	not yet authorise
	MV: <del>22500</del> 22500 Brand new 23000 from boon stew
	NV: <del>15212</del> 15212
24/1/22	Thevan informed final fig \$4793.70 (red 565, 10%)

Date/Time, File Pass to? ☐ : Prelim. Report  
☐ : Final Report  
 Date/Time, File Return to?

Days Of Repair: 4  
 Resurvey No. of Trip: 1

Survey Fee:	
Transportation:	
S + P.S. \$	
Fuel	
Others	
TOTAL	

Add Fee: ☐ : Site Insp (\$) ☐ : Interview (\$) ☐ : Tech. Insp (\$) ☐ : Wheel end

24/1/22-typist

Report Form: OD

Final Sum / F.D. : \$4793.70

> Back to OneMotoring

### Enquire PARF/COE Rebate for Registered Vehicle

<b>Vehicle Owner Particulars</b>	
Owner ID Type:	Company
Owner ID:	882K
<b>Vehicle Details</b>	
Vehicle No.:	FBS4159B
Vehicle to be Exported:	No
Intended Deregistration Date:	24 Nov 2021
Vehicle Make:	HONDA
Vehicle Model:	CB400XA
Primary Colour:	White
Manufacturing Year:	2019
Engine No.:	NC56E5000309
Chassis No.:	JH2NC5690KK000319
Maximum Power Output:	-
Open Market Value:	\$7,718.00
Original Registration Date:	19 Apr 2021
First Registration Date:	19 Apr 2021
Transfer Count:	0
Actual ARF Paid:	\$2,109.00
<b>Intended PARF Rebate Details</b>	
PARF Eligibility:	No
PARF Eligibility Expiry Date:	-
PARF Rebate Amount:	\$0.00
<b>Intended COE Rebate Details</b>	
COE Expiry Date:	18 Apr 2031
COE Category:	D - Motorcycle
COE Period(Years):	10
QP Paid:	\$7,752.00
COE Rebate Amount:	\$7,288.00
<b>Total Rebate Amount:</b>	<b>\$7,288.00</b>

The information contained herein is correct as at 24 Nov 2021

OK

## Vehicle Details

Vehicle No.	Make / Model
<b>FBS4159B</b>	<b>HONDA / CB400XA</b>
Vehicle Type :	Vehicle Attachment 1 :
<b>P00 - Passenger Motorcycle/Autocycle /Moped</b>	<b>No Attachment</b>
Vehicle Scheme :	Chassis No. :
<b>Normal</b>	<b>JH2NC5690KK000319</b>
Propellant :	Engine No. :
<b>Petrol</b>	<b>NC56E5000309</b>
Motor No. :	Engine Capacity :
<b>-</b>	<b>399 cc</b>
Power Rating :	Maximum Power Output :
<b>-</b>	<b>-</b>
Maximum Laden Weight :	Unladen Weight :
<b>386 kg</b>	<b>197 kg</b>
Year Of Manufacture :	Original Registration Date :
<b>2019</b>	<b>19 Apr 2021</b>
Lifespan Expiry Date :	COE Category :
<b>-</b>	<b>D - Motorcycle</b>
Quota Premium :	COE Expiry Date :
<b>\$7,752.00</b>	<b>18 Apr 2031</b>
Road Tax Expiry Date :	PARF Eligibility Expiry Date :
<b>18 Oct 2022</b>	<b>-</b>
Inspection Due Date :	Intended Transfer Date :
<b>18 Apr 2024</b>	<b>24 Nov 2021</b>
CO2 Emission :	CEV/VES Rebate Utilised Amount :
<b>-</b>	<b>-</b>
CO Emission :	HC Emission :



## SINGAPORE ACCIDENT STATEMENT

### IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. **Any false reporting may be referred to the Police for investigation.**
6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

### ACCIDENT STATEMENT

Date of Submission	17/11/2021 09:34 (SGT)
Date of Accident	15/11/2021 21:30 (SGT)
Exact Location of Accident	Bedok S, Singapore
Additional Location Information	BEDOK SOUTH AVE 1
Country/State of Loss	Singapore

### DETAILS OF OWN VEHICLE

Vehicle Registration Number	FBS4159B
-----------------------------	----------

#### INSURED/POLICYHOLDER

Is company?	Yes
Name Of Registered Owner	CERTIS CISCO AUXILIARY POLICE FORCE PTE LTD
Company Reg No	2XXXXX882K
Email Address	JEREMYC_QUEK@CERTISGROUP.COM
Mobile Phone No	(Phone) +65-68428849
Alternative Phone No	(Office) +65-68428849

#### VEHICLE PARTICULARS

Manufacturer	Honda
Model	Cb400x
Variant	-
Exact purpose for which vehicle was being used at time of accident	-
Are you claiming under your own insurance policy for repair to your vehicle?	Yes
Vehicle Category	Motorcycle
Transmission	Manual
CC	400

#### INSURANCE COMPANY

Name of Insurance Company	MS First Capital Insurance Ltd
Type of Coverage	Comprehensive
Fleet Policy	Yes
Policy Number	D-2109290MFCE/133
Cover Note Number	-

#### DRIVER

Name of Driver	MOHAMAD ZULFADLY BIN MOHAMAD AEDEY
NRIC No	SXXXX023E

Date Of Birth	21/09/1996
Occupation	Outdoor
Date Of Driving Pass	18/05/2018
Driving experience	3 YEARS AND 6 MONTHS
Gender	Male
Mobile Number	(Phone) +65-97886103
Alt. Phone Number	-
Email Address	JEREMYC_QUEK@CERTISGROUP.COM
Address	BLK 141 PASIR RIS ST 11 #06-161
Address complement	-
Postcode	-
Is the driver the policyholder?	No
If No, Relationship of the Driver with the Insured	Employee
Does Driver Own Other Vehicles?	No
Vehicle Registration Number of Other Vehicle Owned by Driver	-
Insurance Company of Other Vehicle Owned by Driver	-

#### GENERAL INFORMATION OF THE ACCIDENT

Type of Accident	Side Swipe
Weather Conditions	Clear
Road Surface	Dry

#### OTHER INFORMATION

Was any foreign vehicle involved in the accident?	No
Number of vehicles involved in the accident	1
Was anybody injured in the Accident?	No
Was any injured conveyed to hospital by ambulance?	-
Was any other vehicle or property damaged?	No
Number of Passengers (Including Driver)	1
Has the driver been approached by unknown person(s) soliciting/offering accident claims assistance?	No

#### DETAILS OF POLICE ACTION

Was the accident reported to the police?	Yes
Police Station Name	Pasir Ris Neighbourhood Police Centre
Police Station Phone No	(Phone) +65-18005852999
Alt. Police Station Phone No	(Fax) +65-65855261
Police Station Address	1 Pasir Ris Drive 4 #01-01 Singapore 519457
Was notice of intended Prosecution given?	No
If yes, against whom?	-

#### CIRCUMSTANCES OF ACCIDENT

REFER TO POLICE REPORT.

#### ATTACHMENT(S)

Are accident photos available for attachment?	Yes
Was there any video captured by Car Camera?	No
Was there any audio recorded?	No

## SKETCH PLAN

### SKETCH PLAN

#### IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorized Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Traffic Police Department for investigation.
6. This report will be forwarded by the insurers to the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for preserving and that copies of this report will for a fee be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

#### B. Consent under the Personal Data Protection Act (PDPA)

I understand, acknowledge, agree and consent that:

- (a) My Insurer, my workshop and the General Insurance Association of Singapore ("GIA") may/are permitted to collect, use, disclose and/or process my personal data/personal information set out in this [Form] and any other personal information provided by me or possessed by my insurer (collectively the "Personal Information") and disclose and transfer such Personal Information to all insurer(s) who have insured vehicle(s) involved in this accident (all insurer(s) who have insured vehicle(s) involved in this accident shall be collectively referred to as the "Insurers"), the Insurers' lawyers/law firms, the Monetary Authority of Singapore and any relevant government agency/authority (such as the police), for the purpose(s) of:
  - (i) processing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigations relating to the claims;
  - (ii) investigating the accident and/or my claims;
  - (iii) carrying out and/or dealing with my instructions or responding to any enquiries by me;
  - (iv) administering my claims (including the mailing of correspondence, statements, invoices, reports or notices to me, which could involve disclosure of certain personal data about me to bring about delivery of the same as well as on the external cover of envelopes/mail packages), and/or
  - (v) complying with applicable law in administering, processing, handling and/or dealing with my claims.
 (collectively the "Purposes")
- (b) all insurer(s) who have insured vehicle(s) involved in this accident and the Insurers' lawyers/law firms, may/are permitted to collect, use, disclose and/or process my Personal Information for one or more of the above Purposes; and
- (c) my Personal Information may/can be disclosed by any of the Insurers and/or GIA to their third party service providers or agents (including their lawyers/law firms), which may be sited outside of Singapore, for one or more of the above Purposes.

Policyholder's Signature / Date & Time

Driver's Signature (if driver is not the policyholder) / Date & Time

Witnessed by Reporting Centre Personnel

#### Sketch Plan

Page 4

Describe Circumstance of the Accident



Refer to attached police report T/20211116/2000.

Declaration

I/We declare the foregoing particulars are true in every respect.

  
Policyholder's Sig / Date / Date & Time

  
Driver's Signature (if driver is not the policyholder) / Date  
& Time

  
Witnessed by Reporting Centre Personnel



SINGAPORE  
POLICE FORCE



T/20211116/2000

1 of 3

Report No. T/20211116/2000

Police Station Of Origin:  
Pasir Ris N.P.C  
1 Pasir Ris Drive 4 #01-01 SINGAPORE  
519457  
Tel No: 1800-5852899

REPORT OF A TRAFFIC ACCIDENT

Date/Time Report Made:  
16/11/2021 00:27

Vide Report No.:

Station Diary No.:  
6

Informant's Particulars

Name of Informant: MOHAMAD ZULFADLY BIN MOHAMAD AEDEY			Address: APT BLK 141 PASIR RIS STREET 11 #08-161 SINGAPORE 510141		
ID Type / ID No.: NRIC NO / S9333023E			Contact No.: Home/Office: Mobile: 97885103		
Nationality: SINGAPORE CITIZEN			Email:		
Sex: Male	Age: 25	Date of Birth: 21/09/1996	Type of Informant: Driver		
Race: Malay			Language:		Institution / School Name:
Occupation: CERTIS CISCO			Driving Licence Information: Class: 2B,2A,2,3,4 Date of Expiry:		

General information of the Accident

Type of Accident:	Non-Injury Others	Drink Drive: No	Date/Time of Accident: 15/11/2021 21:30	Type of Location:
Location: BEDOK SOUTH AVENUE 1				
Weather: Clear		Road Surface: Dry	Road Speed Limit:	
Traffic Flow:		Traffic Control:	Traffic Volume:	
Type of Collision: self skid			Anyone conveyed by ambulance: No	

Details of Vehicle Involved

Vehicle No.	Type	Make	Model	Color	Condition	No of Passenger
FBS4159B	Motorcycle	HONDA	CB400X	White	Slightly Damaged	0





SINGAPORE  
POLICE FORCE

Police Station Of Origin:  
Pasir Ris N.P.C  
1 Pasir Ris Drive 4 #01-01 SINGAPORE  
519457  
Tel No: 1800-5852999



T/20211116/2000

Report No. T/20211116/2000

CONTINUATION OF REPORT

Brief Details.

On the 16/11/2021 at 2130hrs, I was travelling along Badok south avenue 1 just after exiting my base I had self-skidded on the company's motorcycle. No injuries I had informed my supervisor and was advised to lodge this police report for their record. The damages on the motorcycle are the windshield was broken, clutch issue, crash bar side and rear, the left blinker, slight scratches on the fairing.

**SINGAPORE  
POLICE FORCE**

Police Station Of Origin  
Pasir Ris N.P.C  
1 Pasir Ris Drive 4 #01-01 SINGAPORE  
519457  
Tel No: 1800-5552999


Barcode: 1202111182800

Page No: 1202111182800

CONTINUATION OF REPORT

**Sketch Plan**  
Informant is not able to provide sketch plan

**IMPORTANT:** Please attach a copy of your vehicle's Insurance Certificate to this report. If you don't have the certificate with you now, please fax a copy to 65474885 stating the report number as reference.

Signature of Officer Recording The Report: G/ Sgt 2 MUHAMMAD FAIZ BIN MUHAMMAD FAIZAL	Signature Of Informant: 
Signature Of Interpreter: Not applicable	Date/Time: 16/11/2021 00:27
Officer In Charge Of Case: TP / CIA / SI TAN JEOK LENG Contact No.: 65476151	Classification Of Case:
Authentication Stamp NP168	



**BAN HOCK HIN**  
Co., Pte Ltd

Co. Reg. No: 197000268K  
MOTORCYCLE ACCESSORIES | SERVICE CENTRE  
MODIFICATIONS | SPRAY PAINTING AND BODY WORK | METAL  
WORKS | LEASING & RENTALS | FLEET SALES | INSURANCE SALES

**\*39514\***

Customer :

MS FIRST CAPITAL INSURANCE LTD  
36 ROBINSON ROAD  
#16-01 CITY HOUSE  
SINGAPORE 068877

ATTN: MOTOR CLAIMS DEPT

TEL :  
FAX :

VEHICLE NO. : FBS4159B  
MAKE/MODEL : HON - HONDA CB400X

*thuan@chhauto.com*  
*24/11/21 1200*  
*PIP ~~for~~ paint photo*  
*after*  
*Excess 1500*  
*4 days wp*

## QUOTATION

NO. : 39514 - Rev. 1

DATE : 19/11/2021  
JOB NO. : DLJB40277659  
FROM : SHIWEI

MILEAGE: 13189

(Page 1 of 4)

S/N	Description	Action	Qty	Unit Price	Amount
1	BAR HANDLE P/N: 71324 Reason: CRACKED / BENT / BROKEN / DAMAGED- (REPORTED BY MECHANIC) Stock Availability (Days): 1	REPLACE	1.00	\$70.50	✓ \$70.50 <i>BT</i>
2	BOX SIDE (MOTOMALL) ALUMINIUM 38L (MATT BLACK) P/N: 69470 Reason: CRACKED / BENT / BROKEN / DAMAGED- (REPORTED BY MECHANIC) Stock Availability (Days): 1	REPLACE	1.00	\$529.50	✓ \$529.50 <i>Scr</i>
3	BRACKET FOOTREST REAR LH P/N: 49262 Reason: CRACKED / BENT / BROKEN / DAMAGED- (REPORTED BY MECHANIC) Stock Availability (Days): 1	REPLACE	1.00	\$60.00	✓ \$60.00 <i>Shoe W?</i>
4	BRACKET IU METER (UNIVERSAL) S/STEEL P/N: 31712 Reason: CRACKED / BENT / BROKEN / DAMAGED- (REPORTED BY MECHANIC) Stock Availability (Days): 1	REPLACE	1.00	\$24.00	✓ \$24.00 <i>BT</i>
5	BRACKET LED XT12 PEDESTAL MOUNT WITH KIT P/N: 62717 Reason: CRACKED / BENT / BROKEN / DAMAGED- (REPORTED BY MECHANIC) Stock Availability (Days): 1	REPLACE	1.00	\$46.50	✗ \$46.50 <i>Sub</i>
6	BRACKET SUPPORT CRASH BAR FRONT LH (CISCO) P/N: 70242 Reason: CRACKED / BENT / BROKEN / DAMAGED- (REPORTED BY MECHANIC) Stock Availability (Days): 1	REPLACE	1.00	\$82.50	✓ \$82.50 <i>Scr</i>
7	BRACKET UPPER COWLING FRONT P/N: 71341 Reason: CRACKED / BENT / BROKEN / DAMAGED- (REPORTED BY MECHANIC) Stock Availability (Days): 1	REPLACE	1.00	\$47.00	✓ \$47.00 <i>7</i>

*bizSAFE<sub>3</sub>*





S/N	Description	Action	Qty	Unit Price	Amount
8	CAMERA REAR IP68 P/N: 71342 Reason: CRACKED / BENT / BROKEN / DAMAGED- (REPORTED BY MECHANIC) Stock Availability (Days): 60	REPLACE	1.00	\$618.00	\$618.00
9	COVER A FRONT UPPER P/N: 71316 Reason: CRACKED / BENT / BROKEN / DAMAGED- (REPORTED BY MECHANIC) Stock Availability (Days): 60	REPLACE	1.00	\$53.50	\$53.50
10	COVER B FRONT UPPER P/N: 71305 Reason: CRACKED / BENT / BROKEN / DAMAGED- (REPORTED BY MECHANIC) Stock Availability (Days): 60	REPLACE	1.00	\$53.50	\$53.50
11	COWLING FRONT LH Reason: CRACKED / BENT / BROKEN / DAMAGED- (REPORTED BY MECHANIC) Stock Availability (Days): 1	REPLACE	1.00	\$363.70	\$363.70
12	CRASH BAR OUTER LH FRONT WITH SIREN MOUNT (CISCO) P/N: 70239 Reason: CRACKED / BENT / BROKEN / DAMAGED- (REPORTED BY MECHANIC) Stock Availability (Days): 1	REPLACE	1.00	\$288.50	\$288.50
13	CRASH BAR REAR LH (CISCO) P/N: 70238 Reason: CRACKED / BENT / BROKEN / DAMAGED- (REPORTED BY MECHANIC) Stock Availability (Days): 1	REPLACE	1.00	\$155.00	\$155.00
14	LABOUR P/N: 06766 - LABOUR QUOTED FOR DISMANTLING AND INSTALLATION OF PARTS. Stock Availability (Days): 1	Supply/Install	14.00	\$45.00	\$630.00
15	LAMP SIGNAL FRONT LH Reason: CRACKED / BENT / BROKEN / DAMAGED- (REPORTED BY MECHANIC) Stock Availability (Days): 1	REPLACE	1.00	\$103.10	\$103.10
16	LIGHT LED (JL) 12 LED RED / BLUE WITH CLEAR LENS P/N: 62716 Reason: CRACKED / BENT / BROKEN / DAMAGED- (REPORTED BY MECHANIC) Stock Availability (Days): 1	REPLACE	1.00	\$297.00	\$297.00
17	METER ASSY Reason: CRACKED / BENT / BROKEN / DAMAGED- (REPORTED BY MECHANIC) Stock Availability (Days): 60	REPLACE	1.00	\$424.20	\$424.20
18	METER IU (12V) NEW MODEL P/N: 34351 Reason: CRACKED / BENT / BROKEN / DAMAGED- (REPORTED BY MECHANIC) Stock Availability (Days): 1	REPLACE	1.00	\$206.00	\$206.00
19	MIRROR LH P/N: 71300 Reason: CRACKED / BENT / BROKEN / DAMAGED- (REPORTED BY MECHANIC) Stock Availability (Days): 1	REPLACE	1.00	\$86.00	\$86.00

bizSAFE<sub>3</sub>

S/N	Description	Action	Qty	Unit Price	Amount
20	PANEL L. INNER P/N: 71286 Reason: CRACKED / BENT / BROKEN / DAMAGED- (REPORTED BY MECHANIC) Stock Availability (Days): 1	REPLACE	1.00	\$20.50	\$20.50
21	PANEL METER P/N: 71304 Reason: CRACKED / BENT / BROKEN / DAMAGED- (REPORTED BY MECHANIC) Stock Availability (Days): 1	REPLACE	1.00	\$62.50	\$62.50
22	SCREW PAN Reason: CRACKED / BENT / BROKEN / DAMAGED- (REPORTED BY MECHANIC) Stock Availability (Days): 60	REPLACE	2.00	\$4.60	\$9.20
23	SPRAY PAINT ON COWLING FRONT LH Reason: CRACKED / BENT / BROKEN / DAMAGED- (REPORTED BY MECHANIC) Stock Availability (Days): 1	Spray	1.00	\$145.00	\$145.00
24	STAY COWLING FRONT UPPER P/N: 71340 Reason: CRACKED / BENT / BROKEN / DAMAGED- (REPORTED BY MECHANIC) Stock Availability (Days): 1	REPLACE	1.00	\$117.50	\$117.50
25	STAY SCREEN LH P/N: 54749 Reason: CRACKED / BENT / BROKEN / DAMAGED- (REPORTED BY MECHANIC) Stock Availability (Days): 1	REPLACE	1.00	\$41.50	\$41.50
26	STAY SCREEN RH P/N: 54744 Reason: CRACKED / BENT / BROKEN / DAMAGED- (REPORTED BY MECHANIC) Stock Availability (Days): 1	REPLACE	1.00	\$41.50	\$41.50
27	STICKER (CERTIS CISCO) WINDSHIELD P/N: 67401 Reason: CRACKED / BENT / BROKEN / DAMAGED- (REPORTED BY MECHANIC) Stock Availability (Days): 1	REPLACE	1.00	\$36.50	\$36.50
28	STICKER (CISCO) COWLING FRONT LH P/N: 69684 Reason: CRACKED / BENT / BROKEN / DAMAGED- (REPORTED BY MECHANIC) Stock Availability (Days): 1	REPLACE	1.00	\$19.50	\$19.50
29	STICKER (CISCO) COWLING SIDE LH P/N: 69681 Reason: CRACKED / BENT / BROKEN / DAMAGED- (REPORTED BY MECHANIC) Stock Availability (Days): 1	REPLACE	1.00	\$32.00	\$32.00
30	STICKER (LTA) TRAFFIC MARSHALL SIDE BOX LH P/N: 69955 Reason: CRACKED / BENT / BROKEN / DAMAGED- (REPORTED BY MECHANIC) Stock Availability (Days): 1	REPLACE	1.00	\$292.50	\$292.50
31	STICKER NUMBER PLATE FRONT (BLACK) STRAIGHT REPLACE P/N: 32921 Reason: CRACKED / BENT / BROKEN / DAMAGED- (REPORTED BY MECHANIC) Stock Availability (Days): 1		1.00	\$20.00	\$20.00

bizSAFE<sub>3</sub>



S/N	Description	Action	Qty	Unit Price	Amount
32	WINDSHIELD - CLEAR (PUIG) P/N: 69455 Reason: CRACKED / BENT / BROKEN / DAMAGED- (REPORTED BY MECHANIC) Stock Availability (Days): 30	REPLACE	1.00	\$222.00 ✓ C19	\$222.00
33	TRANSPORT CHARGES (MOTORCYCLE) CLASS 2 P/N: 45836		2.00	\$55.00 ✓ nec	\$110.00

SUB TOTAL	\$5,308.70
GST @ 7 %	\$371.61
<b>GRAND TOTAL (SGD)</b>	<b>\$5,680.31</b>

**Remarks:**

Validity: 30 days

For &amp; on Behalf of

**BAN HOCK HIN CO PTE LTD****RAYMOND**

Acknowledge &amp; Accepted By

This quotation is sent via email / LAN-Fax and will bear a computer generated signature.

LKK Auto Consultants hence notify  
the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and  
is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

**\$4793.70****bizSAFE<sub>3</sub>**

Address: No. 6, Defu lane 4, Singapore 539410 | Telephone: +65 6281 6520 | Web: www.bhh.com.sg

Fax: (Main) +65 6281 2830, (Spare Parts) +65 6285 7530, (Insurance/Project) +65 6284 2969, (Accounts) +65 6281 6759

CERT NO.: 2002-1-0363  
ISO 9001:2015





**BAN HOCK HIN**  
Co., Pte Ltd

Co. Reg. No: 197000288K  
MOTORCYCLE ACCESSORIES / SERVICE CENTRE  
MODIFICATIONS / SPRAY PAINTING AND BODY WORK / METAL  
WORKS / LEASING & RENTALS / FLEET SALES / INSURANCE SALES

**\*39514\***

**QUOTATION**

NO. : 39514 - Rev. 1

Customer :

MS FIRST CAPITAL INSURANCE LTD  
36 ROBINSON ROAD  
#16-01 CITY HOUSE  
SINGAPORE 068877

ATTN: MOTOR CLAIMS DEPT

TEL :  
FAX :

VEHICLE NO. : FBS4159B  
MAKE/MODEL : HON - HONDA CB400X

thruvan @ chhauto. / ou  
24/11/21 1200  
PIP ~~for~~ paint photo  
after  
Excess 1500  
4 days w/p

DATE : 19/11/2021  
JOB NO. : DLJB40277659  
FROM : SHIWEI

MILEAGE: 13189

(Page 1 of 4)

S/N	Description	Action	Qty	Unit Price	Amount
1	BAR HANDLE P/N: 71324 Reason: CRACKED / BENT / BROKEN / DAMAGED- (REPORTED BY MECHANIC) Stock Availability (Days): 1	REPLACE	1.00	\$70.50	\$70.50
2	BOX SIDE (MOTOMALL) ALUMINIUM 38L (MATT BLACK) P/N: 69470 Reason: CRACKED / BENT / BROKEN / DAMAGED- (REPORTED BY MECHANIC) Stock Availability (Days): 1	REPLACE	1.00	\$529.50	\$529.50
3	BRACKET FOOTREST REAR LH P/N: 49262 Reason: CRACKED / BENT / BROKEN / DAMAGED- (REPORTED BY MECHANIC) Stock Availability (Days): 1	REPLACE	1.00	\$60.00	\$60.00
4	BRACKET IU METER (UNIVERSAL) S/STEEL P/N: 31712 Reason: CRACKED / BENT / BROKEN / DAMAGED- (REPORTED BY MECHANIC) Stock Availability (Days): 1	REPLACE	1.00	\$24.00	\$24.00
5	BRACKET LED XT12 PEDESTAL MOUNT WITH KIT P/N: 62717 Reason: CRACKED / BENT / BROKEN / DAMAGED- (REPORTED BY MECHANIC) Stock Availability (Days): 1	REPLACE	1.00	\$46.50	\$46.50
6	BRACKET SUPPORT CRASH BAR FRONT LH (CISCO) P/N: 70242 Reason: CRACKED / BENT / BROKEN / DAMAGED- (REPORTED BY MECHANIC) Stock Availability (Days): 1	REPLACE	1.00	\$82.50	\$82.50
7	BRACKET UPPER COWLING FRONT P/N: 71341 Reason: CRACKED / BENT / BROKEN / DAMAGED- (REPORTED BY MECHANIC) Stock Availability (Days): 1	REPLACE	1.00	\$47.00	\$47.00

bigSAFE<sub>3</sub>



S/N	Description	Action	Qty	Unit Price	Amount
8	CAMERA REAR IP68 P/N: 71342 Reason: CRACKED / BENT / BROKEN / DAMAGED- (REPORTED BY MECHANIC) Stock Availability (Days): 60	REPLACE	1.00	\$618.00	\$618.00
9	COVER A FRONT UPPER P/N: 71316 Reason: CRACKED / BENT / BROKEN / DAMAGED- (REPORTED BY MECHANIC) Stock Availability (Days): 60	REPLACE	1.00	\$53.50	\$53.50
10	COVER B FRONT UPPER P/N: 71305 Reason: CRACKED / BENT / BROKEN / DAMAGED- (REPORTED BY MECHANIC) Stock Availability (Days): 60	REPLACE	1.00	\$53.50	\$53.50
11	COWLING FRONT LH Reason: CRACKED / BENT / BROKEN / DAMAGED- (REPORTED BY MECHANIC) Stock Availability (Days): 1	REPLACE	1.00	\$363.70	\$363.70
12	CRASH BAR OUTER LH FRONT WITH SIREN MOUNT (CISCO) P/N: 70239 Reason: CRACKED / BENT / BROKEN / DAMAGED- (REPORTED BY MECHANIC) Stock Availability (Days): 1	REPLACE	1.00	\$288.50	\$288.50
13	CRASH BAR REAR LH (CISCO) P/N: 70238 Reason: CRACKED / BENT / BROKEN / DAMAGED- (REPORTED BY MECHANIC) Stock Availability (Days): 1	REPLACE	1.00	\$155.00	\$155.00
14	LABOUR P/N: 06766 - LABOUR QUOTED FOR DISMANTLING AND INSTALLATION OF PARTS. Stock Availability (Days): 1	Supply/Install	14.00	\$45.00	\$630.00
15	LAMP SIGNAL FRONT LH Reason: CRACKED / BENT / BROKEN / DAMAGED- (REPORTED BY MECHANIC) Stock Availability (Days): 1	REPLACE	1.00	\$103.10	\$103.10
16	LIGHT LED (JL) 12 LED RED / BLUE WITH CLEAR LENS P/N: 62716 Reason: CRACKED / BENT / BROKEN / DAMAGED- (REPORTED BY MECHANIC) Stock Availability (Days): 1	REPLACE	1.00	\$297.00	\$297.00
17	METER ASSY Reason: CRACKED / BENT / BROKEN / DAMAGED- (REPORTED BY MECHANIC) Stock Availability (Days): 60	REPLACE	1.00	\$424.20	\$424.20
18	METER IU (12V) NEW MODEL P/N: 34351 Reason: CRACKED / BENT / BROKEN / DAMAGED- (REPORTED BY MECHANIC) Stock Availability (Days): 1	REPLACE	1.00	\$206.00	\$206.00
19	MIRROR LH P/N: 71300 Reason: CRACKED / BENT / BROKEN / DAMAGED- (REPORTED BY MECHANIC) Stock Availability (Days): 1	REPLACE	1.00	\$86.00	\$86.00

bizSAFE





S/N	Description	Action	Qty	Unit Price	Amount
20	PANEL L. INNER P/N: 71286 Reason: CRACKED / BENT / BROKEN / DAMAGED- (REPORTED BY MECHANIC) Stock Availability (Days): 1	REPLACE	1.00	\$20.50	\$20.50
21	PANEL METER P/N: 71304 Reason: CRACKED / BENT / BROKEN / DAMAGED- (REPORTED BY MECHANIC) Stock Availability (Days): 1	REPLACE	1.00	\$62.50	\$62.50
22	SCREW PAN Reason: CRACKED / BENT / BROKEN / DAMAGED- (REPORTED BY MECHANIC) Stock Availability (Days): 60	REPLACE	2.00	\$4.60	\$9.20
23	SPRAY PAINT ON COWLING FRONT LH Reason: CRACKED / BENT / BROKEN / DAMAGED- (REPORTED BY MECHANIC) Stock Availability (Days): 1	Spray	1.00	\$145.00	\$145.00
24	STAY COWLING FRONT UPPER P/N: 71340 Reason: CRACKED / BENT / BROKEN / DAMAGED- (REPORTED BY MECHANIC) Stock Availability (Days): 1	REPLACE	1.00	\$117.50	\$117.50
25	STAY SCREEN LH P/N: 54749 Reason: CRACKED / BENT / BROKEN / DAMAGED- (REPORTED BY MECHANIC) Stock Availability (Days): 1	REPLACE	1.00	\$41.50	\$41.50
26	STAY SCREEN RH P/N: 54744 Reason: CRACKED / BENT / BROKEN / DAMAGED- (REPORTED BY MECHANIC) Stock Availability (Days): 1	REPLACE	1.00	\$41.50	\$41.50
27	STICKER (CERTIS CISCO) WINDSHIELD P/N: 67401 Reason: CRACKED / BENT / BROKEN / DAMAGED- (REPORTED BY MECHANIC) Stock Availability (Days): 1	REPLACE	1.00	\$36.50	\$36.50
28	STICKER (CISCO) COWLING FRONT LH P/N: 69684 Reason: CRACKED / BENT / BROKEN / DAMAGED- (REPORTED BY MECHANIC) Stock Availability (Days): 1	REPLACE	1.00	\$19.50	\$19.50
29	STICKER (CISCO) COWLING SIDE LH P/N: 69681 Reason: CRACKED / BENT / BROKEN / DAMAGED- (REPORTED BY MECHANIC) Stock Availability (Days): 1	REPLACE	1.00	\$32.00	\$32.00
30	STICKER (LTA) TRAFFIC MARSHALL SIDE BOX LH P/N: 69955 Reason: CRACKED / BENT / BROKEN / DAMAGED- (REPORTED BY MECHANIC) Stock Availability (Days): 1	REPLACE	1.00	\$292.50	\$292.50
31	STICKER NUMBER PLATE FRONT (BLACK) STRAIGHT P/N: 32921 Reason: CRACKED / BENT / BROKEN / DAMAGED- (REPORTED BY MECHANIC) Stock Availability (Days): 1	REPLACE	1.00	\$20.00	\$20.00

bizSAFE<sub>3</sub>



S/N	Description	Action	Qty	Unit Price	Amount
32	WINDSHIELD - CLEAR (PUIG) P/N: 69455 Reason: CRACKED / BENT / BROKEN / DAMAGED- (REPORTED BY MECHANIC) Stock Availability (Days): 30	REPLACE	1.00	\$222.00	\$222.00
33	TRANSPORT CHARGES (MOTORCYCLE) CLASS 2 P/N: 45836		2.00	\$55.00	\$110.00

SUB TOTAL \$5,308.70

GST @ 7 % \$371.61

GRAND TOTAL (SGD) \$5,680.31

5358.70

## Remarks:

Validity: 30 days

For &amp; on Behalf of

BAN HOCK HIN CO PTE LTD



RAYMOND

Acknowledge &amp; Accepted By

This quotation is sent via email / LAN-Fax and will bear a computer generated signature.

bizSAFE<sub>3</sub>



**BAN HOCK HIN**  
Co., Pte Ltd

Co.Reg.No: 197000288K

MOTORCYCLE ACCESSORIES | SERVICE CENTRE  
MODIFICATION | SPRAY PAINTING AND BODY WORK | METAL  
WORKS | LEASING & RENTALS | FLEET SALES | INSURANCE SALES

## QUOTATION

Customer :

MS FIRST CAPITAL INSURANCE LTD  
36 ROBINSON ROAD  
#16-01 CITY HOUSE  
SINGAPORE 068877

NO. : 39857

Supplementary 1 To QTN: 39522

DATE : 11/01/2022  
CLAIM NO. : 11820  
POLICY NO. : D-2109290MFCE133  
FROM : RAYMOND

VEHICLE NO. : FBS4159B  
MAKE/MODEL : HON / CB400X

S/N	Description	Action	Qty	Unit Price	Amount
1	M10 WHEELWALKER WALKING MEASURE	AOD Replace	1.00	\$50.00	Payed 50.00
SUB TOTAL					\$50.00
GST @ 7 %					\$3.50
GRAND TOTAL (SGD)					\$53.50

50% deposit required before ordering of parts.

Validity: 30 days

For & on Behalf of  
**BAN HOCK HIN CO PTE LTD**

Acknowledge & Accepted By



RAYMOND

This quotation is sent via email / LAN-Fax and will bear a computer generated signature.

\*39857 \*



Address: No.6, Defu Lane 4, Singapore 539410 | Telephone: +65 6281 6520 | Web: www.bhh.com.sg  
Fax: (Main) + 65 6281 2830, (Spare Parts) + 65 6285 7530, (Insurance/Project) +65 6284 2969, (Accounts) + 65 6281 6759

CERT NO.: 2002-1-0383  
ISO 9001 : 2015