

MOTOR SURVEY ASSIGNMENT

Date 22/11/2021 **Our Ref No.** D21003218MFCE
Accident Date 15-11-2021 **Claim Type** Own Damage
Insured Vehicle FBS4159B **Third Party Vehicle**

Survey Location BAN HOCK HIN CO PTE LTD
NO. 6 DEFU LANE 4 (S) 539410 **Contact Person** RAYMOND
Contact No. 62816520 **Fax No.** 62812830

Survey Type Authorise if in order

Appointed Surveyor LKK AUTO CONSULTANTS PTE LTD
Contact Person **Fax No.** 68416315
Contact Number 62563561

EXCESS APPLICATION FOR OWN DAMAGE CLAIM
ADDITIONAL \$500.00 FOR INSURED VEHICLE INSTALLED WITH CNG TANKER

Basic	Y/I Driver	Total
\$0	\$0	\$0

Encl. Accident Reports & est

Cc : Workshop BAN HOCK HIN CO PTE LTD
Officer Incharge ERICWOO

Attention RAYMOND

IMPORTANT NOTE

Kindly submit the survey report by **email only** to surveyor@msfirstcapital.com.sg within 14 days for survey assignment and 7 days for re-inspection.

This is a computer generated letter, no signature required.