

ComfortDelGro Engineering Pte Ltd 59 Loyang Drive Singapore 508969

Our Ref

Via Fax

Date

Your Insured

Time of Fax

Date of Acc

Attn: Motor Claims Department

Dear Sirs

SURVEY OF CLIENT'S DAMAGED VEHICLE REG NO. SH

Our client has engaged us to repair the above vehicle and submit claims against the other party/partiesinvolved in the accident.

In accordance to the motor claims framework, we hereby request your presence at 59 Loyang Drive, Singapore 508969 to survey our client's damaged vehicle.

Enclosed, please find:

- Our initial estimate of repairs of the damaged vehicle; i)
- ii) Accident report made by our client.

I would appreciate it if you could call us to arrange for the survey of the vehicle:

Tel: 6214 8355 or HP: 9824 0811 ◆ Lim Kwok Eng ♦ Jumani Bin Masudin Tel: 6214 8315 or HP: 9635 5305 ◆ Lim Tien Siong

Tel: 6214 8398 or HP: 9635 8546

◆ Chiang Liat Choon

Tel: 6214 8314 or HP: 9296 6006

jumanibm@cdge.com.sg Fax no. 6546 8156

If we do not hear from you within the next 48 hours, we shall deem that you have waived your rights to survey our client's vehicle and we shall proceed to engage independent surveyor without further reference to you. We henceforth reserve our rights to claim for Loss of Use and Loss of Rental during any delayed period of this survey arrangement.

This is an initial estimate based on a visual inspection of the above vehicle. The final repair quantum will be prepared after the vehicle is surveyed by a Motor Surveyor appointed by the Insurance company.

Thank you.

Yours faithfully

For Vice President Tax Accident Repair



ComfortDelGro Engineering Pte Ltd

205 Braddell Road Singapore 579701 Mainline + 65 6383 6280 Facsimile + 65 6280 9755

Workshops 205 Braddell Road Singapore 579701 59 Loyang Drive Singapore 508969 383 Sin Ming Dxive Singapore 575717

Date/Time: 22.11.2021 14:18

Page: 1

ARC Repair TP(CLSO)1

JOB CARD Sales Order: 4143089

JC NO305495205

am: OMER

IS

(R)

COMFORT TRANSPORTATION PTE LTD

7010045

OMER NO 383 SIN MING DRIVE

Singapore SINGAPORE 575717

65508755

(O)

DUNT CARD NO.

	REGN NO.: SHC8595L	MILEAGE
	MAKE: HYUNDAI	FUEL EF
		DATE/TIME IN 11.2021 09:55
	YR OF MANU. 17.12.2015	TARGET DATE
	CHASSIS CODE KMHLB41UMGU082967	COMPLETION DATE/TIME:

JOB DESCRIPTION


:cident Date: 20.11.2021 TURE: 3P.20.11.2021

Service Advisor

urned to Service Reception upon collection

LABOR CODE

DESCRIPTION



Date

KED & PASSED OUT BY:	
SERVICE ADVISOR	CUSTOMER'S SIGNATURE
edgement Slip	Exit Pass
o.: SHC8595L JU AIG	Vehicle No.: SHC8595L
•	

Name of Service Advisor

To be kept by Security Guard

Signature/Date

COMFORTDELGRO ENGINEERING PTE LTD

Date: 22.11.2021

REPAIR ESTIMATE

Time: 14:52:41 Page: 1

COMPANY: THIRD PARTY'S CLAIMS (CAS) JOB NO **CUSTOMER: 7010045** REGN NO MILEAGE ADDRESS: COMFORT TRANSPORTATION PTE LTD

305495205 : SHC8595L 0000000000

383 SIN MING DRIVE

MAKE HYUNDAI

SINGAPORE SINGAPORE 575717

MODEL : I-40 DATE OF REGN

65508755

: 17.12.2015 : 22.11.2021 09:55 DATE/TIME IN

ACCIDENT DATE

20.11.2021

JOB / PARTS DESCRIPTION

OTY IND UNIT-PRICE DISC% AMOUNT

PART REQUISITION

0001 04-01-0103-0579-G COVER ASSY-RR BUMPER# 1 553.00 20.00 442.40

0002 04-01-0103-0738-G COVER-RR BUMPER LWR# 1 228.00 20.00 182.40

0003 04-01-0103-0739-G ABSORBER-RR BUMPER ENERGY 1 119.50 20.00 95.60

0004 04-01-0103-0740-G BEAM-RR BUMPER# 1 428.40 20.00 342.72

0005 04-01-0101-0111-G BUMPER COVER CLIP REAR 10 L 22.00 20.00 17.60

0006 04-01-0103-1150-A PROTECTOR MAT 1 N 50.00 2.00- 50.00

0007 09-01-9999-0068-A REVERSE SENSOR ASSY* 1 N 135.70 0.20 135.70

SUB-TOTAL : 1,266.42

JOB NATURE

0000 PB PANEL BEATING 300.00

0001 SP SPRAYPAINT CHARGE 300.00

0002 L REMOVE/REFIX REVERSE SENSOR 80.00

SUB-TOTAL : 680.00

COMFORTDELGRO ENGINEERING PTE LTD

REPAIR ESTIMATE

Date: 22.11.2021 Time: 14:52:41

Page: 2

COMPANY: THIRD PARTY'S CLAIMS (CAS)

CUSTOMER: 7010045

ADDRESS: COMFORT TRANSPORTATION PTE LTD

383 SIN MING DRIVE

SINGAPORE SINGAPORE 575717

65508755

JOB NO REGN NO MILEAGE 305495205 : SHC8595L : 0000000000

MAKE

: HYUNDAI

MODEL

: I-40

DATE OF REGN : 17.12.2015 DATE/TIME IN : 22.11.2021

: 22.11.2021 09:5

ACCIDENT DATE : 20.11.2021

JOB / PARTS DESCRIPTION

QTY IND UNIT-PRICE DISC% AMOUNT

TOTAL : 1,946.42

AUTHORISED: YES/NO

MVA NAME & SIGNATURE

SURVEYOR NAME & SIGNATURE

DATE:

DATE:

INSURER ENQUIRY

Find insurer

Vehicle reg. no.

SLL8425A

Date of Accident

20/11/2021

Reset

% RESULT & RECEIPT

TP Insurer Enquiry Insurance AIG Asia Pacific Insurance Pte.... Period of Insurance 13/03/2021 - 12/03/2022 Requested By Janet Lim Siang Gek (COMFOR... Requested Date 22/11/2021 11:05

Payment details

Request Amount: **\$\$1.87** GST Amount: **\$\$0.13**

Total Amount Due (GST Inclusive): \$\$2

General Insurance Association

Records Management Centre GST Registration No: **M400017735**