

COMFORTDELGRO ENGINEERING PTE LTD  
REPAIR ESTIMATE

WLG (Yuan)

Date: 22.11.2021  
Time: 14:52:41  
Page: 1

COMPANY : THIRD PARTY'S CLAIMS (CAS)  
CUSTOMER: 7010045  
ADDRESS : COMFORT TRANSPORTATION PTE LTD  
383 SIN MING DRIVE  
SINGAPORE SINGAPORE 575717  
65508755

JOB NO : 305495205  
REGN NO : SHC8595L  
MILEAGE : 0000000000  
MAKE : HYUNDAI  
MODEL : I-40  
DATE OF REGN : 17.12.2015  
DATE/TIME IN : 22.11.2021 09:55  
ACCIDENT DATE : 20.11.2021

JOB / PARTS DESCRIPTION

QTY IND UNIT-PRICE DISC% AMOUNT

PART REQUISITION

0001 04-01-0103-0579-G	COVER ASSY-RR BUMPER#	1	553.00	20.00	442.40	50% DISCOUNT	276.50
0002 04-01-0103-0738-G	COVER-RR BUMPER LWR#	1	228.00	20.00	182.40		
0003 04-01-0103-0739-G	ABSORBER-RR BUMPER ENERGY	1	119.50	20.00	95.60		
0004 04-01-0103-0740-G	BEAM-RR BUMPER#	1	428.40	20.00	342.72		
0005 04-01-0101-0111-G	BUMPER COVER CLIP REAR	10 L	22.00	20.00	17.60		
0006 04-01-0103-1150-A	PROTECTOR MAT	1 N	50.00	2.00-	50.00		
0007 09-01-9999-0068-A	REVERSE SENSOR ASSY*	1 N	135.70	0.20	135.70		
SUB-TOTAL :							1,266.42

JOB NATURE

0000 PB	PANEL BEATING
0001 SP	SPRAYPAINT CHARGE
0002 L	REMOVE/REFIX REVERSE SENSOR

300.00	280	
300.00	250	
80.00	30	560
	<del>250</del>	
		1178.56
SUB-TOTAL :		680.00
		11589.50

Tanphir 97495745  
WP 22/11/21 @ 3pm  
c/s Resurvey after repair  
Tanphir @ 11/11/21  
02 days

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer  
Signature:  
Date: