

WLG (48um)

COMFORTDELGRO ENGINEERING PTE LTD
REPAIR ESTIMATE

Date: 22.11.2021
Time: 14:52:41
Page: 1

COMPANY : THIRD PARTY'S CLAIMS (CAS)
CUSTOMER: 7010045
ADDRESS : COMFORT TRANSPORTATION PTE LTD
383 SIN MING DRIVE
SINGAPORE SINGAPORE 575717
65508755

JOB NO : 305495205
REGN NO : SHC8595L
MILEAGE : 0000000000
MAKE : HYUNDAI
MODEL : I-40
DATE OF REGN : 17.12.2015
DATE/TIME IN : 22.11.2021 09:55
ACCIDENT DATE : 20.11.2021

JOB / PARTS DESCRIPTION

QTY IND UNIT-PRICE DISC% AMOUNT

PART REQUISITION

0001 04-01-0103-0579-G	COVER ASSY-RR BUMPER#	1	553.00	20.00	442.40	di
0002 04-01-0103-0738-G	COVER-RR BUMPER LWR#	1	228.00	20.00	182.40	X
0003 04-01-0103-0739-G	ABSORBER-RR BUMPER ENERGY	1	119.50	20.00	95.60	?
0004 04-01-0103-0740-G	BEAM-RR BUMPER#	1	428.40	20.00	342.72	?
0005 04-01-0101-0111-G	BUMPER COVER CLIP REAR	10 L	22.00	20.00	17.60	nei
0006 04-01-0103-1150-A	PROTECTOR MAT	1 N	50.00	2.00	50.00	nei
0007 09-01-9999-0068-A	REVERSE SENSOR ASSY*	1 N	135.70	0.20	135.70	nei

SUB-TOTAL : 1,266.42

JOB NATURE

0000 PB	PANEL BEATING
0001 SP	SPRAYPAINT CHARGE
0002 L	REMOVE/REFIX REVERSE SENSOR

300.00 280
300.00 250
30 80.00 250

SUB-TOTAL : 680.00

Tanphie 97495745
'WB' 22/11/21 @ 3pm
1/3 Resurvey after repair
Tanphie @ Manta.com
2 days

LKK Auto Consultants hence notify
the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer
Signature:
Date:

COMFORTDELGRO ENGINEERING PTE LTD

REPAIR ESTIMATE

Date: 22.11.2021

Time: 14:52:41

Page: 2

COMPANY : THIRD PARTY'S CLAIMS (CAS)
CUSTOMER: 7010045
ADDRESS : COMFORT TRANSPORTATION PTE LTD
383 SIN MING DRIVE
SINGAPORE SINGAPORE 575717
65508755

JOB NO : 305495205
REGN NO : SHC8595L
MILEAGE : 0000000000
MAKE : HYUNDAI
MODEL : I-40
DATE OF REGN : 17.12.2015
DATE/TIME IN : 22.11.2021 09:5
ACCIDENT DATE : 20.11.2021

JOB / PARTS DESCRIPTION

QTY IND UNIT-PRICE DISC% AMOUNT

TOTAL : 1,946.42

AUTHORISED : YES / NO

MVA NAME & SIGNATURE
DATE :

SURVEYOR NAME & SIGNATURE
DATE :

Date/Time: 22.11.2021 14:18

Page : 1

am: ARC Repair TP(CLSO)1

JOB CARD Sales Order: 4143089

JC NO305495205

OMER

IS COMFORT TRANSPORTATION PTE LTD
OMER NO. 7010045
ESS 383 SIN MING DRIVE
Singapore SINGAPORE 575717
(R) 65508755 (O)
(P)

JUNT CARD NO.

REGN NO:

SHC8595L

MILEAGE

MAKE:

HYUNDAI

FUEL

E.....1/2.....F

MODEL

I-40

DATE/TIME IN
22.11.2021 09:55

YR OF MANU.

17.12.2015

TARGET DATE

CHASSIS CODE

KMHLB41UMGU082967

COMPLETION DATE/TIME:


JOB DESCRIPTION

Accident Date: 20.11.2021
ATURE: 3P.20.11.2021

NO

LABOR CODE

DESCRIPTION



KED & PASSED OUT BY:

SERVICE ADVISOR

CUSTOMER'S SIGNATURE

edgement Slip

Exit Pass

lo.: SHC8595L

JU AIG

Vehicle No.:

SHC8595L

Service Advisor

Signature/Date

Name of Service Advisor

Date

urned to Service Reception upon collection

To be kept by Security Guard

INSURER ENQUIRY

Find
insurer

Vehicle reg. no.

SLL8425A

Date of Accident

20/11/2021 

Reset

% RESULT & RECEIPT

TP Insurer Enquiry

Insurance **AIG Asia Pacific Insurance Pte....**
Period of Insurance **13/03/2021 - 12/03/2022**
Requested By **Janet Lim Siang Gek (COMFOR...**
Requested Date **22/11/2021 11:05**

Payment details

Request Amount: **S\$1.87**GST Amount: **S\$0.13**Total Amount Due (GST Inclusive): **S\$2**

General Insurance Association

Records Management Centre

GST Registration No: **M400017735**