

ASSIGNMENT

Filing No. _____

Estimated Cost _____

(OR) TYPE / INSURANCE POLICY NO. / EVALUATION

To Inspect Vehicle No. _____

at Workshop no. _____

City _____

Insured By _____

Policy No. _____

Claime No. 8699788432SG

Sum Insured _____ Excess _____ O/- _____

(Client's Recd.) _____

Make of Vehl _____

(Policy Condition)

I Certify That the veh has commenced its repair at the time of inspection.

Date of Market Value: _____

IDNC Accident Report Consistent? Yes or No

GIA / PR Sess Consistent? Yes or No

Esl. Repairs: 13 days Res.: Yes or No

Lum Sum % J Val.: Yes or No

GA / REV / REP. / 24 HRS

Date Person Contacted: _____ Vehicle IN/OUT

VEH No: SMF 2257C Yr Regd: 31/10/18
 Type: M. Cap / M. Cycle / Bus / Van / Lorry / Truck / Prime Mover /
Truck / Trailer or
 Make: KIA Cerato CB: 1591
 Colour: Blue A/C: Insured / St / M / H
 Sp. Reading: N/A T/Ratio: Insured / St / M / H
 Eng/No: _____
 Chassis: KNAF 3416 M.K 5019831
 Gen. Cond: Good / Fair / Poor / Buryt
 Steering: As / of / Jammed / Locked / Burnt or
 Brake: As / of / Jammed / Locked / Burnt or
 Model: M / B / R / M / B / O / A / R / M / or
 Tyre Size: P1 225/45R17
R1
 BU / DUN / EXNÖVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /
 TOYO / YOKO or B. Kumho
 Front R/Wal. 5 mm R/Wal. 5 mm
 U/Wal. 5 mm U/Wal. 5 mm
 D.O.A. 19/11/21 b.o.l. 23/11/21
 Survey held at Cycle & Carriage
 Det. of Damages: Pri Reor / O/S / H/S / U/C / Rq/Rep or
 The U/C / H/S/H/S frame / Body Structure affected due to collision

23/11/21@2.07pm revert to AIG via Merimon.
23/11/21@2.31pm Lois Chang informed C/A via Merimon.
23/11/21@5.48pm Informed Kevin C/A & ex.\$0/- by email.
28/12/21@10.18am confirmed with Larry final fig \$13787.60, 13 days. (Red \$1752.40, 11%)

28/12 Typist	<input type="checkbox"/>	Prell Report	Days Of Report:	<u>13</u>	Survey Fee Transportation
	<input type="checkbox"/>	Final Report	Resurvey No. of Trips	<u>3</u>	
			Add Fee:	Site Insp (\$ <u> </u>)	Sens.
				Interview (\$ <u> </u>)	Fuel
				Transp. Invo (\$ <u> </u>)	Dinner
				VV&S Invo (\$ <u> </u>)	TOTAL
MER-OD					
13787.60					



CYCLE & CARRIAGE

CYCLE & CARRIAGE KIA PTE LTD

PANDAN GARDENS CUSTOMER SERVICE CENTRE

209 Pandan Gardens Singapore 609339 Tel: 65684555 Fax: 65651240



Movement that inspires

Co Reg No : 199405410K

ESTIMATE

GST Reg No : MR-8500111-X

Invoice Name & Address	Owner Name & Vehicle Info														
AIG Asia Pacific Insurance Pte. Ltd. MOTOR CLAIM DEPARTMENT 78 SHENTON WAY #09-16 AIG BUILDING SINGAPORE 079120 Contact No 64191000	<table> <tr><td>Cust No/Name</td><td>/JOANNE TAN JONG HENG</td></tr> <tr><td>Reg No/Reg Date</td><td>SMF2257C / 31/10/201</td></tr> <tr><td>Date In/Mileage</td><td>19/11/2021/ 0</td></tr> <tr><td>Chassis No</td><td>KNAF3416MK5019831</td></tr> <tr><td>Engine No</td><td>G4FGJH709009</td></tr> <tr><td>Make/Model</td><td>KIA/CERATO 1.6 A SR SX G335</td></tr> <tr><td>Colour/Trim</td><td>B4U GRAVITY BLUE / WK SATURN BLACK</td></tr> </table>	Cust No/Name	/JOANNE TAN JONG HENG	Reg No/Reg Date	SMF2257C / 31/10/201	Date In/Mileage	19/11/2021/ 0	Chassis No	KNAF3416MK5019831	Engine No	G4FGJH709009	Make/Model	KIA/CERATO 1.6 A SR SX G335	Colour/Trim	B4U GRAVITY BLUE / WK SATURN BLACK
Cust No/Name	/JOANNE TAN JONG HENG														
Reg No/Reg Date	SMF2257C / 31/10/201														
Date In/Mileage	19/11/2021/ 0														
Chassis No	KNAF3416MK5019831														
Engine No	G4FGJH709009														
Make/Model	KIA/CERATO 1.6 A SR SX G335														
Colour/Trim	B4U GRAVITY BLUE / WK SATURN BLACK														

Account No	Terms	Date/Time Printed	CSE	Operator	WIP No
LAX00000	Credit	22/11/2021/ 18:03	BLK	282 / Kevin Leong	42813
Description of Goods / Services		Qty	Unit Price	Disc%	Amount
E PNT88000	REPLACE REAR BUMPER, END PANEL, BOOT & AFFECTED AREA 4.5 x 400				1800 2400.00
	REPAIR ON FLOOR PANEL & REAR LH FENDER 1/2				
E PNT98000	PAINT WORK ON REAR BUMPER, BOOT, END PANEL, REAR LH FENDER & FLOOR PANEL 4 x 350				1400 1750.00
E PNT88000	REMOVE & REPLACE REAR PARKING ASSIST				80 120.00
E PNT88000	REMOVE & INSTALL REAR BOOT COMPARTMENT FOR FACILITATE REPAIR				120.00
E PNT88000	TO TANSFER REAR BOOT ATTACHMENTS TO NEW PANEL				120.00
M SUNDRY	TO APPLY SEALANT ON AFFECTED AREA				80.00
M SUNDRY	PERFORM RUST PREVENTION				40 80.00
A 54900099	CHECK WIRING & CHASSIS ELECTRICAL SYSTEM				30.00
A 10028901	TO CARRY OUT DIAGNOSTIC CHECK ON ELECTRONIC CONTROL SYSTEM				120.00
M SUNDRY	TO SUPPLY C & C EMBLEM				40.00
M SUNDRY	TO SUPPLY REAR NUMBER PLATE WITH FRAME				X 50.00
A 15900099	REPLACE REAR EXHAUST MUFFLER				? 400.00
M SUNDRY	SUNDRIES				20 50.00
M LAMP ASSY-REAR COMB INSIDE,LH		1.00	608.00	20.00	486.40
M LAMP ASSY-REAR COMB INSIDE,RH		1.00	608.00	20.00	486.40
M LAMP ASSY-REAR COMB OUTSIDE,LH		1.00	675.00	20.00	540.00
M LAMP ASSY-REAR COMB OUTSIDE,RH		1.00	675.00	20.00	540.00
M LAMP ASSY-CENTER GARNISH		1.00	690.00	20.00	552.00

Confirm & accepted by

Authorized signatory and company stamp

Validity of this estimate is 14 days from date of quote. This is a computer generated document, no signature is required. Estimated costs quoted are excluding GST. We would mention that the above estimate is based on our initial inspection and does not include any additional parts or labour which may be required after repair work has commenced. Occasionally worn or damaged parts are discovered after work has started and needed for repairs or replacement. However, should this occur, we would advise you. Please be informed that a deposit of 50% of the above estimate is payable before commencement of the work. Payment for this may be made in cash, credit card or cheque. You must also agree to pay full amount for renewal of the windscreen in the event of inadvertent breakage in the course of renewing the rubber seal or other repair requiring the removal of the windscreen.



CYCLE & CARRIAGE

CYCLE & CARRIAGE KIA PTE LTD
PANDAN GARDENS CUSTOMER SERVICE CENTRE
209 Pandan Gardens Singapore 609339 Tel: 65684555 Fax: 65651240



Movement that inspires

Co Reg No : 199405410K

ESTIMATE

GST Reg No : MR-8500111-X

Invoice Name & Address	Owner Name & Vehicle Info
AIG Asia Pacific Insurance Pte. Ltd. MOTOR CLAIM DEPARTMENT 78 SHENTON WAY #09-16 AIG BUILDING SINGAPORE 079120 Contact No 64191000	Cust No/Name /JOANNE TAN JONG HENG Reg No/Reg Date SMF2257C / 31/10/201 Date In/Mileage 19/11/2021/ 0 Chassis No KNAF3416MK5019831 Engine No G4FGJH709009 Make/Model KIA/CERATO 1.6 A SR SX G335 Colour/Trim B4U GRAVITY BLUE / WK SATURN BLACK

Account No	Terms	Date/Time Printed	CSE	Operator	WIP No
LAX00000	Credit	22/11/2021/ 18:03	BLK	282 / Kevin Leong	42813
Description of Goods / Services		Qty	Unit Price	Disc%	Amount
M MUFFLER ASSY-REAR		1.00	757.00	20.00	605.60
M GASKET-EXHAUST PIPE		1.00	14.00	20.00	11.20
M PANEL ASSY-TRUNK LID		1.00	1297.00	20.00	1037.60
M PANEL ASSY-BACK		1.00	324.00	20.00	259.20
M EMBLEM-CERATO		1.00	28.00	20.00	22.40
M LOGO ASSY-KIA SUB		1.00	32.00	20.00	25.60
M COVER-RR BUMPER		1.00	651.00	20.00	520.80
M COVER-RR BUMPER LWR		1.00	241.00	20.00	192.80
M COVER-RR BUMPER UNDER, LH		1.00	33.00	20.00	26.40
M COVER-RR BUMPER FOG LAMP, LH		1.00	88.00	20.00	70.40
M COVER-RR BUMPER FOG LAMP, RH		1.00	88.00	20.00	70.40
M LAMP ASSY-SIDE T/SIGNAL, LH		1.00	181.00	20.00	144.80
M LAMP ASSY-SIDE T/SIGNAL, RH		1.00	181.00	20.00	144.80
M EXTN WIRING ASSY-BWS		1.00	207.00	20.00	165.60
M BRACKET-RR BEAM UPR MTG, LH		1.00	9.00	20.00	7.20
M BRACKET-RR BEAM UPR MTG, RH		1.00	9.00	20.00	7.20
M BRACKET-RR BEAM LWR, CTR		1.00	6.00	20.00	4.80
M BRACKET-RR BEAM LWR MTG		2.00	6.00	20.00	9.60
M BEAM-RR BUMPER		1.00	318.00	20.00	254.40
M ANTENNA ASSY-SMARTKEY		1.00	46.00	20.00	36.80
M STAY-RR BUMPER LH		1.00	65.00	20.00	52.00
M STAY-RR BUMPER RH		1.00	65.00	20.00	52.00
M BRACKET ASSY-RR BPR SIDE UPR, L		1.00	25.00	20.00	20.00
M BRACKET-ASSY RR BPR SIDE UPR, R		1.00	31.00	20.00	24.80
M ULTRASONIC SENSOR ASSY-BWS		1.00	163.00	20.00	130.40
M ULTRASONIC SENSOR ASSY-BWS		1.00	163.00	20.00	130.40
M ULTRASONIC SENSOR ASSY-BWS		1.00	163.00	20.00	130.40

Estimate

Steve (LKK)
23/11/21, 10:00

00-MH HL
EXCISE-?
P/P

My BCL Sy

8 days

Confirm & accepted by

LKK Auto Consultants hence notify the Repairer of the following.

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Authorized signatory and company stamp

Nett 12,122.40
7% GST on 12122.40 848.57
Total Payable 12,970.97

Validity of this estimate is 14 days from date of quote. This is a computer generated document, no signature is required. Estimated costs quoted are excluding GST. We would mention that the above estimate is based on our initial inspection and does not include any additional parts or labour which may be required after repair work has commenced. Occasionally worn or damaged parts are discovered after work has started and needed for repairs or replacement. However, should this occur, we would advise you. Please be informed that a deposit of 50% of the above estimate is payable before commencement of the work. Payment for this may be made in cash, credit card or cheque. You must also agree to pay full amount for renewal of the windscreen in the event of inadvertent breakage in the course of renewing the rubber seal or other repair requiring the removal of the windscreen.

SINGAPORE ACCIDENT STATEMENT

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. This report will be forwarded by the Insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
7. By the lodgement of this report to the Insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

ACCIDENT STATEMENT

Date of Submission	22/11/2021 17:34 (SGT)
Date of Accident	19/11/2021 18:35 (SGT)
Exact Location of Accident	Changi Rd, Singapore
Additional Location Information	ALONG CHANGI ROAD TOWARDS GEYLANG ROAD BEFORE SIGLAP PLAIN
Country/State of Loss	Singapore

DETAILS OF OWN VEHICLE

Vehicle Registration Number	SMF2257C
INSURED/POLICYHOLDER	
Is company?	No
Name Of Registered Owner	JOANNE TAN JONG HENG (CHEN RONGTING)
NRIC No	SXXXX187A
Email Address	TANJHJO@YAHOO.COM.SG
Mobile Phone No	(Phone) +65-84280407
Alternative Phone No	+65-84280407

VEHICLE PARTICULARS

Manufacturer	Kia
Model	Cerato
Variant	-
Exact purpose for which vehicle was being used at time of accident	Private use
Are you claiming under your own insurance policy for repair to your vehicle?	Yes
Vehicle Category	Private car
Transmission	Auto
CC	1591

INSURANCE COMPANY

Name of Insurance Company	AIG Asia Pacific Insurance Pte. Ltd.
Type of Coverage	Comprehensive
Fleet Policy	No
Policy Number	1800128102-02
Cover Note Number	-

DRIVER

Name of Driver	JOANNE TAN JONG HENG (CHEN RONGTING)
----------------	--------------------------------------

NRIC No	SXXXX187A
Date Of Birth	15/10/1964
Occupation	Indoor
Date Of Driving Pass	11/12/1990
Driving experience	30 YEARS AND 11 MONTHS
Gender	Female
Mobile Number	(Phone) +65-84280407
Alt. Phone Number	+65-84280407
Email Address	TANJHJO@YAHOO.COM.SG
Address	BLK 42 CASSIA CRESCENT #07-200
Address complement	*
Postcode	390042
Is the driver the policyholder?	Yes
If No, Relationship of the Driver with the Insured	*
Does Driver Own Other Vehicles?	No
Vehicle Registration Number of Other Vehicle Owned by Driver	*
Insurance Company of Other Vehicle Owned by Driver	*

GENERAL INFORMATION OF THE ACCIDENT

Type of Accident	Collision - Head to Rear
Weather Conditions	Clear
Road Surface	Dry

OTHER INFORMATION

Was any foreign vehicle involved in the accident?	No
Number of vehicles involved in the accident	2
Was anybody injured in the Accident?	Yes
Was any injured conveyed to hospital by ambulance?	Yes
Was any other vehicle or property damaged?	Yes
Number of Passengers (Including Driver)	1
Has the driver been approached by unknown person(s) soliciting/offering accident claims assistance?	No

DETAILS OF POLICE ACTION

Was the accident reported to the police?	Yes
Police Station Name	Geylang Neighbourhood Police Centre
Police Station Phone No	(Phone) +65-18008486999
Alt. Police Station Phone No	(Fax) +65-68486799
Police Station Address	1 Cassia Link Singapore 397618
Was notice of intended Prosecution given?	No
If yes, against whom?	-

CIRCUMSTANCES OF ACCIDENT

REFER TO ATTACHMENT

ATTACHMENT(S)

Are accident photos available for attachment?	Yes
Was there any video captured by Car Camera?	Yes
Was there any audio recorded?	No

DETAILS OF OTHER VEHICLE PROPERTY 1

Vehicle Registration Number	SH6008Y
Vehicle Manufacturer	Hyundai
Vehicle Model	I40
Vehicle Variant	-
Vehicle Colour	Blue

Vehicle Category	Taxi
Name of Driver	OH TECK SOON
Contact Number	(Phone) +65-84987711
Address	-
Address complement	-
Postcode	-
Insurance Company Name	-
Nature Of Damage	-
Details of property damaged in accident	-
No. Of Passenger (Including Driver)	-

INJURED PERSONS DETAILS

INJURED 1

Name of injured person	JOANNE TAN JONG HENG (CHEN RONGTING)
Gender	-
Phone No	-
Address	-
Address Complement	-
Post Code	-
Approximate Age Years Old	-
Injuries Sustained	-
Injured person in which vehicle?	SMF2257C
Were seat belts worn?	Yes
Was this injured conveyed to hospital by ambulance?	Yes

SKETCH PLAN

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. The report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

8. Consent under the Personal Data Protection Act (PDPA)

I understand, acknowledge, agree and consent that:

(a) My insurer, my workshop and the General Insurance Association of Singapore ("GIA") may/are permitted to collect, use, disclose and/or process my personal data/personal information set out in this (form) and any other personal information provided by me or possessed by my insurer (collectively the "Personal Information") and disclose and transfer such Personal Information to all insurer(s) who have insured vehicle(s) involved in this accident (all insurer(s) who have insured vehicle(s) involved in this accident shall be collectively referred to as the "Insurers"), the Insurers' lawyers/law firms, the Monetary Authority of Singapore and any relevant government agency/authority (such as the police), for the purpose(s) of:

- (i) processing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigations relating to the claims;
- (ii) investigating the accident and/or my claims;
- (iii) carrying out and/or dealing with my instructions or responding to any enquiries by me;
- (iv) administering my claims (including the mailing of correspondence, statements, invoices, reports or notices to me, which could involve disclosure of certain personal data about me to bring about delivery of the same as well as on the external cover of envelopes/mail packages); and/or
- (v) complying with applicable law in administering, processing, handling and/or dealing with my claims.

(collectively the "Purposes")

(b) all insurer(s) who have insured vehicle(s) involved in this accident and the Insurers' lawyers/law firms, may/are permitted to collect, use, disclose and/or process my Personal Information for one or more of the above Purposes; and

(c) my Personal Information may/can be disclosed by any of the Insurers and/or GIA to their third party service providers or agents (including their lawyers/law firms), which may be sited outside of Singapore, for one or more of the above Purposes.

Policyholder's Signature / Date & Time

Driver's Signature (If driver is not the policyholder) / Date & Time

Witnessed by Reporting Centre Personnel

Sketch Plan

Siglap Plain

Bus stop

(83079)

Changi Road

My car

SH 6008 Y

Siglap Ave

Describe Circumstances of the Accident

Refer to Police report.

At that time, there was heavy traffic on my lane in front of my vehicle, so I slowed down and came to almost a complete stop. Suddenly, I felt a great impact from the rear.

My head was blank after the impact, my whole body was aching and had headache, chest was tight. I was later conveyed by the ambulance to the hospital.

Declaration

We declare the foregoing particulars are true in every respect.



Policyholder's Signature / Date & Time

22 Nov 2021

Driver's Signature (If driver is not the policyholder) / Date & Time

Witnessed by Reporting Centre Personnel



Police Station Of Origin:
Geylang N.P.C
1 Cassia Link SINGAPORE 397618
Tel No: 1800-8486999

Report No. T/20211122/2094

REPORT OF A TRAFFIC ACCIDENT

Date/Time Report Made: 22/11/2021 17:08	Vide Report No.: T/20211120/2092	Station Diary No.: 53
--	-------------------------------------	--------------------------

Informant's Particulars

Name of Informant: JOANNE TAN JONG HENG			Address: APT BLK 42 CASSIA CRESCENT #07-200 SINGAPORE 390042	
ID Type / ID No.: NRIC NO / S1642187A			Contact No.:	Mobile: 84280407
Nationality: SINGAPORE CITIZEN			Home/Office:	
			Email:	
Sex: Female	Age: 57	Date of Birth: 15/10/1964	Type of Informant: Driver	
Race: Chinese			Language:	Institution / School Name:
Occupation: SURVEY INTERVIEWER			Driving Licence Information: Class: 3	
			Date of Expiry:	

General Information of the Accident

Type of Accident:	Injury Conveyed By Ambulance	Drink Drive: No	Date/Time of Accident: 19/11/2021 18:35	Type of Location:
Location: CHANGI ROAD				
Weather: Clear	Road Surface: Dry	Road Speed Limit:		
Traffic Flow: One Way	Traffic Control: Traffic Light - Working	Traffic Volume: Moderate		
Type of Collision: Between Moving Vehicles - Head To Rear		Anyone conveyed by ambulance: Yes		

Details of Vehicle Involved

Vehicle No.	Type	Make	Model	Color	Condition	No of Passenger
SH6008Y	Car	HYUNDAI	I40 1.7 CRDI F/L AT ABS AIRBAG 4DR	Blue	Slightly Damaged	1
SMF2257C	Car	KIA	CERATO 1.6(A) SX	Blue	Seriously Damaged	0

Details of Vehicle Insurance

Vehicle No.	Insurance Company	Insurance No	Effective	Expiry Date



**SINGAPORE
POLICE FORCE**



T/20211122/2094

Police Station Of Origin:
Geylang N.P.C
1 Cassia Link SINGAPORE 397618
Tel No: 1800-8486999

2 of 3

Report No. 1/20211122/2094

CONTINUATION OF REPORT

Details of Vehicle Insurance				
Vehicle No.	Insurance Company	Insurance No	Effective	Expiry Date
SMF2257C	AIG ASIA PACIFIC INSURANCE PTE. LTD.	1800128102-02	01/05/2021	30/04/2022

Details of Person Involved			
Any Pedestrian Involved: No			
No. of Pedestrians Injured: NIL		Use of Pedestrian Crossing: NA	
Driver			
Name	JOANNE TAN JONG HENG	ID No.	S1642187A
Related Vehicle	SMF2257C (Car)	Contact No.	84280407
Hospital/Clinic	NH Changi General Hospital	Class of Driving Licence & Expiry Date	Class: 3 Date of Expiry: NIL
Date Treatment	19/11/2021	Date Discharge	20/11/2021
No. of Days Granted Medical Leave	03	Degree of Injury	Slight

Brief Details.

On the 19/11/2021, about 1830 hours. I was driving along Changi Road before Siglap Plain on the third lane.

At that time, there was heavy traffic in front of my vehicle, hence, I had to slow down and came to an almost complete stop. While waiting for the front vehicle to move off, I felt a very strong collision from the rear of my vehicle. My mind instantly went blank after the strong impact. My entire body was aching and my head was aching too, I also experienced chest tightness. I was still conscious but was temporarily immobilized by the shock.

I then saw from the rear view mirror that the taxi driver and another passenger exited the vehicle and walked over to the bus stop nearby. After a very long time, the taxi driver then came forward to check on me.

The police was called in and the officer on scene subsequently took my SD card from the in car camera.

I was also conveyed to Changi General Hospital via an Ambulance for treatment and received 3 days medical leave.



**SINGAPORE
POLICE FORCE**



T/20211122/2094

3 of 3

Police Station Of Origin:
Geylang N.P.C
1 Cassia Link SINGAPORE 397618
Tel No: 1800-8486999

Report No. T/20211122/2094

CONTINUATION OF REPORT

Sketch Plan

Informant is not able to provide sketch plan

IMPORTANT: Please attach a copy of your vehicle's Insurance Certificate to this report. If you don't have the certificate with you now, please fax a copy to 65474885 stating the report number as reference.

Signature of Officer Recording The Report
G /
Sgt 3 FUN YIK CHUEN, ELDON

Signature Of Interpreter:
Not applicable

Officer In Charge Of Case:
TP / GIT /
Staff Sgt SITI NORHAFIDAH BINTE HANAFI
Contact No.: 65476202

Authentication Stamp
NP168

Signature Of Informant:

Date/Time:
22/11/2021 17:08

Classification Of Case:



SIGNATURE



CERTIFICATE OF INSURANCE

KIA AUTO PROTECTOR PRIVATE VEHICLE

Name of Policyholder : Joanne Tan Jong Heng
Period of Insurance : 01 May 2021 To 30 Apr 2022
Engine No. : G4FGJH709009
Chassis No. : KNAF3416MK5019831

Vehicle No. : SMF2257C
Policy No. : 1800128102-02
Endorsement No. :
Issued Date : 06 Apr 2021

ABOUT THE COVER

Make/Model : KIA Cerato
Engine Capacity/Tonnage : 1,591.00 CC
Driver Restriction : NA

Sum Insured : Market Value
Off Peak Car : No

First Year of Registration : 2018
Insuring with COE/PAF : Yes

Person or Classes of Persons Entitled to Drive* :

- a) The Policyholder
b) Any other person who is driving on the Policyholder's order or with his/her permission.
This Policy will indemnify the Policyholder or any authorised driver only if he/she meets the specified age condition.

You have to pay an additional sum of \$3,000 as "Young and/or Inexperienced Driver Excess" ("YIDR") if You are or Your Authorised Driver (named or unnamed) is under the age of 23 and/or has less than 2 years' driving experience.

Age Condition : All Age Condition
Limitation as to use* :

Mileage Condition : Unlimited Mileage

Use only for social, domestic and pleasure purposes and for the Policyholder's business.

This Policy does not cover use for hire or reward, driving tuition, driving test, racing, pace-making, reliability trial or speed-testing, the carriage of goods other than samples in connection with any trade or business or use for any purpose in connection with Motor Trade.

Loss of Use 1500cc - 1600cc

* Limitations rendered inoperative by Section 8 of the Motor Vehicles (Third-Party Risks and Compensation) Act (Cap. 189), Section 95 of the Road Transport Act, 1987 (Malaysia) and Road Transport (Amendment) Act 2019, are not to be included under these headings.

EXCESS

Section 1

Fire - \$0 Own Damage - \$600 Theft - \$0 Flood Cover - \$600

Section 2

Property Damage - \$0

Windscreen : \$100

Named Driver and Excess (where applicable)

Joanne Tan Jong Heng - \$600 (Own Damage), \$600 (Flood Cover)

APPROVED REPORTING CENTRES/AUTHORISED REPAIRERS (FOR CLAIMS RELATED REPAIRS)

1. Cycle & Carriage Authorised Service Centre (For accident reporting & windscreen claim only) Add: 330 Ubi Rd 3 Singapore 408650 67461000
2. Cycle & Carriage Body & Paint Centre Add: 209 Pandan Gardens Singapore 609339 85684501
3. Cycle & Carriage Authorised Service Centre (For accident reporting & windscreen claim only) Add: 241 Alexandra Road Singapore 159931 64278800
4. Cycle & Carriage Authorised Service Centre (For accident reporting & windscreen claim only) Add: 600 Sin Ming Ave Singapore 575733 69328000

For other Approved Reporting Centres/AIG Authorised Repairers, please contact our 24-hour accident emergency hotline at +65 6338 6200. Alternatively, you may refer to AIG website www.aig.sg or AIG SG Mobile App. Simply search and download "AIG SG" from iTunes or Google Play.

IMPORTANT NOTES

Hire Purchase Company/Employer's Loan: Standard Chartered Bank (Singapore) Limited

We hereby certify that the policy to which this Certificate of Insurance relates is issued in accordance with the provisions of the Motor Vehicles (Third Party Risks and Compensation) Act (Cap. 189), Part IV of the Road Transport Act, 1987 (Malaysia), Road Transport (Amendment) Act 2019 and Motor Vehicles (Third Party Risks) Rules, 1959 (Malaysia).

0504824206

FULCOKICP2 - KT

22 UBI ROAD 4 FULCO BUILDING

SINGAPORE 408617

Underwritten by AIG Asia Pacific Insurance Pte. Ltd.

AIG Asia Pacific Insurance Pte. Ltd.

This computer generated document does not require a signature.

SSPCUE