

03/11/13) wef

ASS. REC. BY:

REF:

CS3/AH21011898/RVf3

0842

ASSIGNMENT

From:

Date:

Estimated Cost:

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No:

at Workshop m/s

of

Insured:

SMZ 4301P

Policy No.

7210041545

Claims No.

3806905140SG

Sum Insured:


Excess:

(Client's Record)

Make of Veh:

(Policy Condition)

Remark: The veh had commenced its
repair at the time of inspection.



Bal. or Market Value:

IDAC Accident Rpt:

Consistent?: Yes or No

GIA / PR Seen:

Consistent?: Yes or No

Est. Repairs:

days

Res.:

Yes or No

Lum Sum:

%

3 Val.:

Yes or No

CA / REV / REP. / 24 HRS

Date:

Person Contacted:

Vehicle: IN / OUT

Date / Time

Action / Instruction

REPAIR LIMIT - 4.5K

29/11/21

Submit DAR

Veh No:

FT 700L

Yr Regn:

2020 / NOV

Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make:

YAMAHA NMAX 155 ABS CVC.c 155

Colour

WHITE

A/C:

Insured / Std / NI / NA

Sp. Reading

5700

T/Radio:

Insured / Std / NI / NA

Eng/No:

C/No:

MH3SG680LK031501

Gen. Cond: Good / Fair / Poor / Burnt

Steering: Inorder / Jammed / Leaked / Burnt or

Brake: Inorder / Jammed / Leaked / Burnt or

Modi:

Nil / S/Rim / STD A/Rim or

Tyre Size:

F:

110/70-13

R:

130/70-13

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or

IRC

Front

Rear

R/Bal.

3

mm

R/Bal.

3

mm

L/Bal.

mm

L/Bal.

mm

D.O.A.

07/07/21

D.O.I.

25/11/21

Survey held at

SPEEDY MOTOR

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

The U/C / Chassis frame / Body Structure affected due to collision.

Date/Time, File Pass to?



Preli. Report

1)



Final Report

Date/Time, File Return to?

2) 29/11/21-typist

Days Of Repair:

2

Resurvey No. of Trip:

Survey Fee:

Transportation:

Add Fee:



Site Insp (\$



Interview (\$



Tech. Invs (\$



Weekend (\$

Report Format :

Lump Sum / I.B.I: (\$

) S + RS, SI

) Photos

) Others

TOTAL

(CON)

(2)Dented (3)Distorted (4)Cracked (5)Cut (6)Scratched
 (7)Bent (8)Shifted (9)Buckled (10)Broken (11)Necessary
 (12)Missing (13)Torn (14)Unconfirmed (15)Not Working

FOR MOTORCYCLE

ACTION (AC)

1. Replace (✓) 2. Repair (X) 3. Check (?)
 4. Not Consistent (NC)

FT 700L

Vehicle No:

Motorcycle

NAC	INC	Item	CON	AC	Qty
1001	991886	Front Number Plate			
3001	995065	Front Tyre			
3002	995095	Front Rim			
3003	994872	Front Tyre Rim Spoke			
3004	991771	Front Fender Wheel Guard			
3005	991283	Front Brake Disc			
3006	991281	Front Brake Caliper			
3007	991785	Front Fork Assy			
3008	991787	Front Fork Inner Tube			
3009	991789	Front Fork Outer Tube			
3010	991167	Front Fork Bracket			
3011	991182	Front Fork Oil Seal			
3012	991174	Front Fork Garnish			
3013	992376	Front Headlamp Rim			
3014	992328	Front Headlamp			
3015	992337	Front Headlamp Bracket			
3016	992345	Front Headlamp Fairing			
3017	992130	Front Windshield			
3018	992134	Front Wing Mirror RH	SC	/	
3019	995245	Front LH Signal Lamp			
3020	995246	Front RH Signal Lamp			
3021	992556	Meter Casing			
3022	992553	Meter Assy			
1118	991019	ERP Bracket			
1119	991020	ERP Unit			
3023	992446	Ignition Switch			
3024	992442	Ignition Key Assy			
3025	990706	Cowling Stay			
3026	994470	Steering Stem			
3027	994427	Steering Cone			
3028	992299	Handle Bar			
3029	992312	Handle Bar Switch			
3030	992310	Handle Bar Grip			
3031	995184	Handle Bar Balancer LH			
3032	992300	Handle Bar Balancer RH	SC	/	
1252	992179	Fuel Tank			
3033	990438	Brake Reservoir			
3034	990621	Clutch Lever			
3035	992293	Hand Brake Lever	SC	/	
3036	991119	Side Fairing			
3037	994220	Side Fairing Top Garnish			
3038	994219	Side Fairing Inner Garnish			
3039	991118	Fairing Shield			
3040	992047	Front Top Fairing Inner Garnish			
3041	991123	Fairing Top Garnish			
3042	990538	Center Fairing			
3043	993378	Rear Fairing			
3044	991121	Fairing Stopper			
3045	991117	Fairing Lower			

NAC	INC	Item	CON	AC	Qty
1052	995074	Radiator			
1053	992738	Radiator Cowling			
3046	994146	Seat Assy			
3047	990915	Engine Crash Bar			
3048	990928	Engine Guard			
1067	990219	Battery			
1068	990224	Battery Cover			
1069	990223	Battery Bracket			
3049	991144	Foot Brake			
3050	991154	Front Foot Rest			
3051	991779	Front Foot Rest Bracket			
3052	994269	Side Stand			
3053	992549	Main Stand			
3054	990615	Clutch Engine Cover			
3055	992478	Kick Starter Rubber			
3056	992477	Kick Starter Lever			
3057	991145	Foot Gear Shifter			
3058	993500	Rear Foot Rest			
3059	993501	Rear Foot Rest Bracket			
3060	992581	Exhaust Muffler Heat Shield			
3061	991058	Exhaust Muffler Assy			
1405	993719	Rear LH Shock Absorber			
1445	993720	Rear RH Shock Absorber			
3062	995065	Rear Tyre			
3063	991200	Rear Rim			
3064	994872	Rear Tyre Rim Spoke			
3065	993474	Rear Fender Wheel Guard			
3066	993443	Rear Fender Mudflap			
3067	992940	Rear Brake Disc			
3068	992936	Rear Brake Caliper			
3069	995236	Rear Spocket			
3070	990585	Chain			
3071	990580	Chain Guard			
3072	994530	Swing Arm			
1420	993819	Rear Sub frame			
3073	995245	Rear LH Signal Lamp			
3074	995246	Rear RH Signal Lamp			
3075	995251	Rear Taillamp			
1137	993626	Rear Number Plate			
3076	994192	Side Box			
3077	992927	Rear Box	CR	/	
3078	992928	Rear Box Bracket			
3079	991328	Emblem			
1136	990247	Sticker			
		RH Side Vrsore	SC	/	

2 days

No of Items:

Assessor:

SINGAPORE ACCIDENT STATEMENT

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

ACCIDENT STATEMENT

Date of Submission	17/11/2021 19:21 (SGT)
Date of Accident	07/07/2021 16:15 (SGT)
Exact Location of Accident	Singapore
Additional Location Information	THOMSON ROAD
Country/State of Loss	Singapore

DETAILS OF OWN VEHICLE

Vehicle Registration Number FT700L

INSURED/POLICYHOLDER

Is company?	No
Name Of Registered Owner	LIM CHENG LIANG
NRIC No	S7112004Z
Email Address	jaylim@asia.com
Mobile Phone No	(Phone) +65-97930926
Alternative Phone No	+65-97930926

VEHICLE PARTICULARS

Manufacturer	Yamaha
Model	NMAX
Variant	-
Exact purpose for which vehicle was being used at time of accident	Private use
Are you claiming under your own insurance policy for repair to your vehicle?	No - Claiming third party
Vehicle Category	Motorcycle
Transmission	Auto
CC	155

INSURANCE COMPANY

Name of Insurance Company	NTUC Income Insurance Co-operative Ltd
Type of Coverage	Comprehensive
Fleet Policy	No
Policy Number	5119776783
Cover Note Number	07/11/2020 - 06/11/2021

DRIVER

Name of Driver	KELLY GRACE CHUA
NRIC No	S7522293I

th	16/07/1975
on	Indoor
Driving Pass	07/01/1994
experience	27 YEARS AND 6 MONTHS
er	Female
ie Number	(Phone) +65-92399909
Phone Number	-
ell Address	kellychua@asia.com
Address	BLK 160 LORONG 1 TOA PAYOH #03-1586
Address complement	-
Postcode	310160
Is the driver the policyholder?	No
If No, Relationship of the Driver with the Insured	FIANCEE
Does Driver Own Other Vehicles?	No
Vehicle Registration Number of Other Vehicle Owned by Driver	-
Insurance Company of Other Vehicle Owned by Driver	-

GENERAL INFORMATION OF THE ACCIDENT

Type of Accident	Hit and run / Vandalism / Damaged whilst parked
Weather Conditions	Clear
Road Surface	Dry

OTHER INFORMATION

Was any foreign vehicle involved in the accident?	No
Number of vehicles involved in the accident	2
Was anybody injured in the Accident?	No
Was any injured conveyed to hospital by ambulance?	-
Was any other vehicle or property damaged?	Yes
Number of Passengers (Including Driver)	1
Has the driver been approached by unknown person(s) soliciting/offering accident claims assistance?	No

DETAILS OF POLICE ACTION

Was the accident reported to the police?	Yes
Police Station Name	Traffic Police
Police Station Phone No	(Phone) +65-65470000
Alt. Police Station Phone No	(Fax) +65-65474900
Police Station Address	10 Ubi Avenue 3 Singapore 408865
Was notice of intended Prosecution given?	No
If yes, against whom?	-

CIRCUMSTANCES OF ACCIDENT

REFER TO POLICE REPORT

ATTACHMENT(S)

Are accident photos available for attachment?	Yes
Was there any video captured by Car Camera?	No
Was there any audio recorded?	No

DETAILS OF OTHER VEHICLE PROPERTY 1

Vehicle Registration Number	SMZ4301P
Vehicle Manufacturer	-
Vehicle Model	-
Vehicle Variant	-
Vehicle Colour	-
Vehicle Category	Private car

Driver	JIANG KUN
Vehicle Number	S8365388D
Phone	(Phone) +65-83181910
Passenger complement	-
Police code	21 OXLEY WALK #01-16
Insurance Company Name	238593
Nature Of Damage	-
Details of property damaged in accident	-
No. Of Passenger (Including Driver)	-



**SINGAPORE
POLICE FORCE**



T/20210707/7029

Police Station Of Origin:
Traffic Police
10 Ubi Avenue 3 SINGAPORE 408865
Tel No: 65470000

2 of 3

Report No, T/20210707/7029

CONTINUATION OF REPORT

Details of Person Involved			
Any Pedestrian Involved: No			
No. of Pedestrians Injured: NIL		Use of Pedestrian Crossing: NA	
Rider			
Name	KELLY GRACE CHUA	ID No.	S7522293I
Related Vehicle	FT700L (Motorcycle)	Contact No.	92399909
Hospital/Clinic	NIL	Class of Driving Licence & Expiry	Class: NIL Date of Expiry: NIL
Date	NIL	Date	NIL
No. of Days granted Medical Leave	NIL	Degree of	NIL

Brief Details.

At 4:13pm on 7 July 2021, I (FT700L) parked at the slip road, exactly in front of Far East Flora main gate at Thomson Road behind vehicle SMZ4301P. The exact coordinates is 120°10.8'N 10350°12.7'E. From the incident video, it is a dark grey Mitsubishi MPV (model looks like Mitsubishi Outlander).

I went into Far East Flora to purchase a pot of flower and was alerted by Far East Flora staff who attends to scanning customer's temperature at the main gate, that my bike was hit and toppled. I came out of Far East Flora at 4:20pm (after 7 minutes from the start of my parking time) to check on the bike. The bike toppled to the right side and content in my top box was scattered all over the floor. The bike was damage on the right and the top box cracked. Contents like my helmet was scarred and my mobile phone screen cracked.

This is a obvious hit-and-run case by vehicle SMZ4301P. There is no way the driver is unaware of the hit as there would have been a loud noise from the falling. The driver could have reversed the car onto my bike front wheel causing it to fall. My bike was within the driver's view on the right side mirror but I suppose the driver reverse without checking the rear camera view or check the right side mirror. Whatever the case, the driver drove off irresponsibly.

To add on, the motorcycle owner is my fianc (Lim Cheng Liang) and I am the authorised rider under his insurance. There is no pedestrian crossing on this road and I have a video of the vehicle in front of me but I am unable to upload the file here. I am now awaiting another stationery vehicle (parked behind me) to come back to me if his in-car camera captured any footage that might be useful for this case.

> Back to OneMotoring

Enquire PARF/COE Rebate for Registered Vehicle

Owner ID Type:	Singapore NRIC
Owner ID:	004Z
Vehicle No.:	FT700L
Vehicle to be Exported:	No
Intended Deregistration Date:	29 Nov 2021
Vehicle Make:	YAMAHA
Vehicle Model:	NMAX 155 ABS CVT
Primary Colour:	White
Manufacturing Year:	2020
Engine No.:	G3L8E0210062
Chassis No.:	MH3SG5680LK031501
Maximum Power Output:	-
Open Market Value:	\$2,754.00
Original Registration Date:	07 Nov 2020
First Registration Date:	07 Nov 2020
Transfer Count:	1
Actual ARF Paid:	\$414.00
PARF Eligibility:	No
PARF Eligibility Expiry Date:	-
PARF Rebate Amount:	\$0.00
COE Expiry Date:	06 Nov 2030
COE Category:	D - Motorcycle
COE Period(Years):	10
QP Paid:	\$7,300.00
COE Rebate Amount:	\$6,525.00
Total Rebate Amount:	\$6,525.00

The information contained herein is correct as at 29 Nov 2021

OK