

08/11/13) wef

ASS. REC. BY: James

REF:

CS3/AH21011898/Rivf3

0042

ASSIGNMENT

From:

Date:

Estimated Cost:

Veh No:

FT 700L

Yr Regn: 2020 / NOV

Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

Truck / Trailer or

To Inspect Vehicle No:

FT 700L

Make:

YAMAHA NMAX 155 ABS CVT.c 155

at Workshop m/s

SPEEDY MOTOR CYCLE SERVICE

Colour:

WHITE

A/C: Insured / Std / NI / NA

of

10, AMK IND PK 2A (AMPOINT) #05-21

Sp. Reading

5700

T/Radio: Insured / Std / NI / NA

Insured:

AKH

Eng/No:

Policy No.

C/No:

MH3SG680LK031501

Claims No.

Gen. Cond: Good / Fair / Poor / Burnt

Sum Insured:

Excess:

Steering: Inorder / Jammed / Leaked / Burnt or

(Client's Record)


Brake: Inorder / Jammed / Leaked / Burnt or

Make of Veh:

Modi: Nil / S/Rim / STD A/Rim or

(Policy Condition)

Remark: The veh had commenced its repair at the time of inspection.



Bal. or Market Value:

11K

Tyre Size:

F:

110/70-13

R:

130/70-13

IDAC Accident Rpt:

Consistent? : Yes or No

Front

Rear

R/Bal.

3

mm

R/Bal.

3

mm

GIA / PR Seen:

Consistent? : Yes or No

L/Bal.

mm

L/Bal.

mm

Est. Repairs:

days

Res.: Yes or No

D.O.A.

07/07/21

D.O.I.

25/01/21

Lum Sum:

%

3 Val.: Yes or No

Survey held at

SPEEDY MOTOR

CA / REV / REP. / 24 HRS

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

Date:

Person Contacted:

Vehicle: IN / OUT

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time

Action / Instruction

REPAIR LIMIT - 4.5K

Date/Time, File Pass to?



: Preli. Report

1)



: Final Report

Date/Time, File Return to?

2)

Days Of Repair:

Resurvey No. of Trip:

Survey Fee:

Transportation:

Add Fee:



: Site Insp (\$

) S + RS, SI



: Interview (\$

) Photos



: Tech. Invs (\$

) Others



: Weekend (\$

)

Report Format :

Lump Sum / I.B.I: (\$

)

TOTAL

(CON)

(2)Dented (3)Distorted (4)Cracked (5)Cut (6)Scratched
(7)Deformed (8)Shifted (9)Buckled (10)Broken (11)Necessary
(12)Missing (13)Torn (14)Unconfirmed (15)Not Working

FOR MOTORCYCLE

FT 700L

1. Replace (✓) 2. Repair (X) 3. Check (?)
4. Not Consistent (NC)

Vehicle No:

Motorcycle

[illegible][illegible]

No of Items:

Assessor:

SINGAPORE ACCIDENT STATEMENT

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

ACCIDENT STATEMENT

Date of Submission	17/11/2021 19:21 (SGT)
Date of Accident	07/07/2021 16:15 (SGT)
Exact Location of Accident	Singapore
Additional Location Information	THOMSON ROAD
Country/State of Loss	Singapore

DETAILS OF OWN VEHICLE

Vehicle Registration Number	FT700L
INSURED/POLICYHOLDER	
Is company?	No
Name Of Registered Owner	LIM CHENG LIANG
NRIC No	S7112004Z
Email Address	jaylim@asia.com
Mobile Phone No	(Phone) +65-97930926
Alternative Phone No	+65-97930926

VEHICLE PARTICULARS

Manufacturer	Yamaha
Model	NMAX
Variant	-
Exact purpose for which vehicle was being used at time of accident	Private use
Are you claiming under your own insurance policy for repair to your vehicle?	No - Claiming third party
Vehicle Category	Motorcycle
Transmission	Auto
CC	155

INSURANCE COMPANY

Name of Insurance Company	NTUC Income Insurance Co-operative Ltd
Type of Coverage	Comprehensive
Fleet Policy	No
Policy Number	5119776783
Cover Note Number	07/11/2020 - 06/11/2021

DRIVER

Name of Driver	KELLY GRACE CHUA
NRIC No	S7522293I

16/07/1975	16/07/1975
Indoor	Indoor
07/01/1994	07/01/1994
27 YEARS AND 6 MONTHS	27 YEARS AND 6 MONTHS
Female	Female
(Phone) +65-92399909	(Phone) +65-92399909
-	-
kellychua@asia.com	kellychua@asia.com
BLK 160 LORONG 1 TOA PAYOH #03-1586	BLK 160 LORONG 1 TOA PAYOH #03-1586
-	-
310160	310160
No	No
FIANCEE	FIANCEE
No	No
-	-
-	-

GENERAL INFORMATION OF THE ACCIDENT

Type of Accident	Hit and run / Vandalism / Damaged whilst parked
Weather Conditions	Clear
Road Surface	Dry

OTHER INFORMATION

Was any foreign vehicle involved in the accident?	No
Number of vehicles involved in the accident	2
Was anybody injured in the Accident?	No
Was any injured conveyed to hospital by ambulance?	-
Was any other vehicle or property damaged?	Yes
Number of Passengers (Including Driver)	1
Has the driver been approached by unknown person(s) soliciting/offering accident claims assistance?	No

DETAILS OF POLICE ACTION

Was the accident reported to the police?	Yes
Police Station Name	Traffic Police
Police Station Phone No	(Phone) +65-65470000
Alt. Police Station Phone No	(Fax) +65-65474900
Police Station Address	10 Ubi Avenue 3 Singapore 408865
Was notice of intended Prosecution given?	No
If yes, against whom?	-

CIRCUMSTANCES OF ACCIDENT

REFER TO POLICE REPORT

ATTACHMENT(S)

Are accident photos available for attachment?	Yes
Was there any video captured by Car Camera?	No
Was there any audio recorded?	No

DETAILS OF OTHER VEHICLE PROPERTY 1

Vehicle Registration Number	SMZ4301P
Vehicle Manufacturer	-
Vehicle Model	-
Vehicle Variant	-
Vehicle Colour	-
Vehicle Category	Private car

Driver	JIANG KUN
Number	S8365388D
Pass complement	(Phone) +65-83181910
Code	-
Insurance Company Name	21 OXLEY WALK #01-16
Nature Of Damage	238593
Details of property damaged in accident	-
No. Of Passenger (Including Driver)	-



**SINGAPORE
POLICE FORCE**



T/20210707/7029

Police Station Of Origin:
Traffic Police
10 Ubi Avenue 3 SINGAPORE 408865
Tel No: 65470000

2 of 3

Report No. T/20210707/7029

CONTINUATION OF REPORT

Details of Person Involved			
Any Pedestrian Involved: No			
No. of Pedestrians Injured: NIL		Use of Pedestrian Crossing: NA	
Rider			
Name	KELLY GRACE CHUA	ID No.	S75222931
Related Vehicle	FT700L (Motorcycle)	Contact No.	92399909
Hospital/Clinic	NIL	Class of Driving Licence & Expiry	Class: NIL Date of Expiry: NIL
Date	NIL	Date	NIL
No. of Days granted Medical Leave	NIL	Degree of	NIL

Brief Details.

At 4:13pm on 7 July 2021, I (FT700L) parked at the slip road, exactly in front of Far East Flora main gate at Thomson Road behind vehicle SMZ4301P. The exact coordinates is 120°10.8'N 10350'12.7"E. From the incident video, it is a dark grey Mitsubishi MPV (model looks like Mitsubishi Outlander).

I went into Far East Flora to purchase a pot of flower and was alerted by Far East Flora staff who attends to scanning customer's temperature at the main gate, that my bike was hit and toppled. I came out of Far East Flora at 4:20pm (after 7 minutes from the start of my parking time) to check on the bike. The bike toppled to the right side and content in my top box was scattered all over the floor. The bike was damage on the right and the top box cracked. Contents like my helmet was scarred and my mobile phone screen cracked.

This is a obvious hit-and-run case by vehicle SMZ4301P. There is no way the driver is unaware of the hit as there would have been a loud noise from the falling. The driver could have reversed the car onto my bike front wheel causing it to fall. My bike was within the driver's view on the right side mirror but I suppose the driver reverse without checking the rear camera view or check the right side mirror. Whatever the case, the driver drove off irresponsibly.

To add on, the motorcycle owner is my fianc (Lim Cheng Liang) and I am the authorised rider under his insurance. There is no pedestrian crossing on this road and I have a video of the vehicle in front of me but I am unable to upload the file here. I am now awaiting another stationery vehicle (parked behind me) to come back to me if his in-car camera captured any footage that might be useful for this case.

> Back to OneMotoring

Enquire PARF/COE Rebate for Registered Vehicle

Owner ID Type:	Singapore NRIC
Owner ID:	004Z
Vehicle No.:	FT700L
Vehicle to be Exported:	No
Intended Deregistration Date:	29 Nov 2021
Vehicle Make:	YAMAHA
Vehicle Model:	NMAX 155 ABS CVT
Primary Colour:	White
Manufacturing Year:	2020
Engine No.:	G3L8E0210062
Chassis No.:	MH35G5680LK031501
Maximum Power Output:	-
Open Market Value:	\$2,754.00
Original Registration Date:	07 Nov 2020
First Registration Date:	07 Nov 2020
Transfer Count:	1
Actual ARF Paid:	\$414.00
PARF Eligibility:	No
PARF Eligibility Expiry Date:	-
PARF Rebate Amount:	\$0.00
COE Expiry Date:	06 Nov 2030
COE Category:	D - Motorcycle
COE Period(Years):	10
QP Paid:	\$7,300.00
COE Rebate Amount:	\$6,525.00
Total Rebate Amount:	\$6,525.00

The information contained herein is correct as at 29 Nov 2021

OK