

ASS. REG. BY

Steve

03/11/2019/29/EF3

ASSIGNMENT

From:

Date:

Estimated Cost

OD / TP / WRT / PRR / OD-RES / EVA / INV / MV

To inspect Vehicle No:

at Workshop m/s

Insured:

Policy No.

Claims No.

Sum Insured:

Excess:

(Client's Record)

Make of Vehicle

(Policy Condition)

Remarks: The vehicle concerned need its repair at the time of inspection.

Ref. or Market Value:

ICAC Accident Report

Consistent? : Yes or No

RIA / PR Seen

Consistent? : Yes or No

Est. Repairs:

days

Rep.: Yes or No

Com Sum:

%

3 Vol.: Yes or No

QA / REV / REP. / 24 HRS

Vehicle: IN / OUT

Date:

Person Contacted:

Date / Time

Action / Instruction

MV-706

26.01.2022 Confirmed final fig \$8,500.00; 8 days with Andrew (Red \$12,173.30; 58%)

one/Two, FDR, Resolved

☐ Prelim. Report  
☐ Final Report

one/Two, FDR, Returned

Approved:

OD

Value Sum / U.P. / P

LS \$8,500.00

Vehicle No:

GRK 3085D

YR Regn:

30/3/20

Type: M/Car / M/Cycle / Bus / Van / Lorry / H/Veh / Prime Mover /

Truck / Trailer or

Make:

Nissan NV350

CB 26.88

Colour:

White

AG: Insured / Std / NI / N

Sp/Reading

60385

T/Ratio: Insured / Std / NI / N

Eng/No:

JNIMC2E9620036087

Chassis

Gen. Cond: Good / Fair / Poor / Burnt

Steering: Inop / Jammed / Locked / Burnt or

Brakes: Inop / Jammed / Locked / Burnt or

Mod: H/M / S/Rim / STD / Air / or

195R15C

Tyre Size:

P1

RI

SS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or

TRIANGLE

Front

R/Rat.

4

mm

Rear

R/Rat.

4

mm

U/Rat.

4

mm

U/Rat.

4

mm

D.O.A.

20/11/21

Efficient Motor

Survey held at

Dist. of Damages: Pri / Rear / C/S / H/S / VIC / Reglap or

The R/O / CHASSIS frame / Body structure affected due to collision

Days Of Repair:

8

Resurvey No. of Trips

Survey Fee

Transportation

Breaks

Others

Add Fee:

☐

Site Insp (\$

☐

Interview (\$

☐

Tech. Inve (\$

☐

Weekend (\$