



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile				
AUTO & GENERAL INSURANCE (S) PL (BUDGET DIRECT INSURANCE) 190 CLEMENCEAU AVENUE #03-01 SINGAPORE SHOPPING CENTRESINGAPORE 239924			Ref: CS/AGI21011936/Avf3n2	Date: 20/12/2021
			Code: AGI	
1. Policy Particulars :- THIRD PARTY CLAIM				
Insured Veh.	SDD 997E	Veh. Inspected	SMG 7878Y	
Policy No.		Coverage (\$)	0.00	
Claim No.	C10012612/EE	Excess (\$)	0.00	
Assign From	IVY RATILLA	Assign Date	24/11/2021	
2. Vehicle Particulars & Condition				
Make & Model	MERCEDES BENZ S300L	c.c	2997	
Engine No.	HIDDEN	Year of Reg.	2008	
Chassis No.	WDD2211542A200155	Colour	BEIGE	
Odometer	133873 KM	Steering	IN ORDER	
Brakes	IN ORDER	Modification	SPORTS RIM	
General	GOOD			
3. Conditions of Tyres				
	Size	Make	Balance	
R/H Front Tyre	235/55 R17	MICHELIN	6 mm	
L/H Front Tyre	235/55 R17	MICHELIN	6 mm	
R/H Rear Tyre	235/55 R17	MICHELIN	6 mm	
L/H Rear Tyre	235/55 R17	MICHELIN	6 mm	
4. Description of Damages				
THE VEHICLE SUSTAINED DAMAGES AT THE FRONT AND REAR PORTION. DAMAGES SEE DETAILS.				
5. General Information				
Accident Date	22/11/2021	Inspection Date	24/11/2021	
Survey held at	J-MART MOTOR PTE LTD BLK 5 DEFU LANE 10 #01-578 DEFU INDUSTRIAL PARK C SINGAPORE 539186			
5a. Remarks				
A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.				
5b. Estimate Days of Repair				
ESTIMATED NORMAL PERIOD FOR REPAIR:			5 Working Days	