



Your Ref: CMTD1600395

Date: 05th May 2022

Our Ref: CS1/LAW21011964/Gtf3e2

M/s Sompo Insurance Singapore PL

C/o : Chey LLC

20 Havelock Road

#02-47 Central Square

Singapore 059765

Dear Sir / Madam,

EVALUATION REPORT (PAPER SURVEY) OF ACCIDENT VEHICLE NO: PA 2713T

INSURED VEHICLE: CB 7030X

ACCIDENT DATE: 27/01/2016

We thank you for your instruction on 24/11/2021.

We acknowledge receipt of the following documents:-

- a) Automobile Inspection Report of PA 2713T from M/s Vicom LTD.
- b) Final Repair Bill of PA 2713T from M/s Teng Meng Motor Service.
- c) Singapore Accident Statement and Police Report of Vehicles PA 2713T and CB 7030X.
- d) Colour damaged vehicle photographs of PA 2713T.

Based on the documents received from you, we have evaluated the damages of the vehicle and have the following comments:-

1. Information Recorded: -

Registration Number	: PA 2713T
Make & Model	: Toyota Hiace Auto
Chassis Number	: LH1721006179
Year of Registration	: 2001
Engine Capacity	: 2985 cc

2. We recommend that the repairs of the entire damage require about 16 (Sixteen) working days to complete.
3. We hereby provide our recommendations on the cost of repair to the damaged vehicle as stated in the following page.