

Motor Survey Report

Claim No : CMTD1600395
Type : TPD
Survey at : TENG MENG MOTOR SERVICE
Inspection Date : 05/02/2016
Insured Vehicle : CB7030X
Vehicle Surveyed : PA2713T
Date of Accident : 27/01/2016
@06:00 PM
Excess : S\$.00

Vehicle Details

Make : TOYOTA
Model : HIACE(A)
Chasis No. : 172-1006179
Engine No. : NIL
Speedometer : NO KEY
Tyres Condition : Good
Front Tyre N/S : 50%
O/S : 50%
Year : 2001
cc/Tonnage : 6693
Colour : White
Brakes : Serviceable
Steering : Affected
General Condition : Good
Size : BRIDGESTONE 185 R14
Rear Tyre N/S : 60%
O/S : 60%

Description of Damages

FRONTAL, O/S & N/SBODY

Estimate Normal Period for Repairs : 12-14 DAYS

Inspection and Adjustment

Original quotation : S\$10,000 - \$15,000

Surveyed by : IN-HOUSE SURVEYOR - TEO SEE LING