

## **LKK Auto Consultants Pte Ltd**

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 1

PRE-REPAIR INSPECTION REPORT						
	AXA INSURANCE	PTE LTD		Ref:	CS3/ASM21011965/Bqy3e2	
	8 SHENTON WAY SINGAPORE 0688		Date:	11/02/2022		
	ATTN: KOH JANIC	E		Code:	ASM	
1.	Policy Particulars :- (THIRD PARTY CLAIM)					
	Insured Veh.	SHA 6121U	Veh. Inspected	l	SLU 9826Y	
	Policy No.	VFX/P2419138	Coverage (\$)		0.00	
	Claim No.	S1M03MT4	Excess (\$)		0.00	
	Assign From	KOH JANICE	Assign Date		25/11/2021	
2. Vehicle Particulars & Condition						
	Make & Model	SEAT LEON 5DR 1.0	c.c		999	
	Engine No.	HIDDEN	Year of Reg.		2017	
	Chassis No.	VSSZZZ5FZJR055857	Colour		GREY	
	Odometer	76595 KM	Steering		IN ORDER	
	Brakes	IN ORDER	Modification		SPORTS RIM	
	General	GOOD				
3. Conditions of Tyres						
		Size	Make		Balance	
	R/H Front Tyre	225/40 R18	CONTINENTAL		6 mm	
	L/H Front Tyre	225/40 R18	CONTINENTAL		6 mm	
	R/H Rear Tyre	225/40 R18	CONTINENTAL		6 mm	
	L/H Rear Tyre	225/40 R18	CONTINENTAL		6 mm	
4. Description of Damages						
	THE VEHICLE SUS	HE VEHICLE SUSTAINED DAMAGES AT THE O/S BODY.				
5.	5. General Information					
	Accident Date	22/11/2021	Inspect Date /	Time	25/11/2021 ( 02:26 PM )	
	Survey held at	BLK 7 SIN MING INDUSTRIAL E	STATE SECTOR	C #01-82	2	
	Repairer	GUAN AUTO SERVICE				
5a.	Remarks					
	A) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS. B) THE REPAIR ESTIMATE WAS NOT PRESENTED AT THE TIME OF INSPECTION. THE REPAIRER WAS TOLD TO PREPARE THE ESTIMATE. C) ENCLOSED PLEASE FIND DAMAGED VEHICLE PHOTOGRAPHS. D) THE ESTIMATED REPAIR COST OF THE DAMAGED VEHICLE IS IN THE REGION OF \$2,000-\$3,000					
5b. Estimate Days of Repair						
	ESTIMATED NORMAL PERIOD FOR REPAIR: 4 Working Days					

Report Ref No. CS3/ASM21011965/Bqy3e2

Inspected By

LIM TEOW GUAN

**Automotive Assessor** 

K.K.LAU CPT(RET)

 $BEng(Hons), B. Bus, MBA, PEng, PE, \, MInstAEA, MASME, MIRTE$ 

**REGD Auto Consultant-SAE, Licensed Appraiser**