

LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile						
	SOMPO INSURAN	CE SINGAPORE PL		Ref:	CS/SMO21012021/Aqf3n2	
	50 RAFFLES PLAC SINGAPORE LAND	CE #03-03 O TOWERSINGAPORE 048623		Date:	21/12/2021	
				Code:	SMO	
1.	Policy Particulars :- THIRD PARTY CLAIM					
	Insured Veh.	FBS 6400R	Veh. Inspected	k	SLZ 7107B	
	Policy No.		Coverage (\$)		0.00	
	Claim No.	CMTD2103497/GPL	Excess (\$)		0.00	
	Assign From	GRACE TEO	Assign Date		26/11/2021	
2. Vehicle Particulars & Condition						
	Make & Model	TOYOTA VIOS	c.c		1496	
	Engine No.	HIDDEN	Year of Reg.		2018	
	Chassis No.	MR2B23F3901121103	Colour		BRONZE	
	Odometer	57864 KM	Steering		IN ORDER	
	Brakes	IN ORDER	Modification		SPORTS RIM	
	General	GOOD				
3. Conditions of Tyres						
		Size	Make		Balance	
	R/H Front Tyre	185/60 R15	FALKEN		6 mm	
	L/H Front Tyre	185/60 R15	FALKEN		6 mm	
	R/H Rear Tyre	185/60 R15	FALKEN		6 mm	
	L/H Rear Tyre	185/60 R15	FALKEN		6 mm	
4.	4. Description of Damages					
	THE VEHICLE SUSTAINED DAMAGES AT THE REAR N/S PORTION.					
	DAMAGES SEE DETAILS.					
5.	General Information					
	Accident Date	25/11/2021	Inspection Dat	te	26/11/2021	
	Survey held at	J-MART MOTOR PTE LTD	-			
		BLK 5 DEFU LANE 10				
		#01-578 DEFU INDUSTRIAL PARK C SINGAPORE 539186				
5a.	Remarks					
		A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.				
5b.	Estimate Days of Repair					
	STIMATED NORMAL PERIOD FOR REPAIR: 6 Working Days					
	-					