

ASS. REC. BY:

REF: LPC / 21012047 lkgy3

C

Kenneth

**ASSIGNMENT**

From: \_\_\_\_\_ Date: \_\_\_\_\_  
 Estimated Cost: \_\_\_\_\_  
 OD /  TP /  WS /  TP RES /  OD RES /  EVA /  INV /  MV  
 To Inspect Vehicle No: \_\_\_\_\_  
 at Workshop m/s Cheng Ltao  
 of \_\_\_\_\_  
 Insured: \_\_\_\_\_  
 Policy No. \_\_\_\_\_  
 Claims No. \_\_\_\_\_  
 Sum Insured: \_\_\_\_\_ Excess: 07  
 (Client's Record)  
 Make of Veh: \_\_\_\_\_

(Policy Condition)

Remark: The veh had commenced its repair at the time of inspection.

<input checked="" type="checkbox"/>	<input checked="" type="checkbox"/>
N/S	O/S
<input type="checkbox"/>	<input type="checkbox"/>

Bal. or Market Value: 861K  
 IDAC Accident Rpt: \_\_\_\_\_ Consistent? : Yes or No  
 GIA / PR Seen: \_\_\_\_\_ Consistent? : Yes or No  
 Est. Repairs: 0.4 days Res.: Yes or No  
 Lum Sum: 13.1 % 3 Val.: Yes or No  
 CA / REV / REP. / 24 HRS  
 Date: \_\_\_\_\_ Person Contacted: \_\_\_\_\_ Vehicle: IN / OUT

Veh No: SBW 7777 Yr Regn: 01.15  
 Type:  M.Car /  M.Cycle /  Bus /  Van /  Lorry /  Taxi /  Prime Mover /  Truck /  Traller or  
 Make: Mercedes CLA 180 c.c. 1595  
 Colour: M. Silver A/C:  Insured /  Std /  NI /  NA  
 Sp. Reading: 125439 T/Radio:  Insured /  Std /  NI /  NA  
 Eng/No: \_\_\_\_\_  
 C/No: W001173422-N 143195  
 Gen. Cond:  Good /  Fair /  Poor /  Burnt  
 Steering:  Inorder /  Jammed /  Leaked /  Burnt or  
 Brake:  Inorder /  Jammed /  Leaked /  Burnt or  
 Mod:  Nil /  S/Rlm /  STD /  Rlm or  
 Tyre Size: F: 225/40R18  
 R: \_\_\_\_\_  
 BS /  DUN /  EXNOVA /  GY /  FS /  LIZA /  MIC /  OHTSU /  PIR /  SUMI /  TOYO /  YOKO or  
 Front R/Bal. 8 mm Rear R/Bal. 8 mm  
 L/Bal. 8 mm L/Bal. 8 mm  
 D.O.A. 26/11/21 D.O.I. 29/11/2021  
 Survey held at \_\_\_\_\_  
 Des. of Damages:  Frt /  Rear /  O/S /  N/S /  UIC /  Rooftop or  
 The UIC / Chassis frame / Body Structure affected due to collision.

Date / Time	Action / Instruction
<u>22/12</u>	<u>8534.65 Cabin</u>
<u>23/12/2021 1.36pm</u>	<u>confirmed with Epsada final fig 85406.70, 4 days. Cred 2168.45, 29.1%</u>

Date/Time, File Pass to?  : Prell. Report  
 : Final Report  
 Date/Time, File Return to?

Report Format: OD  
 Lump Sum / I.B.I. (\$) 5406.70

Days Of Repair: 4  
 Resurvey No. of Trip: 3

Add Fee:  : Site Insp (\$) )  
 : Interview (\$) )  
 : Tech Invs (\$) )  
 : Weekend (\$) )

Survey Fee: \_\_\_\_\_  
 Transportation: \_\_\_\_\_  
 S + RS: \_\_\_\_\_  
 Fuel: \_\_\_\_\_  
 Others: \_\_\_\_\_  
 TOTAL: \_\_\_\_\_

**Cheng Hoe Motor Pte Ltd**

Blok 1019, Yishun Industrial Park A #01-374/382, Singapore 768761  
 TEL: 67556142 (YIS) FAX: 67557719 (YIS) Email: chmotor@singnet.com.sg  
 GST: 201001158E RCB NO:201001158E

SBW777Y  
 OD/Lonpac

M/S : LONPAC INSURANCE BERHAD  
 300 BEACH ROAD  
 #17-04/07 THE CONCOURSE  
 SINGAPORE 199555

TEL: 62507388 FAX: 62963767  
 ATTN: Motor Claim Department

WS Ref: OD/LONPAC  
 Claim Type: Own Damage  
 Accident Date: 26/11/2021

*Not authorized*  
*Running After Rain*  
*Today*

Claim No: ES2191152  
 Estimate No: ES2191152/YISHUN  
 Date: 29 Nov 2021  
 Policy No: Z21VP05028230  
 Veh Reg No: SBW777Y  
 Make/Model: MERCEDES BENZ  
 CLA180 (R18 BI)  
 Chassis No: WDD1173422N143145  
 Engine No: 27091030511146  
 Reg. Date: 05/01/2015

**Estimate Repair Cost to Vehicle No : SBW777Y**

Pages: 1/1

Description	U/Price	Quantity	Cost S\$	Amount S\$
<b>Cost Plus</b>				
1 ENGINE UNDER COVER	290.00	1 PC	290.00	✓
2 FRONT BUMPER UNDER COVER	185.00	1 PC	185.00	✓
3 ENGINE TURBO COOLER	480.00	1 PC	480.00	✓ 485 ✓
4 ENGINE TURBO COOLER COVER	25.00	1 PC	25.00	✓ 245 ✓
5 AIR-CON CONDENSER	585.00	1 PC	585.00	✓ 920
6 RADIATOR	405.00	1 PC	405.00	✓ 290
7 RADIATOR FAN MOTOR	285.00	1 PC	285.00	✓ 290
8 ENGINE FRT UNDER CROSS MEMBER	755.00	1 PC	755.00	✓ 800 ✓
9 FRONT EXHAUST PIPE	1,240.00	1 PC	1,240.00	✓
10 WATER COOLER	295.00	1 PC	295.00	✓
11 WATER COOLER BRACKET	20.00	1 PC	20.00	✓
			4,555.00	
	Add 15%		684.75	5,249.75
<b>Special Net</b>				
12 RADIATOR COOLANT (4 LTRS)	60.00	1 UNIT	60.00	✓ 60.00
<b>Labour</b>				
13 TOWING	50.00	1 LA	50.00	✓
14 REMOVE & REFIX FRT BUMPER ASSY, HEADLAMPS, RADIATOR & MOTOR, GRILLE, UNDER COVER, TO REPAIR FRT SUPPORT PANEL & REALIGN THE SAME	600.00	1 LA	600.00	✓ 450 ✓
15 REMOVE AND REFIX AIRCON, CHECK, VACUUM & REFILL GAS	100.00	1 LA	100.00	✓
16 REMOVE & REFIX ENGINE TURBO COOLER, FRT EXHAUST PIPE, ENGINE UNDER CROSS MEMBER, WATER COOLER & RESET SYSTEM	600.00	1 LA	600.00	✓ 400 ✓
				1,350.00

Total S\$ 6,659.75  
 Add GST @ 7% 466.18  
 Total Amount payable S\$ 7,125.93

For Cheng Hoe Motor Pte Ltd

AUTHORISED SIGNATURE

**LKK Auto Consultants** hence notify  
 the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from insurance Company

Acknowledged by Repairer  
 Signature:  
 Date:

&gt; Back to OneMotoring

**Enquire PARF/COE Rebate for Registered Vehicle**

<b>Vehicle Owner Particulars</b>	
Owner ID Type:	Singapore NRIC
Owner ID:	530A
<b>Vehicle Details</b>	
Vehicle No.:	SBW777Y
Vehicle to be Exported:	No
Intended Deregistration Date:	26 Nov 2021
Vehicle Make:	MERCEDES BENZ
Vehicle Model:	CLA180 (R18 BI)
Primary Colour:	Silver
Manufacturing Year:	2014
Engine No.:	27091030511146
Chassis No.:	WDD1173422N143145
Maximum Power Output:	90.0 kW (120 bhp)
Open Market Value:	\$27,392.00
Original Registration Date:	05 Jan 2015
First Registration Date:	05 Jan 2015
Transfer Count:	1
Actual ARF Paid:	\$20,349.00
<b>Intended PARF Rebate Details</b>	
PARF Eligibility:	Yes
PARF Eligibility Expiry Date:	04 Jan 2025
PARF Rebate Amount:	\$13,226.00
<b>Intended COE Rebate Details</b>	
COE Expiry Date:	04 Jan 2025
COE Category:	A - Car up to 1600cc & 97kW (130bhp)
COE Period(Years):	10
QP Paid:	\$63,990.00
COE Rebate Amount:	\$19,885.00
<b>Total Rebate Amount:</b>	<b>\$33,111.00</b>

The information contained herein is correct as at 26 Nov 2021

OK

SC1G21BQ0002 / CHENG HOE MOTOR PTE LTD[768761]  
 ENTRY DATE & TIME: 26/11/2021 17:53 (SGT)  
 SUBMITTED BY: CHIONG BENG CHOON  
 VERSION: 1 (26/11/2021 17:53 (SGT))

## SINGAPORE ACCIDENT STATEMENT

### IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. This report will be forwarded by the Insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

### ACCIDENT STATEMENT

Date of Submission .....	26/11/2021 17:53 (SGT)
Date of Accident .....	26/11/2021 07:30 (SGT)
Exact Location of Accident .....	Singapore
Additional Location Information .....	PIE TOWARDS CHANGI AIRPORT BEFORE BKE EXIT
Country/State of Loss .....	Singapore

### DETAILS OF OWN VEHICLE

Vehicle Registration Number .....	SBW777Y
-----------------------------------	---------

#### INSURED/POLICYHOLDER

Is company? .....	No
Name Of Registered Owner .....	COLIN TAN BOON LEE
NRIC No .....	SXXXX530A
Email Address .....	colintanbl@gmail.com
Mobile Phone No .....	(Phone) +65-96569037
Alternative Phone No .....	+65-96569037

#### VEHICLE PARTICULARS

Manufacturer .....	Mercedes
Model .....	CLA180 (R18 BI)
Variant .....	-
Exact purpose for which vehicle was being used at time of accident .....	Private use
Are you claiming under your own insurance policy for repair to your vehicle? .....	Yes
Vehicle Category .....	Private car
Transmission .....	Auto
CC .....	1595

#### INSURANCE COMPANY

Name of Insurance Company .....	Lonpac Insurance Bhd
Type of Coverage .....	Comprehensive
Fleet Policy .....	No
Policy Number .....	Z21VP05028230
Cover Note Number .....	05/01/21 - 04/01/22

#### DRIVER

Name of Driver .....	COLIN TAN BOON LEE
NRIC No .....	SXXXX530A

Date Of Birth ..... 12/12/1970  
 Occupation ..... Indoor  
 Date Of Driving Pass ..... 01/09/1992  
 Driving experience ..... 29 YEARS AND 2 MONTHS  
 Gender ..... Male  
 Mobile Number ..... (Phone) +65-96569037  
 Alt. Phone Number ..... +65-96569037  
 Email Address ..... colintanbl@gmail.com  
 Address ..... 11 WOODLANDS DRIVE 72 #09-39  
 Address complement ..... -  
 Postcode ..... 738094  
 Is the driver the policyholder? ..... Yes  
 If No, Relationship of the Driver with the Insured ..... -  
 Does Driver Own Other Vehicles? ..... No  
 Vehicle Registration Number of Other Vehicle Owned by Driver ..... -  
 Insurance Company of Other Vehicle Owned by Driver ..... -

GENERAL INFORMATION OF THE ACCIDENT

Type of Accident ..... Collided into Property  
 Weather Conditions ..... Clear  
 Road Surface ..... Dry

OTHER INFORMATION

Was any foreign vehicle involved in the accident? ..... No  
 Number of vehicles involved in the accident ..... 1  
 Was anybody injured in the Accident? ..... No  
 Was any injured conveyed to hospital by ambulance? ..... -  
 Was any other vehicle or property damaged? ..... No  
 Number of Passengers (Including Driver) ..... 1  
 Has the driver been approached by unknown person(s) soliciting/offering accident claims assistance? ..... No

DETAILS OF POLICE ACTION

Was the accident reported to the police? ..... No  
 Was notice of intended Prosecution given? ..... No  
 If yes, against whom? ..... -

CIRCUMSTANCES OF ACCIDENT

Driving along lane 2. There was a block of wood in the middle of the lane. There were cars so unable to avoid driving over the block of wood cause my car under carriage damage.

ATTACHMENT(S)

Are accident photos available for attachment? ..... Yes  
 Was there any video captured by Car Camera? ..... Yes  
 Was there any audio recorded? ..... No

**SKETCH PLAN**

1. VEHICLE NO: SBW 777 Y

2. INSURER CO: LONPAC

3. ACCIDENT DATE & TIME: 26/11/21 7:30 AM

**IMPORTANT NOTICE**

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to reputate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. The report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.
8. **Consent under the Personal Data Protection Act (PDPA)**

I understand, acknowledge, agree and consent that:

(a) My insurer, my workshop and the General Insurance Association of Singapore ("GIA") may/are permitted to collect, use, disclose and/or process my personal data/personal information set out in this [form] and any other personal information provided by me or possessed by my insurer (collectively the "Personal Information") and disclose and transfer such Personal Information to all insurer(s) who have insured vehicle(s) involved in this accident (all insurer(s) who have insured vehicle(s) involved in this accident shall be collectively referred to as the "Insurers"), the insurers' lawyers/law firms, the Monetary Authority of Singapore and any relevant government agency/authority (such as the police), for the purpose(s) of:

(i) processing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigations relating to the claims;

(ii) investigating the accident and/or my claims;

(iii) carrying out and/or dealing with my instructions or responding to any enquiries by me;

(iv) administering my claims (including the mailing of correspondence, statements, invoices, reports or notices to me, which could involve disclosure of certain personal data about me to bring about delivery of the same as well as on the external cover of envelopes/mail packages); and/or

(v) complying with applicable law in administering, processing, handling and/or dealing with my claims. (collectively the "Purposes")


(b) all insurer(s) who have insured vehicle(s) involved in this accident and the insurers' lawyers/law firms, may/are permitted to collect, use, disclose and/or process my Personal Information for one or more of the above Purposes; and

(c) my Personal Information may/can be disclosed by any of the insurers and/or GIA to their third party service providers or agents (including their lawyers/law firms), which may be sited outside of Singapore, for one or more of the above Purposes.


 26/11/21

Policyholder's Signature / Date & Time


Driver's Signature (if driver is not the policyholder) / Date & Time

 26/11/21  
Witnessed by Reporting Centre Personnel

**Sketch Plan**



Sketch Plan



DESCRIBE CIRCUMSTANCES OF THE ACCIDENT

Driving along lane 2  
 There was a block of wood in the middle of the lane  
 There were cars so unable to avoid driving over the block of wood, cause my car undercarriage damage


Note : Please note that your Insurer may have 14days Time Frame for you to submit an Own Damage Claim under your own comprehensive policy. Please check with your policy for more information.

DECLARATION

I/We declare the foregoing particulars are true in every respect:

 26/11/21

Policyholder's Signature  
Date & Time:

  
 Driver's Signature  
 (If driver is not the policyholder)  
 Date & Time:

 26/11/21

Reporting Centre Personnel's Signature

Name:  
NRIC/FIN No.:

- Claim Own Policy     Claim Third Party     Reporting Only  
 Claim OD/TP at other workshop (\_\_\_\_\_)



# Efficient Towing Services

403 Sin Ming Avenue #13-307, Sin Ming Garden, Singapore 570403

Ah Di Mobile: 8588 8877

Email: efficienttowing.sg@gmail.com

Business Reg. No.: 53349344K

biSAFE<sub>3</sub>

NO. 85070

## CASH SALE / JOB ORDER

Date: 26/11/21

Messrs: Cheng Hoe Woodhill  
 车牌 SBW 777Y 车型 CLARUS  
 Vehicle No. SBW 777Y Model No: CLARUS  
 时间 (日/夜) 0952 联络号码 96569037  
 Time (day/night): 0952 Contact No: 96569037  
 由 Pasir Panjang Nature Park  
 Location: Pasir Panjang Nature Park  
 到 38 Woodhill Ind Park E1  
 To: 38 Woodhill Ind Park E1  
 银额 50 其他 Others:  
 Cash \$ 50  
 经手人 2 Tow Truck  
 Authorised By: 2 Driver Name: WD

- Jump Start/Changing of battery
- Tyre Replacement
- Accident/Breakdown
- Multi/Basement
- With Load/Cargo Box
- King Dolly
- Transport Charge
- Low Body Kit
- Door Opening Service
- Crane Up/Winch Out
- Collect Doc/Key
- Repo
- Woodlands and Tuas Checkpoint

注意: 本公司对所拖之车辆, 在道行中如有任何损失或破坏, 一概由车主自行负责。

Note: Vehicle is towed at owner's risk. The company accepts no responsibility for damages or other misdemeanour to your vehicle whilst being towed.

E. & O. E.