Our Job Ref No :			305495980		ENGINEERIN			
Date :			02/12/21		Co 59	omfortDelGro Engineering Pte Lt. Loyang Drive Singapore 50896		
FINA	ALIZAT	TION FORM			Fa	x: 6546 8156		
То	: _		LKK		Fax:			
Attn	: <b>N</b>	Иr	Thevan					
Vehi	cle Re	g No. : SH	D3512D CTPL			26/11/2021		
The	survey	and estimates	of the repairs of the above-m	entioned vehic	le are as follow	/s:-		
1.		repair job shall		AIG		SKZ8066R		
2.	The	finalized amou	nt shall be:					
	(a)	Spare Parts	after List discount					
	(b)	Labour Charg	ges					
		Total for Par	rt-By-Part Repair Cost			\$0.00		
	(c.)	Lumpsum Repair (if applicable) Total for Lumpsum repair cost after Less:		20%				
		Final Lumps	um Repair cost	207	Occopsis.	\$2,150.00		
3. 4.	We si	hall treat the a	eriod for repairs:  bove amount as Correct an		orking days. there is no re	eply from you within 7		
4. 5.	We sl worki	hall treat the a ing days < you for your a	bove amount as Correct an	d Confirmed in	there is no re e confirm the a	estimates and		
<b>4</b> . <b>5</b> .	We si worki Thank	hall treat the a ing days	bove amount as Correct and assistance.	d Confirmed in W	there is no re	estimates and		
<b>4</b> . <b>5</b> .	We si worki Thank	hall treat the a ing days	issistance.	d Confirmed in Walter Si	there is no red te confirm the conditionalized amount	estimates and		
<b>4</b> . <b>5</b> .	We si worki Thank Signal Name	hall treat the aing days  k you for your a  ture:  : MS. LO	issistance.  KE YY	d Confirmed in Walter Si	there is no reference is no re	Theyun		
<b>4</b> . <b>5</b> .	We si worki Thank Signal Name Tel Fax	ture:  MS. LO	issistance.  KE YY	d Confirmed in Walter Si	there is no reference is no re	Theyun		
<b>4</b> . <b>5</b> .	We si worki Thank Signal Name Tel Fax	ture:  MS. LO  621483	issistance.  KE YY	d Confirmed in William Si Na Da	re confirm the chalized amount gnature:	They un		
4. 5.	We si worki Thank Signal Name Tel Fax	ture:  : MS. LOI : 621483 : 654681	issistance.  KE YY  556	d Confirmed in W fir Si Na Da  Document Attached Yes or No	there is no reference is no re	They un 7 1/2/2		
4. 5. For Of	We si worki Thank Signat Name Tel Fax ficial L	ture:  : MS. LOI : 621483 : 654681  Jse Only  tem	issistance.  KE YY  556	Document Attached Yes or No	re confirm the chalized amount gnature:	They un 7 1/2/2		
4. 5. For Of	We si worki Thank Signal Name Tel Fax ficial L	ture:  : MS. LOI : 621483 : 654681  Jse Only  tem  te P/Day come Paid	issistance.  KE YY  556	d Confirmed in W fir Si Na Da  Document Attached Yes or No	re confirm the chalized amount gnature:	They un 7 1/2/2		
5. Ren	We si worki Thank Signat Name Tel Fax ficial L	ture:  : MS. LOI : 621483 : 654681  Jse Only  tem  te P/Day come Paid es	issistance.  KE YY  555  Amount	Document Attached Yes or No	re confirm the chalized amount gnature:	They un 7 1/2/2		
For Off  Ren  Loss  LTA  Med	We si worki Thank Signat Name Tel Fax ficial L  Ital Rai s of Inc. Search dical Fe	ture:  : MS. LOI : 621483 : 654681  Jse Only  tem  te P/Day come Paid es	issistance.  KE YY  556	Document Attached Yes or No	re confirm the chalized amount gnature:	They un 7 1/2/2		

## **COMFORT TRANSPORTATION PTE LTD**

REPAIR ESTIMATE

Vehicle No. : SHD3512D

Make

: HYUNDAI

Model : I-40

Date: 29.11.21

Insurance: AIG

MVA: MS. LOKE YY

Qty	Parts Description / Labour	Туре	Unit Price	Amount
	FRONT BUMPER COVER			\$1,052.20
10	FRONT BUMPER CLIPS	=	\$2.20	\$22.00
	FRT BUMPER BRACKET TOP LH			\$44.80
•	RADIATOR GRILLE		_ = = =	\$1,480.00
	HEADLAMP LH			\$1,388.00
	HEADLAMP SUPPORT PANEL	1		\$907.40
•	FRT BUMPER GRILLE TOP GARNISH	73	= = =	\$80.00
4	FRT BUMPER SPONGE	= =		\$379.20
•	FRT BUMPER REINFORCEMENT		= = = =	\$588.40
	RADIATOR			\$1,637.20
-	FRT BUMPER GRILLE AIR DUCT LH	= = =		\$126.20
1	RADIATOR BRACKET LH	=======================================		\$13.00
	SUB TOTAL			\$7,718.40
	LESS 20%			\$1,543.68
	DISCOUNTED TOTAL	===		\$6,174.72
	FRT NUMBER PLATE WITH TRIM COVER			\$55.00 <b>\$55.0</b> 0
	Labour Charge			
	PANEL BEATING			\$600.00
	SPRAY PAINTING CHARGE			\$300.00
	CHK ALL LIGHTING		-	\$60.00
	TOTAL LABOUR			\$960.00
	ESTIMATE TOTAL			\$7,189.72

This is an initial estimate based on a visual inspection of the above vehicle. The final repair quantum will be prepared after the vehicle is surveyed by a motor Surveyor appointed by the insurance company.

LKK Auto Consultants hence notify

Thwane and to com

82235769

29/11/21 1630

LIS 9fter repair photo Page 1

2 clays wp

the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date: