

ESTIMATED ACCIDENT REPAIR COST



ACCIDENT TIME REPORTED	13:16HRS
ACCIDENT DATE	24-Nov-21
BUS CAPTAIN NAME	MUHAMMAD HAMZAH BI MOHD ZAINI
THIRD PARTY CLAIM AGAINST	MS First Capital Insurance Ltd

BUS REGISTRATION NUMBER	SG5869R
BUS TYPE (SD/DD)	DD
BUS ROUTE NUMBER	
BUS ADVERTS (Y/N)	N

SECTION 1 : PARTS & CONSUMABLE ITEMS (MATERIAL COST)

NO.	Part or Item Description	Quantity	Total Cost
1	OUTDOOR IP CAMERA WITH LENS ASSY <i>ca</i>	1	\$ 1,200.00
		7% GST	\$ 84.00
		PARTS TOTAL COST	\$ 1,284.00

SECTION 2 : ASSESSMENT / REPAIR / SPRAY PAINT (LABOUR COST)

LABOUR ITEM (PLEASE SPECIFY IF ITS ASSESSMENT, REPAIR OR SPRAY PAINT)	TOTAL COST
TO DISMANTLE & REPLACE :- <ul style="list-style-type: none"> OUTDOOR IP CAMERA WITH LENS ASSY CONFIGURATION TESTING 	<div>1200</div> <div>320</div> <div>\$ 1,300.00</div>
TO REMOVE & INSTALL PARTS AND TO PERFORM REPAIR WORKS :- <ul style="list-style-type: none"> NS REAR ACCESS DOOR SIDE ACCESS DOOR 	<div>320</div> <div>\$ 1,350.00</div>
SPRAY PAINTING :- <ul style="list-style-type: none"> NS REAR ACCESS DOOR SIDE ACCESS DOOR 	<div>640</div> <div>\$ 1,280.00</div>
<div>1280</div>	
<div>7% GST</div> <div>\$ 317.10</div>	
<div>LABOUR TOTAL COST</div> <div>\$ 4,847.10</div>	

SPRAY PAINTING \$640 PER PANEL
LABOUR CHARGES \$650 PER DAY

ESTIMATED ACCIDENT REPAIR COST



SECTION 3 : RECOVERY OF ACCIDENT BUS (TOWING COST)

TOTAL TOWING COST	-
-------------------	---

SECTION 4 : NUMBER OF DAYS BUS IN WORKSHOP FOR SURVEY & REPAIRS

		DATE IN	
		DATE & TIME SURVEY	
		DATE OUT	
		TOTAL NUMBER OF DAYS	
BUS TYPE (SD / DD)	DD		
LOSS OF USE COST		\$	2,000.00

1200
1280
2480
2 days

SUMMARY	
SECTION NO.	COST
1	\$ 1,284.00
2	\$ 4,847.10
3	-
4	\$ 2,000.00
TOTAL	\$ 8,131.10

PAGE 2

LKK Auto Center

I hereby certify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature: _____

Date: _____

Rasul
Hp 90010068
2 days
29/11/21 @ 1450
Resy after repair