



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile				
SOMPO INSURANCE SINGAPORE PL 50 RAFFLES PLACE #03-03 SINGAPORE LAND TOWERSINGAPORE 048623			Ref: CS/SMO21012070/Kvf3n2	
			Date: 10/12/2021	
			Code: SMO	
1. Policy Particulars :- THIRD PARTY CLAIM				
Insured Veh.	SJZ 1138A		Veh. Inspected	SLZ 280D
Policy No.			Coverage (\$)	0.00
Claim No.	CMTD2103517/MYE		Excess (\$)	0.00
Assign From	MELVIN YE YONG KANG		Assign Date	29/11/2021
2. Vehicle Particulars & Condition				
Make & Model	HONDA JAZZ (A)		c.c	1339
Engine No.	HIDDEN		Year of Reg.	2006
Chassis No.	JHMGD18506S221577		Colour	RED
Odometer	224797 KM		Steering	IN ORDER
Brakes	IN ORDER		Modification	STANDARD ALLOY RIM
General	GOOD			
3. Conditions of Tyres				
		Size	Make	Balance
R/H Front Tyre		185/55 R15	YOKOHAMA	6 mm
L/H Front Tyre		185/55 R15	YOKOHAMA	6 mm
R/H Rear Tyre		185/55 R15	YOKOHAMA	6 mm
L/H Rear Tyre		185/55 R15	YOKOHAMA	6 mm
4. Description of Damages				
THE VEHICLE SUSTAINED DAMAGES AT THE REAR N/S PORTION. DAMAGES SEE DETAILS.				
5. General Information				
Accident Date	27/11/2021		Inspection Date	30/11/2021
Survey held at	LAI HUAT (MENG KEE) MOTOR PTE LTD 160 SIN MING DRIVE #04-01/02 SIN MING AUTOCITY SINGAPORE 575722			
5a. Remarks				
A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.				
5b. Estimate Days of Repair				
ESTIMATED NORMAL PERIOD FOR REPAIR:			7 Working Days	