

ASS. REC. BY:

REF:

AGG/21012073/KV

Kenneth

ASSIGNMENT

From: _____ Date: _____

Estimated Cost: _____

OD / TP / WS / TP RES / QD RES / EVA / INV / MV

To Inspect Vehicle No: _____

at Workshop m/s _____

of _____

Insured: _____

Policy No. _____

Claims No. _____

Sum Insured: _____ Excess: _____

(Client's Record)

Make of Veh: _____

(Policy Condition)

Remark: The veh had commenced its repair at the time of inspection.

N/S	O/S

Bal. or Market Value: _____

IDAC Accident Rpt: _____ Consistent?: Yes or No

GIA / PR Seen: _____ Consistent?: Yes or No

Est. Repairs: 03 days Res.: Yes or NoLum Sum: 20 % 3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Date: _____ Person Contacted: _____ Vehicle: IN / OUT

Veh No: PTS 87684 Yr Regn: 09, 09

Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or WagonMake: Hyundai i30 c.c. 1391Colour: N. Red A/C: Insured / Std / NI / NASp. Reading: 212878 T/Radio: Insured / Std / NI / NA

Eng/No: _____

C/No: KM14DC 81 DM AU 055103Gen. Cond: Good / Fair / Poor / BurntSteering: In order / Jammed / Leaked / Burnt orBrake: In order / Jammed / Leaked / Burnt orModl: Nil / S/Rim / STD A/Rim orTyre Size: F: Kumho R: 195/65R15

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or

Front

R/Bal. 9 mm

Rear

R/Bal. 6 mmL/Bal. 9 mmL/Bal. 6 mmD.O.A. 17/10/21D.O.I. 30/11/2021

Survey held at _____

Des. of Damages: Fr / Rear / O/S / N/S / U/C / Rooftop or

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time Action / Instruction

Date/Time, File Pass to?

☐ : Prell. Report

Days Of Repair: _____

1)

☐ : Final Report

Resurvey No. of Trip: _____

Date/Time, File Return to?

2)

Survey Fee:

Transportation:

S + RS. \$

Fees

Others

TOTAL

Add Fee: ☐ : Site Insp (\$ _____)☐ : Interview (\$ _____)☐ : Tech Invs (\$ _____)☐ : Weekend (\$ _____)

Report Format :

Lump Sum / I.B.I. (\$) _____

H C AUTO PTE LTD

160 Sin Ming Drive # 05-09 Sin Ming Auto City Singapore 575722

Tel : 6457 0678 Fax : 6457 8287

Co. and GST Reg. No. : 200820153N

Date: 29 / 11 / 2021

ESTIMATE COSTS OF REPAIR

M/s Car Philosophy Pte Ltd

C/o 160 Sin Ming Drive #05-09

Sin Ming Auto City

Singapore 575722

*NOT Notified
11/12/21
Repair After Paint
3 days*

Dear Sir / Madam ,

Vehicle no. : SJS 8768 Y - Hyundai i30
Accident date : 17 / 10 / 2021

Quantity	Descriptions	Amount (S\$)
1	1 pc front bumper fascia	\$ 648.90 ?
2	1 pc o/s front bumper side retainer	\$ 75.00 ✓
3	1 pc o/s front fender	\$ 598.00 X
4	1 pc o/s front fender inner garnish	\$ 175.80 X
5	10 pcs o/s front fender inner garnish clip 1 @ 5.00	\$ 50.00 ✓
6	1 pc n/s front bumper fog lamp	\$ 209.00 X
7	1 pc n/s front bumper fog lamp cover	\$ 88.10 ✓
8	1 pc o/s head lamp	\$ 606.20 ?
		\$ 2,451.00
	Less 20%	\$ 490.20
		\$ 1,960.80

Labour charges

To putty and spray painting

Re-seal anti rust

To check, replace, repair wiring

To check wheel alignment

Total

\$ 680.00	300l
\$ 680.00	400l
\$ 80.00	X
\$ 120.00	20l
\$ 120.00	X
\$ 3,640.80	

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

Page 1 of 1



Police Station Of Origin:
Sengkang N.P.C
2 Sengkang Square #01-02 SINGAPORE
545025
Tel No: 1800-343 8999

Report No. T/20211017/2063

REPORT OF A TRAFFIC ACCIDENT

Date/Time Report Made: 17/10/2021 18:26	Vide Report No.:	Station Diary No.: 82
--	------------------	--------------------------

Informant's Particulars

Name of Informant: CHUA CHEE BENG			Address: APT BLK 530 SERANGOON NORTH AVENUE 4 #04-04 SINGAPORE 550530		
ID Type / ID No.: NRIC NO / S7133899A			Contact No.: Home/Office: Mobile: 82338844		
Nationality: SINGAPORE CITIZEN			Email: Jasonchua032@gmail.com		
Sex: Male	Age: 50	Date of Birth: 28/09/1971	Type of Informant: Driver		
Race: Chinese			Language:		Institution / School Name:
Occupation: GO-JEK DRIVER			Driving Licence Information: Class: 3 Date of Expiry:		

General Information of the Accident

Type of Accident:	Non-Injury Others	Drink Drive: No	Date/Time of Accident: 17/10/2021 13:55	Type of Location: Carpark lot
Location: SERANGOON NORTH AVENUE 4				
Weather: Clear		Road Surface: Dry	Road Speed Limit:	
Traffic Flow:		Traffic Control: Not Controlled	Traffic Volume: Light	
Type of Collision: Moving Vehicle Against - Parked Vehicle			Anyone conveyed by ambulance: No	

Details of Vehicle Involved

Vehicle No.	Type	Make	Model	Color	Condition	No of Passenger
SDS905S	Car	HYUNDAI	Elantra	Grey	Slightly Damaged	0
SJS8768Y	Car	HYUNDAI	I30	Red	Slightly Damaged	0

Details of Person Involved

Any Pedestrian Involved: No	
No. of Pedestrians Injured: NIL	Use of Pedestrian Crossing: NA



SINGAPORE POLICE FORCE



T/20211017/2063

002.11ac

2 of 2

Police Station Of Origin:
Sengkang N.P.C
2 Sengkang Square #01-02 SINGAPORE
545025
Tel No: 1800-343 8999

Report No. T/20211017/2063

CONTINUATION OF REPORT

Driver			
Name	Unknown Driver		ID No. NIL
Related Vehicle	SDS905S (Car)		Contact No. NIL
Hospital/Clinic	NIL		Class of Driving Licence & Expiry Date Class: NIL Date of Expiry: NIL
Date Treatment	NIL		
No. of Days granted Medical Leave	NIL	Date Discharge	NIL
Driver		Degree of Injury	NIL
Name	CHUA CHEE BENG		ID No. S7133899A
Related Vehicle	SJS8768Y (Car)		Contact No. 82338844
Hospital/Clinic	NIL		Class of Driving Licence & Expiry Date Class: 3 Date of Expiry: NIL
Date Treatment	NIL		
No. of Days granted Medical Leave	NIL	Date Discharge	NIL
		Degree of Injury	NIL

Brief Details.

On 17/10/2021 at about 1355hrs, when I wanted to retrieve my vehicle bearing SJS8768Y at Blk 542A Serangoon North Avenue 4, 2 male and a female subjects who are washing their vehicle walked towards me informing me that a vehicle bearing SDS905S reversed and knocked my vehicle. I last parked my vehicle at Deck 1A, lot number 57 on 16/10/2021 at about 2200hrs.

I went to checked on my vehicle and observed that the front right side of my vehicle had some damaged to it. Subsequently, the driver of SDS905S came back and I told him that he knocked onto my vehicle. I told him that there are witness that saw what happened. After which, he walked towards the witness and they had an argument. The driver of SDS905S mentioned that the witness and I colluded into blaming him about the damage done on the vehicle.

I then told the guy that I will be making a police report with regards to the matter since he has already denied that he knocked my vehicle. I checked on vehicle SDS905S and saw that the damages are exactly similar to the ones that my vehicle had. The witness mentioned to me that he had indeed saw that the driver of vehicle SDS905S collided with my vehicle. The witness by the name of Mark, Tel: 81520804, 3LU 3276Z informed that he will be my witness if needed be.

wish to state that the driver of vehicle SDS905S parked his vehicle at lot number 58 which is just beside my vehicle. There is a CCTV installed at the carpark.