



INSPECTION CHECKLIST

Reference no: CS5/TP21012081/Cq

Section A: Vehicle Check

| | |
|-----------------------|----------------------|
| Applicant | VENTURE CARS PTE LTD |
| Date of Inspection | 29/11/2021 |
| Time of Inspection | 11:30 HRS |
| Vehicle Make | TOYOTA |
| Vehicle Model | YARIS CROSS 1.5XB |
| Vehicle Model Code | 5BA-MXPB10-BHXRB-B |
| Engine Number | M15AY230521 |
| Chassis Number | MXPB102014648 |
| Motor Number (if any) | - |
| Odometer Reading | 50 KM |

| | |
|-----------------|-----------|
| Wheels | |
| Front Tyre Size | 205/65R16 |
| Rear Tyre Size | 205/65R16 |

| Lighting | Yes | No | Remarks |
|-----------------------|-------------------------------------|---------|---|
| Auto Levelling System | | X | |
| Front Fog Lamp | X | | |
| Rear Fog Lamp | | X | |
| Type of Low Beam | <input checked="" type="checkbox"/> | Halogen | <input type="checkbox"/> LED <input type="checkbox"/> HID |
| Type of High Beam | <input checked="" type="checkbox"/> | Halogen | <input type="checkbox"/> LED <input type="checkbox"/> HID |

| Others | Yes | No | Remarks |
|-----------------------------|-----|---------------------------------|---|
| Sunroof / Moonroof (if any) | | X | |
| Transmission Type | | <input type="checkbox"/> Manual | <input checked="" type="checkbox"/> Automatic |


Vehicle Identification (VIN) Chassis Plate



Chassis Number Stamping




Engine Number Stamping



Front View



Rear View



Right View




Left View




Engine Compartment



Front Tyre Size



Rear Tyre Size




Instrument Panel



Exhaust System



Exhaust System



Exhaust System



Speedometer



Odometer



Vehicle Light Transmittance (VLT)


Windscreen VLT Reading: 82% (front)




Windscreen VLT Reading: 30% (rear)



Front Windows VLT Reading: 78% (left)



Front Windows VLT Reading: 77% (right)



Rear Windows VLT Reading: 30% (left)



Rear Windows VLT Reading: 29% (right)



Rear Quarter Glass VLT Reading: 29% (Left)



Rear Quarter Glass VLT Reading: 28% (Right)



Section B: Observation**Section C: Undertaking by Authorised Inspectors**

We, hereby, verify that we have checked the above-mentioned vehicle on 29/11/21 (date)
and correctly recorded the technical information on this form.

1) Inspector's Name & Signature: Ho Leong Chuan

(with company endorsement)




2) Inspector's Name & Signature: K.K.Lau

MSc,B.ENG(HONS),PE(USA)

(with company endorsement)