

INSPECTION CHECKLIST

Reference no: CS5/TP21012085/Cq

Section A: Vehicle Check


Applicant	VENTURE CARS PTE LTD
Date of Inspection	30/11/2021
Time of Inspection	13:30 HRS
Vehicle Make	TOYOTA
Vehicle Model	YARIS CROSS 1.5XB
Vehicle Model Code	5BA-MXPB10-BHXR-B
Engine Number	M15AY233975
Chassis Number	MXPB103013874
Motor Number (if any)	-
Odometer Reading	14 KM

Wheels	
Front Tyre Size	205/65R16
Rear Tyre Size	205/65R16

Lighting	Yes	No	Remarks
Auto Levelling System		X	
Front Fog Lamp	X		
Rear Fog Lamp		X	
Type of Low Beam	☒ Halogen	☐ LED	☐ HID
Type of High Beam	☒ Halogen	☐ LED	☐ HID

Others	Yes	No	Remarks
Sunroof / Moonroof (if any)		X	
Transmission Type	☐ Manual	☒ Automatic	


Vehicle Identification (VIN) Chassis Plate




Chassis Number Stamping



Engine Number Stamping



Front View



Rear View



Right View



Left View



Engine Compartment




Front Tyre Size




Rear Tyre Size




Instrument Panel



Exhaust System




Exhaust System




Exhaust System



Speedometer



Odometer




Vehicle Light Transmittance (VLT)

Windscreen VLT Reading: 83% (front)



Windscreen VLT Reading: 30% (rear)



Front Windows VLT Reading: 76% (left)




Front Windows VLT Reading: 78% (right)



Rear Windows VLT Reading: 29% (left)



Rear Windows VLT Reading: 29% (right)



Rear Quarter Glass VLT Reading: 28% (Left)



Rear Quarter Glass VLT Reading: 29% (Right)





Section B: Observation

Section C: Undertaking by Authorised Inspectors

We, hereby, verify that we have checked the above-mentioned vehicle on 30/11/21 (date)
and correctly recorded the technical information on this form.

1) Inspector's Name & Signature: Ho Leong Chuan

(with company endorsement)



2) Inspector's Name & Signature: K.K.Lau
MSc,B.ENG(HONS),PE(USA)

(with company endorsement)

