From: Date: 30/11/2021	Veh No: SMT 2/12 M Yr Regn: (4/8/2019)
Estimated Cost:	Type: (Taxi / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /
OD INSTITUTES OD RESTEVATINUT MV	: Truck / Trailer or
To Inspect Vehicle No: SMT 2112 M	Make: BM N 730Li SR c.c 2998
at Workshop m/s Dean Andopro	Colour Grey A/C: Insured / Std / NI / NA
of 160 Sin Aring Dr # 01-14	Sp.Reading 49424 T/Radio: Insured / Std / NI / NA
Insured:	Eng/No: >45856853486208
Policy No.	C/No: WBA7T09-03-8588858
Claims No.	Gen. Cond: Good / Burnt
Sum Insured: Excess:	Sleering: leorder / Jammed / Leaked / Burnt or
(Client's Record)	Brake: order / Jammed / Leaked / Burnt or
Make of Veh:	Modi: NII / STD A/Rim or
	Tyre Size: F: 246/45/19
(Policy Condition)	R: 275/45/79
Remark: The veh had commenced its N/S O/S	BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / TO / SUMI /
repair at the time of inspection.	TOYO / YOKO or
Bal, or Market Value: 397,000/y	Fron! Rear
IDAC Accident Rport: Consistent? : Yes or No	R/Bal. 5 mm R/Bal. 5 mm
GIA / PR Seen: Consistent? : Yes or No	L/Bal. 5 mm L/Bal. 5 mm
Est. Repairs: Yes or No	D.O.A. 23/1/2021 D.O.I. 30/11/2021
Lum Sum: % 3 Val.: Yos or No	Survey held at Dean Autopro
CA / REV / REP. / 24 HRSW	Des. of Damages: 1 Rear / (15) N/S / U/C / Rooftop or
Vehicle: IN/O	
Date: Person Contacted:	The U/C / Chassis frame / Body Structure affected due to collision.
Date / Time Action / Instruction	
Range 15,000/2 -16,000	>
Re commended coris LS \$ 15	5, 600.00 Thuin Mine
Re commended cop 15 LD 71	2, 500.00 Mul
MV 397,000/2	
PV 133,231/2	Talin Sur
NV 263,769/2	30/1/2022
Dotc/Time, File Pass to? Prell. Report	Days Of Repair:
Final Report	Resurvey No. of Trip: Survey Fee:
Date/Time, Filo Return to?	Transportation:
Add F	p-many
2)	: Interview (\$) Photos
Peres format:	: Tech. Invs (\$) Others
Lump Sum/18.1: (3	: Weelend (\$
entials a Mann secures 7	A THEODOGOROUGH PROGRAMMENT OF THE PROGRAMMENT OF T
	TOTAL

Team AutoPro Pte Ltd 160 Sin Ming Dr, #02-12 Sin Ming AutoCity Singapore 575722

Tel: 8269-9999 Email: estimate.tap@gmail.com/teamautopl@gmail.com

SJE:		Vehicle Nos :	SMT 2112 M
Date of Survey :		Model:	BMW 730L1
Date of ReSurvey:	After-Paint:	Year:	2019
Contacts:		Chassis No :	WBA7T02030BS88858

* AGREED Cost Of Repair and Repair Day/s with SJE *

Amount:	Working Day

Nos	DARTE			A STREET, SECTION		2019
	- Acceptance	Qty	100	Unit S\$		TOTAL S\$
1	BONNET	1	\$	2,506.90	100	
2	BONNET LOGO	1	\$	118.60		
3	BONNET LOCK ASSY	2	\$	193.30	\$	√ 386.60
4	BONNET LOCK BRACKET	1	\$	253.40		-253.4 0
5	FRONT BUMPER	1	\$	2,189.60	\$	1501.35 2,189.60
6	FRONT BUMPER SIDE RETANIER UPPER RH	1	\$	84.00	\$	√ 84.00
7	FRONT BUMPER SIDE RETANIER LOWER RH	1	\$	72.60	\$	72.60
8	FRONT BUMPER SIDE CARRIER	1	\$	178.00	\$	100.00 178.00
9	FRONT BUMER BRACKET	2	\$	340.00	\$	-680.00
10	FRONT BUMPER INNER SPONGE	1	\$	289.50	\$	166 - 30 289.50
11	FRONT BUMPER REINFORCEMENT	1	\$	1,100.00	\$	1,100.00
12	FRONT BUMPER REINFORCEMENT BRACKET	2	\$	145.00	\$	290.00
13	FRONT BUMPER LOWER REINFORCEMENT	1	\$	310.60	\$	√ 310.60
14	FRONT BUMPER LOWER GRILLE	1	\$	630.00	\$	500.00 630.00
15	FRONT BUMPER LOWER GRILLE OUTER CHROME	1	\$	180.00	\$	√ 180.00
16	FRONT BUMPER SIDE LOWER GRILLE RH	1	\$	240.00	\$	185,00 240.00
17	FRONT BUMPER SIDE LOWER GRILLE OUTER CHROME RH	1	\$	180.00	\$	V 180.00
18	FRONT BUMPER OUTER CHROME GARNISH RH	1	\$	180.00	\$	V180.00
19	FRONT BUMPER TOW CAP	1	\$	89.00	\$	35.00 89.00
20	FRONT BUMPER PARKING SENSOR	4	\$	210.00		570.00 840.00
21	FRONT GRILLE	2	\$	488.60	\$	-977.20
2	FRONT GRILLE OUTER CHROME	1	\$	345.00	_	220.40 345.00
3	FRONT GRILLE BASE	1	\$	883.90	\$	699.40 883.90
4	FRONT FENDER RH	1	\$			1014.50 1,930.50
5	FRONT FENDER INNER COWLING RH	1	\$	436.40	\$	
	FRONT FENDER INNER AIR DUCTS RH	1	\$	186.00	027	
	RONT SUPPORT PANEL	1	\$		\$	186.00
	RONT SUPPORT PANEL TOP GARNISH	1		1,889.20	\$	1,889.20
	HEADLAMP RH		\$		\$	339.00
	EADLAMP BALLAST RH	1	\$	seeking excess		5947.80 8,470.00
	EADLAMP LOWER BRACKET RH	1	\$	655.00	\$	655.00
	,	1	\$	180.00	\$	180.00
	RONT ENGINE COVER (16Wer) RH	1	\$	248.00	\$	V 248.00
	RONT ABSORBER RH	1	\$	4,100.00	\$.	1026.90 4,100.00
FF	RONT KNUCKLE ARM RH	1	\$	950.00	\$	950.00

35	FRONT KNUCKLE ARM BEARING RH	1	\$ 685.00	\$ 350.00 685.00
	FRONT LOWER ARM RH	1	\$ 595.00	\$ √ 595.00
37	FRONT TRUST ARM RH	1	\$ 415.00	\$ √ 41 5.00

Parts Sub Total:

5%

\$ 17,764.51 34,084.00

Discount

1,704.20 \$ 888.23 32,379.80

PARTS TOTAL: \$

16876.28

. S\$	TOTAL	Unit S\$		Qty	SPECIAL NETT	os.
80.00	\$	80.00	\$	1	SUNDRIES	1
100:00	\$	100.00	\$	1	BONNET SEALANT	2
60:00	30.00	60.00	\$	1	FRONT BUMPER CLIPS	3
60.00	30.00	60.00	\$	1	FRONT BUMPER LOWER GRILLE C/12 5	4
288.00	\$ 120.00	48.00	\$	6	FRONT BUMPER PARKING SENSOR SEALS	5
_60.00	\$	60.00	\$	1	FRONT GRILLE CLIPS	6
_100.00	\$	100.00	\$	1	FRONT FENDER SEALANT	7
 €60.00	\$ 30.00	60.00	\$	1	FRONT FENDER INNER COWLING CLIPS	8
_1,150.00	\$ 200,00	1,150.00	\$	1	FRONT ALLOY RIM LOCAL rapair	9
-580.00	\$	580.00	\$	1	FRONT TYRE	10
2,538.00	\$	ECIAL NETT TOTAL:	SI			

410:00

\$ 60.00 <u>100.00</u> \$ 150.00 450.00
\$ 150.00 450.00
\$ _100.00
\$ 60.00 180.00
\$ 200.00
\$ 200.00 300.00
\$ 10-0'00 300.00
\$ _200.00
\$ 50.00 100.00
\$ 1000-00 1,600.00
\$ -200.00
\$ 600,00 1,600.00
\$ 5,330.00

1630hrz

Toun Uni LKK Auto Consultants hence noting the Repairer of the following:

To resurvey before/after spray painting

To display damaged part(s) during resurvey

Parts prices are subject to confirmation

Third party survey is on a "Without Prejudice" basis

No illegal modification(s) is allowed

 Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature: Date:

Prepared by Eric (8269-9999) Page 2

PARTS TOTAL: \$ 32,379.80 SPECIAL NETT TOTAL: \$ 2,538.00

> LABOUR TOTAL: \$ 5,330.00

GRAND TOTAL:

40,247.80

16,876.28 Parts LS 15,600/2
Tolin Min
30/1/2022 SN 410:00 Labour _ 2240.00 19526-28

@ 200/0 3905.26

> Back to OneMotoring

Enquire PARF/COE Rebate for Registered Vehicle

Vehicle Owner Particulars	THE RESIDENCE OF THE PARTY OF THE PARTY OF THE PARTY.
Owner ID Type:	Singapore NRIC
Owner ID:	064E
Vehicle Details	
Vehicle No.:	SMT2112M
Vehicle to be Exported:	No
Intended Deregistration Date:	30 Jan 2022
Vehicle Make:	B.M.W.
Vehicle Model:	730LI SR ADAPTIVE LED HL RCP HUD NAV
Primary Colour:	Grey
Manufacturing Year:	2019
Engine No.:	24585685B48B20B
Chassis No.:	WBA7T02030BS88858
Maximum Power Output:	195.0 kW (261 bhp)
Open Market Value:	\$87,439.00
Original Registration Date:	14 Aug 2019
First Registration Date:	14 Aug 2019
Transfer Count:	1
Actual ARF Paid: Intended PARF Rebate Details	\$129,391.00
PARF Eligibility:	Yes
PARF Eligibility Expiry Date:	13 Aug 2029
PARF Rebate Amount: Intended COE Rebate Details	\$97,043.00
COE Expiry Date:	13 Aug 2029
COE Category:	E - Open - all except motorcycle
COE Period(Years):	10
QP Paid:	\$52,502.00
COE Rebate Amount:	\$36,188.00
Total Rebate Amount:	\$133,231.00

The information contained herein is correct as at 30 Jan 2022

OK

MV 397,000 pr PV 133,231 pr NV 263,769 pr

Joun Muic 30/1/2022

New Cars Rental Cars Articles Forum Resources Sell My Car Directory Products Insurance 新春猛片馬拉松 CHINESE NEW YEAR MOVIE M 2018 BMW X1 SDrive 2.01 M-Sport. Selling Cheap 132800 Post an Advertisement Sell it yourself! Advertise it at just \$68 until it's SOLD! Speedo Motoring StarAd YONG LEE SENG MOTOR PTE LTD Ways of Selling Post an Ad Advertiser Login ✓ 20 results/page ✓ Sort by Date Posted Browse by Category Advanced Search 1 vehicles BMW 740Li Mileage Status Eng Cap Depreciation Price 2019 Апу Available Search Selection **BMW 740Li** 27-Dec-2019 2,998 cc 23,000 km Available \$40,780 /vr \$398,000 BMW 7 Series 740Li M-Sport Facelift Model. 1 Owner! Bank Loan From 1.68% Or In-House Loan Available. 5 Years PML Warranty Till Dec 2024. Fully Maintained By PML. Needless To Worry Purchasing This Unit. Low Mileage. Contact Us Now To Find Out More! Viewings Based On Appointment Only! CONSTONMENT Posted: 08-Jan-2022 Tags: 2019 BMW 740LI, BMW 740LI, BMW, 740LI Save this search criteria, to get email alerts whenever a match is found. Depreciation Eng Cap Mileage Veh Type 20 v results/page For old advertisements, view Expired ads Home New Cars Used Cars Rental Cars Sell My Car | Directory | Products | Insurance | Article | Forum | Resources

sgCarMart is the number one car classifieds for parallel import cars, Toyota, Honda, Nissan, Mitsubishi & BMW. There are plenty of cars for sale, from vans, trucks, sedan cars, luxury cars, sports cars or stationwagons, SUV, MPV, hatchback, to COE cars & OPC cars. You can also buy from a car auction, look up car loans, financial services, low mileage cars, car brands, carpark rates & car insurance. Find buy used BMW, BMW Singapore, used BMW Singapore, used BMW, used vehicles Singapore or even buy used BMW Singapore. We have new car dealers comprising parallel importers, authorised car dealers, and used car dealers on our site. Find new car price lists, new car launches and new car promotions. Visit our partner sites for job openings for Singapore jobs, real estate, mover, car performance parts, car discussion, forum discussion, commercial vehicle leasing & COE results.

All prices and other information displayed on sgCarMart.com are gathered from sources and based on algorithms that are believed by sgCarMart.com to be reliable, but no assurance can be given that this information is accurate, complete or current, sgCarMart.com does not assume any responsibility for errors or omissions or warrant the accuracy of this information.

Follow sgCarMart.com

About Us | Careers | Contact Us | Sitemap | Terms of Service | Privacy Policy | Personal Data Protection Statement ©2004-2022 sqCarMart, Singapore. All rights reserved,



BMW: 7 Series - G11/G12 (2015 -): Rear Wheel Drive Models: without AFS (Active Front Steering): Series (Air Suspension): 18" Wheel 4-Wheel Total Alignment

Front: Left

Actual	Before	Specified Range
-0°48'	-0°48'	-0°42' 0°18'
4°36'	4°36'	
-0°01'	-0°01'	0°04' 0°08'
11°46'	11°46'	
10°58'	10°58'	
	100	-2°06' -1°06'

Camber Caster Toe SAI Included Angle Turning Angle Diff.

Front : Right				
Actual	Before	Specified Range		
-2°48'	-2°48'	-0°42' 0°18'		
4°37'	4°37'			
-0°20'	-0°20'	0°04' 0°08'		
13°50'	13°50'			
11°02'	11°02'			
		-2°06' -1°06'		
11 02	11 02	-2°06' -1°06'		

Front

Cross Camber Cross Caster Cross SAI **Total Toe** Cross Turn Diff.

Actual	Before	Specified Range
2°00'	2°00'	-0°30' 0°30'
-0°01'	-0°01'	-0°30' 0°30'
-2°04'	-2°04'	
-0°21'	-0°21'	0°00' 0°24'
	7777	-0°12' 0°12'

Rear: Left

Actual	Before	Specified Range
-1°40'	-1°40'	-1°55' -1°05'
0°06'	0°06'	0°06' 0°10'

Camber Toe

Trout Trager			
Actual	Before	Specified Range	
-1°30'	-1°30'	-1°55' -1°05'	
0°08°	0°08'	0°06' 0°10'	

Rear : Right

Rear

Cross Camber **Total Toe** Thrust Angle

Actual	Before	Specified Range
-0°10'	-0°10'	-0°30' 0°30'
0°15'	0°15'	0°04' 0°28'
-0°01'	-0°01'	-0°12' 0°12'

Resurvey 1/12/2021 1700 hrs

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

SD0821BT0001 / Ding Auto Pte Ltd ENTRY DATE & TIME: 29/11/2021 15:46 (SGT) SUBMITTED BY: Nora/Rena VERSION: 1 (29/11/2021 15:46 (SGT))



SINGAPORE ACCIDENT STATEMENT

Please report <u>correctly</u> the details of the accident to speed up the claims process.

2. This Form must be completed by the Policyholder and/or the Authorised Driver
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or witholding of material facts may allow insurance companies to repudiate policy liability.

4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.

6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.

7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid. Any false reporting may be referred to the Police for investigation.

ACCIDENT STATEMENT

29/11/2021 15:46 (SGT) Date of Submission 23/11/2021 19:00 (SGT) Date of Accident Singapore Exact Location of Accident JUNCTION OF JALAN AWANG AND JALAN EUNOS Additional Location Information Country/State of Loss

DETAILS OF OWN VEHICLE

Vehicle Registration Number SMT2112M

INSURED/POLICYHOLDER

No Is company? Name Of Registered Owner CHEAH KIM HONG NRIC No SXXXX064E CHEAHKIMHONG@GMAIL.COM Email Address (Phone) +65-97348302 Mobile Phone No +65-97348302 Alternative Phone No

VEHICLE PARTICULARS

BMW Manufacturer Model 730li Variant Exact purpose for which vehicle was being used at time of Private use accident

Are you claiming under your own insurance policy for repair to

your vehicle? Vehicle Category

Transmission

CC

No - Claiming third party

Private car

Auto 2979

INSURANCE COMPANY

Cover Note Number

Name of Insurance Company Type of Coverage Fleet Policy No Policy Number

Allianz Insurance Singapore Pte. Ltd.

Comprehensive

SP2000676575-01 SP2000676575-01

DRIVER

Name of Driver NRIC No

CHEAH KIM HONG SXXXX064E



Date Of Birth	21/12/1960
Occupation	Indoor
Date Of Driving Pass	08/05/1979
Driving experience	
Gender	Male
Mobile Number	
Alt. Phone Number	+65-97348302
Email Address	CHEAHKIMHONG@GMAIL.COM
Address	42 LENGKONG TUJOH
Address complement	
Postcode	417394
Is the driver the policyholder?	Yes
If No, Relationship of the Driver with the Insured	
Does Driver Own Other Vehicles?	
Vehicle Registration Number of Other Vehicle Owned by Driver	
vehicle Registration Number of Other Vehicle Owned by Driver	
Insurance Company of Other Vehicle Owned by Driver	
GENERAL INFORMATION OF THE ACCIDENT	
Type of Accident	Collision - Change/cross lane
Weather Conditions	
Road Surface	Dry
Nodu Suriace	bly
OTHER INFORMATION	
Was any foreign vehicle involved in the accident?	No
Number of vehicles involved in the accident	2
Was anybody injured in the Accident?	
Was any injured conveyed to hospital by ambulance?	
Was any other vehicle or property damaged?	
Number of Passengers (Including Driver)	
Has the driver been approached by unknown person(s)	
soliciting/offering accident claims assistance?	No
STANDARD STA	
PASSENGER 1	
Name	MDM SIM
Gender	Female
DETAILS OF POLICE ACTION	
Was the accident reported to the police?	No
Was notice of intended Prosecution given?	No
If yes, against whom?	
CIRCUMSTANCES OF ACCIDENT	
REFER TO SKETCH PLAN	
ATTACHMENT(S)	
Are accident photos available for attachment?	No
Was there any video captured by Car Camera?	No
Was there any audio recorded?	No
Tras dicio dily addio recorded :	
DETAILS OF OTHE	R VEHICLE PROPERTY 1
Vehicle Registration Number	GBF6629S
Vehicle Manufacturer	
Vehicle Model	
Vehicle Variant	

Commercial vehicle

Vehicle Category

Vehicle Variant Vehicle Colour

Name of Driver	
NRIC No.	TOH JOO HENG
NRIC No Contact Number Address	SXXXX488J (Phone) +65-98232746
Address complement	(, ,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,
Address complement	
Postcode	
Insurance Company Name	
Insurance Company Name	
Nature Of Damage	
Details of property damaged in accident	
No. Of Passenger (Including Driver)	

Describe Circumstances of the Accident
On the stared date and time, I was travelling along the stated vienue.
Both my vehicle and Vehicle B who turning out from Jalan Awary Into
Jahan Euros. I way at the extreme left force and suddenly Vehrele B
swerved his vehicle to my have and collished onto my vehicle.
After the collector, both of us alighted from our vehicles and exchanged our.
particulars. The driver of vehicle B then applicated to me and admitted A
was his mistake by sworking to my love and collected auto my vehicle due to
con unknown metarble which was travelling smaght along Jalan Euros.
- ALE KAN

Declaration

IWe declare the foregoing particulars are true in every respect.

Policyholder's Signature / Date & Time

Driver's Signature (1 driver is not the policyholder) / Date & Time

Witnessed by Reporting Centre Persophel

SKETCH PLAN

IMPORTANT NOTICE

- 1. Please report correctly the details of the accident to speed up the claims process.
- 2. This Formmust be completed by the Policyholder and/or the Authorised Driver.
- Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
- 4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
- 5. Any false reporting may be referred to the Police for investigation.
- 6. The report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
- 7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.
- 8. Consent under the Personal Data Protection Act (PDPA)

I understand, acknowledge, agree and consent that :

- (a) My insurer, my workshop and the General Insurance Association of Singapore ("GIA") may/are permitted to collect, use, disclose and/or process my personal data/personal information set out in this [form] and any other personal information provided by me or possessed by my insurer (collectively the "Personal Information") and disclose and transfer such Personal Information to all insurer(s) who have insured vehicle(s) involved in this accident (all insurer(s) who have insured vehicle(s) involved in this accident shall be collectively referred to as the "Insurers"), the insurers' law yers/law firms, the Monetary Authority of Singapore and any relevant government agency/authority (such as the police), for the purpose(s) of :
- (i) processing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigations relating to the claims:
- (ii) investigating the accident and/or my claims;
- (iii) carrying out and/or dealing with my instructions or responding to any enquiries by me;
- (iv) administering my claims (including the mailing of correspondence, statements, invoices, reports or notices to me, which could involve disclosure of certain personal data about me to bring about delivery of the same as well as on the external cover of envelopes/mail packages); and/or
- (v) complying with applicable law in administering, processing, handling and/or dealing with my claims.

(collectively the "Purposes")

(b) all insurer(s) who have insured vehicle(s) involved in this accident and the Insurers' law yers/law firms, may/are permitted to collect, use, disclose and/or process my Personal Information for one or more of the above Purposes; and

(c) my Personal Information may/can be disclosed by any of the Insurers and/or GIA to their third party service providers or agents (including their law yers/law firms), which may be sited outside of Singapore, for one or more of the above Purposes

Policyholder's Signature / Date & Time

Driver's Signature of driver is not the policyholder) / Date & Time

Personne

Witnessed by Reporting Centre

Sketch Plan

Dalan Eunos A 2 Veh Al SMT 21/2 M x veh B1, B2, B3. 400 GBF 66295 4 + (0) Unknown meter bike BI Jalan