

|   |   |   |        |   |   |   |   |      |   |   |   |   |             |
|---|---|---|--------|---|---|---|---|------|---|---|---|---|-------------|
| ⏪ | < | 1 | of 2 ? | > | ⏩ | ↺ | ↻ | 100% | ▼ | 📄 | ✓ | 🖨 | Find   Next |
|---|---|---|--------|---|---|---|---|------|---|---|---|---|-------------|



## LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

| Affiliated to Federation Internationale Des Experts En Automobile  |   |                          |                |
|--|---|--------------------------|----------------|
| SOMPO INSURANCE SINGAPORE PL   |   | Ref: CS/SMO21012133/Kvf3 |                |
| 50 RAFFLES PLACE #03-03  |   | Date: 30/11/2021         |                |
| SINGAPORE LAND TOWERSINGAPORE 048623   |   | Code: SMO                |                |
| <b>1. Policy Particulars :- OWN DAMAGE</b>   |   |                          |                |
| <b>Insured Veh.</b>  | <b>Veh. Inspected</b>   | SJZ 1138A                |                |
| <b>Policy No.</b>  | <b>Coverage (\$)</b>  | 0.00                     |                |
| <b>Claim No.</b> CMTD2103517/LOR   | <b>Excess (\$)</b>  | 0.00                     |                |
| <b>Assign From</b> GRACE TEO   | <b>Assign Date</b>  | 30/11/2021               |                |
| <b>2. Vehicle Particulars &amp; Condition</b>  |   |                          |                |
| <b>Make &amp; Model</b>  | <b>c.c</b>  | 0                        |                |
| <b>Engine No.</b> HIDDEN   | <b>Year of Reg.</b>   |                          |                |
| <b>Chassis No.</b>   | <b>Colour</b>   |                          |                |
| <b>Odometer</b> -  | <b>Steering</b>   |                          |                |
| <b>Brakes</b>  | <b>Modification</b>   |                          |                |
| <b>General</b>   |   |                          |                |
| <b>3. Conditions of Tyres</b>  |   |                          |                |
|  | <b>Size</b>   | <b>Make</b>              | <b>Balance</b> |
| <b>R/H Front Tyre</b>  |   |                          | mm             |
| <b>L/H Front Tyre</b>  |   |                          | mm             |
| <b>R/H Rear Tyre</b>   |   |                          | mm             |
| <b>L/H Rear Tyre</b>   |   |                          | mm             |
| <b>4. Description of Damages</b>   |   |                          |                |
|  |   |                          |                |
| <b>5. General Information</b>  |   |                          |                |
| <b>Accident Date</b> 27/11/2021  | <b>Inspection Date</b>  | 30/11/2021               |                |
| <b>Survey held at</b>  | ACCORD AUTO SERVICES PTE LTD<br>10 ANG MO KIO INDUSTRIAL PARK<br>2A AMK AUTO POINT #03-11<br>SINGAPORE 568047 |                          |                |
| <b>5a. Remarks</b>   |   |                          |                |
| A)THE MARKET VALUE IS S\$------(EST. AVERAGE)<br>B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE AUTHORISED REPAIRS. |   |                          |                |