

(08/11/13) wef
ASS. REC. BY: *[Signature]*

REF:

CC4/LPC 21012148/Rips3

9035

ASSIGNMENT

From: _____ Date: _____
Estimated Cost: _____
OD / TP / WS / TP RES / OD RES / EVA / INV / MV
To Inspect Vehicle No: **SMD 1450C**
at Workshop m/s **AUTO INSURE**
of **6, MARILYN LANE**
Insured: **LPC**
Policy No. _____
Claims No. _____
Sum Insured: _____ Excess: _____
(Client's Record)
Make of Veh: _____

(Policy Condition)

Remark: The veh had commenced its
repair at the time of inspection.

N/S	O/S

Bal. or Market Value: **74K**
IDAC Accident Rpt: Consistent? : Yes or No
GIA / PR Seen: Consistent? : Yes or No
Est. Repairs: days Res.: Yes or No
Lum Sum: % 3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Date: _____ Person Contacted: _____ Vehicle: IN / OUT

Veh No: **SMD 1450C** Yr Regn: **2016 / MAR**
Type: **M.Car** / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /
Truck / Trailer or

Make: **Volkswagen CC 210TSI** c.c **1984**
Colour: **Blue** A/C: **Insured / Std / NI / NA**
Sp.Reading: **104368** T/Radio: **Insured / Std / NI / NA**
Eng/No: _____

C/No: **WVWZZZ3CZ G651348**

Gen. Cond: **Good** / Fair / Poor / Burnt

Steering: **In order** / Jammed / Leaked / Burnt or

Brake: **In order** / Jammed / Leaked / Burnt or

Modi: **Nil** / S/Rim / STD A/Rim or

Tyre Size: F: **245/40R18**
R: **245/40R18**

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /
TOYO / **YOKO** or

Front		Rear	
R/Bal.	6 mm	R/Bal.	6 mm
L/Bal.	6 mm	L/Bal.	6 mm
D.O.A.	30/11/21	D.O.I.	01/12/21

Survey held at **AUTO INSURE**

Des. of Damages: **Frt** / Rear / O/S / N/S / U/C / Rooftop or

FRT O/S

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time Action / Instruction

REPAIR LIMIT - 22K

informed w/ship agreed at 22k

Date/Time, File Pass to?

☐ : Preli. Report
☐ : Final Report

1)

Date/Time, File Return to?

2)

Days Of Repair:

Resurvey No. of Trip:

Survey Fee:

Transportation:

Report Format :

Lump Sum / I.B.I.: (\$

Add Fee: ☐ : Site Insp (\$

☐ : Interview (\$

☐ : Tech. Invs (\$

☐ : Weekend (\$

) S + RS, SI

) Photos

) Others

> Back to OneMotoring

Enquire PARF/COE Rebate for Registered Vehicle

Vehicle Owner Particulars	
Owner ID Type:	Singapore NRIC
Owner ID:	903J
Vehicle Details	
Vehicle No.:	SMD1450C
Vehicle to be Exported:	No
Intended Deregistration Date:	01 Dec 2021
Vehicle Make:	VOLKSWAGEN
Vehicle Model:	CC 2.0 TSI 3584P6
Primary Colour:	Blue
Manufacturing Year:	2016
Engine No.:	CCZ492288
Chassis No.:	WWZZZ3CZGE513148
Maximum Power Output:	155.0 kW (207 bhp)
Open Market Value:	\$34,717.00
Original Registration Date:	18 Mar 2016
First Registration Date:	18 Mar 2016
Transfer Count:	1
Actual ARF Paid:	\$40,604.00
Intended PARF Rebate Details	
PARF Eligibility:	Yes
PARF Eligibility Expiry Date:	17 Mar 2026
PARF Rebate Amount:	\$28,422.00
Intended COE Rebate Details	
COE Expiry Date:	17 Mar 2026
COE Category:	B - Car above 1600cc or 97kW (130bhp)
COE Period(Years):	10
QP Paid:	\$55,001.00
COE Rebate Amount:	\$23,611.00
Total Rebate Amount:	\$52,033.00

The information contained herein is correct as at 01 Dec 2021

OK

Volkswagen CC 2.0A TSI R-Line

[Overview](#)

[Financial](#)

[Accessories](#)

[Similar](#)

[Research](#)

[Photos](#)

[Map](#)

Price

\$75,800

Depreciation

\$12,540 /yr

Reg Date

13-Apr-2016

[View models with similar depre](#)

(4yrs 4mths 10days COE left)

Mileage

68,000 km (12.1k /yr)

Manufactured

2015

Road Tax

\$1,194 /yr

Transmission

Auto

Dereg Value

\$50,321 as of today (change)

OMV

\$35,878

COE

\$48,002

ARF

\$42,230

Engine Cap

1,984 cc

Power

155.0 kW (207 bhp)

Curb Weight

1,535 kg

No. of Owners

3

Type of Vehicle

Luxury Sedan