



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile				
TAN CHIN HOE & CO 24 RAFFLES PLACE #24-01 CLIFFORD CENTRESINGAPORE 048621			Ref: CS/LAW21012162/Dvf3e2	
			Date: 23/02/2022	
			Code: L128	
1. Policy Particulars :- THIRD PARTY CLAIM (RESURVEY INSPECTION)				
	Insured Veh.	GBE 2499G	Veh. Inspected	SKS 7309J (SKE 666Y)
	Policy No.		Coverage (\$)	0.00
	Claim No.	RT/EK/208/2018/zx	Excess (\$)	0.00
	Assign From	ANITA AWI	Assign Date	26/11/2021
2. Vehicle Particulars & Condition				
	Make & Model	NISSAN GT-R	c.c	3799
	Engine No.	150994	Year of Reg.	2010
	Chassis No.	R35004341	Colour	PURPLE
	Odometer	-	Steering	IN ORDER
	Brakes	IN ORDER	Modification	SPORTS RIM
	General	GOOD		
3. Conditions of Tyres				
		Size	Make	Balance
	R/H Front Tyre	255/40 R20	BRIDGESTONE	4 mm
	L/H Front Tyre	255/40 R20	BRIDGESTONE	4 mm
	R/H Rear Tyre	285/35 R20	BRIDGESTONE	4 mm
	L/H Rear Tyre	285/35 R20	BRIDGESTONE	4 mm
4. Description of Damages				
	THE VEHICLE HAD COMPLETED ITS REPAIR WORKS. REPAIR CONDITION SEE DETAILS.			
5. General Information				
	Accident Date	28/07/2017	Inspection Date	06/12/2021
	Survey held at	66 Upper Serangoon View Singapore 533885.		
	Repairer	ALDRIN AUTOMOTIVE		
5a. Remarks				
	A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.			
5b. Estimate Days of Repair				
	ESTIMATED NORMAL PERIOD FOR REPAIR:		6 Working Days	