

RESTRICTED

ANNEX D

PHOTOGRAPHS OF INCIDENT VEHICLE



D-1  
RESTRICTED

RESTRICTED



Close Up View of MID41573 LHS



Close Up View of MID41573 LHS



Close up view of Civilian Lorry GBK5217C



Close up view of Civilian Lorry GBK5217C

D-2  
RESTRICTED

RESTRICTED


ANNEX C

SCHEMATIC DIAGRAM OF INCIDENT

Figure C-1 – LCP HON MING driving MID41573 towards the parking lot along the Blk 26 loading bay



Figure C-2 – LCP HON MING positioned MID41573 at an angle, and proceeded to perform his parking drill



C-1  
RESTRICTED

RESTRICTED

Figure C-3 – LCP HON MING sounded the horn of MID41573 before proceeding to reverse



Figure C-4 – GBK5217C proceeded to reverse upon hearing the horn, and came into contact with MID41573




C-2  
RESTRICTED

RESTRICTED

ANNEX E

## STATEMENT OF LCP MOK HON MING (TO) (SAF 1201)

SINGAPORE ARMED FORCES STATEMENT OF DRIVER/WITNESS					
STATEMENT OF	LCP MOK HON MING			ALIASES	REL
AMIC NO.	XXXXXX67F	AGE	22	MALE/FEMALE	MALE
EMPLOYMENT	NSP	DRIVING LICENSE NO		NATIONALITY	SINGAPOREAN
DIALECT		LANGUAGE SPOKEN		TEL NO	
ADDRESS					
INTERPRETED BY		RANK	TIME	DATE	SIGN
RECORDED BY		RANK	TIME	DATE	SIGN
<p>I, XXXXX167F LCP MOK HON MING, on 200921 around 1315hrs was reporting to the loading bay in Clementi Camp for my detail as following the Point of Contact's (POC) instruction. I drove the GP car out of MT Line and approached the loading bay around 1315hrs, that was when I saw a lorry parked with hazard light, in between the Second class 3 lot of the three class 3 lots available. I approached slowly and maneuvered my vehicle slightly facing towards the right side (around 2 o'clock direction) on the right side of the lorry, rear of my vehicle slightly facing the parking lot that I am aiming to park into. I assessed there was sufficient space for me to maneuver and park my vehicle. I got down and did my reversing drill. Afterwards, following the reversing drill, I horn one time before reversing. As I was reversing slowly and carefully into the parking lot, the lorry suddenly started reversing too. Almost half my vehicle already backed up behind the lorry and going into the parking lot already. The lorry suddenly reverse and collided into the left rear side of my vehicle. During the event, I saw it coming and immediately blared my horn. Before the actually collided with my vehicle, but the lorry still continued to reverse. I kept blaring the horn to warn him that I am behind him but the lorry did not stop reversing and eventually collided with my vehicle. Afterwards, when the lorry moved forward and situation was safe, I got out of my vehicle. I talked to the lorry driver and he asked me why did I horn, and he told me that I should not have horned. I told him that I am driving a military vehicle and it is my reversing drill. He told me that because of my horn, he thought that the vehicle that was already in the parking lot that his lorry was blocking is trying to move out that's why he moved his vehicle. Then I asked him if he checked his mirror before he reversed. He told me that he checked rear mirror but can't see my vehicle, without mentioning if checked side mirror, and then he told me he just did eye surgery and could not see clearly. In conclusion, the lorry was parked at a double yellowing zig line with hazard light on but blocking the path way of other vehicle and he did not checked clear before reversing.</p>					
DATE	200921	SIGNATURE OF DRIVER/WITNESS			
<p>All statements and further statements are so true and dated. Witness will be re-warned immediately prior to the recording of further statements. Statements and further statements will be signed by the Recording Officer and Interpreter. Statements of witness must be signed by the Witness.</p>					
SAF 1201					

E-1  
RESTRICTED

RESTRICTED

ANNEX IPOLICE STATEMENT

**SINGAPORE  
POLICE FORCE**



D/20210920/7036

1 of 3

POLICE REPORT (NP259)

Report No. D/20210920/7036

Police Station Of Origin  
Clementi Division HQ  
20 Clementi Avenue 5 SINGAPORE 129050  
Tel No:1800-7740000

Date/Time Report Made 20/09/2021 21:12	Vide Report No.	Station Diary No.
Name Of Informant MOK HON MING	Address [REDACTED]	
ID Type / ID No. NRIC NO / S [REDACTED] 667F	Contact No. Home/Office: Mobile: 97571455	
Nationality SINGAPORE CITIZEN	Email Address [REDACTED]	
Occupation National Service Full Time	Sex Male	Age 22
Institution/School Name	Date of Birth 14/08/1999	Race Chinese
Date/Time Of Incident 20/09/2021 13:10 - 20/09/2021 13:30	Location Of Incident 26 CLEMENTI LOOP #--- CLEMENTI CAMP SINGAPORE 129817	

Brief details.

I LCP Mok Hon Ming, on 200921, around 1315, I was driving a GP car (MID 41573) reporting for my detail at Clementi camp block 26. When I reached the road behind block 26, I saw a lorry (GBK5217C) with hazard light parked in between one of the 3 available parking lot, which was double yellow zig zag lines. It is parked right in front of the lot that I wanted to park in, but he is not blocking my way. So I proceeded with caution and did my reversing drill by walking one round around my vehicle ensuring that there are no obstruction or safety hazards in my vehicle's way, and proceeded with my parking. As per

Signature Of Officer Recording The Report: Not applicable	Signature Of Informant: The identity of the person making this report has been authenticated by Singpass. No signature is required.
Signature Of Interpreter: Not applicable	Date/Time: 20/09/2021 21:12
Officer In-Charge Of Case:	Classification Of Case:

I-1  
RESTRICTED

RESTRICTED


**SINGAPORE  
POLICE FORCE**


D/20210920/7036

2 of 3

POLICE REPORT (NP289)

CONTINUATION OF REPORT

Report No. D/20210920/7036

SAF SOP, military vehicles must hon before reversing to alert anybody who may not noticed my vehicle. After I honed, I reversed and did my parking with caution. At this moment, all of a sudden I saw the lorry started reversing and I immediately stopped my vehicle and blast my horn. The lorry did not stopped despite hearing my horn, so I repeatedly blasted my horn to alert him. However, he still continued reversing and collided into my vehicle.

No personnel was injured in this case.

<b>Subjects Involved</b>			
<b>Suspect</b>			
Person Name	NG KIAN ANN		
ID Type	NRIC NO	ID No	S-573C
Gender	Male	Race	Chinese
Mobile No	[REDACTED]		
<b>Victim</b>			
Person Name	MOK HON MING		
ID Type	NRIC NO	ID No	S-667F
Gender	Male	Age	22
Race	Chinese	Language	English
Occupation	National Service Full Time	Address	[REDACTED]
Mobile No	[REDACTED]	Is Informant A	Yes
		Victim?	

Signature Of Officer Recording The Report: Not applicable	Signature Of Informant: The identity of the person making this report has been authenticated by Singpass. No signature is required.
Signature Of Interpreter: Not applicable	Date/Time: 20/09/2021 21:12
Officer In-Charge Of Case:	Classification Of Case:

 I-2  
 RESTRICTED

RESTRICTED



SINGAPORE  
POLICE FORCE



0/20210920/7036

3 of 3

POLICE REPORT (NP299)

CONTINUATION OF REPORT

Report No. 0/20210920/7036

Person Name	MOK HON MING (Informant)
-------------	--------------------------

Signature Of Officer Recording The Report: Not applicable	Signature Of Informant: The identity of the person making this report has been authenticated by Singpass. No signature is required.
Signature Of Interpreter: Not applicable	Date/Time: 20/09/2021 21:12
Officer In-Charge Of Case:	Classification Of Case:

I-3  
RESTRICTED