



Service Request Details

Claim

S1M03MN5

Reference

CS3/ASM21012193/R1vy3 

Loss Date

20 November 2021

Vendor Name

LKK AUTO CONSULTANTS PTE LTD (TP)

Type of Loss

Third Party Vehicle Damage

Report Date

24 Nov 2021 6:48:00 PM

Request Date

30 November 2021

Due Date

1 December 2022

Services

Standard workshop survey

Actions

Next Step

Finish the work

Complete Work

Vehicle Information

Incident Vehicle Registration #
SMR4588X

Make
TPVD Honda

Model
Fit

Service Address

51 Ubi Avenue 1, #01-25, , , 408933

Primary Contact/Insured

COMFORT TRANSPORTATION PTE LTD
383 SIN MING DRIVE, 575717, Singapore
65551188

Claim Handler

KOH Janice

janice.kohlc@axa.com.sg

Additional Instructions

WS : Lim Motor Pte Ltd CDGE

Messages1

Invoices

History

Documents

Assessment

Metrics

Notes

New Message

TYPE




SUBJECT

IA (PRS) SUBMITTED FOR SMR 4588X

BODY

Dear Janice, Please be informed that IA (PRS) subm...



TYPE

2/12/21 9:04 AM

SENT

KOH Janice

FROM

Re:RE: Re:S1M03MN5

SUBJECT

Morn. email send and cc lkk in as well

BODY



TYPE

1/12/21 7:23 PM

SENT

KOH Janice


FROM

Re:RE: Re:S1M03MN5

SUBJECT

hi they will be engaging independent surveyor for ...

BODY



TYPE

30/11/21 5:05 PM

SENT

LKK AUTO CONSULTANTS PTE LTD (TP)


FROM

RE: Re:S1M03MN5

SUBJECT

Dear Janice, Workshop would like to request your s...

BODY



TYPE

30/11/21 3:29 PM

SENT

KOH Janice


FROM

Re:S1M03MN5

SUBJECT

HI yan, Axel was the one who had survey yest howev...

BODY





FROM

LKK AUTO CONSULTANTS PTE LTD (TP)

SUBJECT

S1M03MN5

BODY

Dear Janice, We would like to check as we have con...

