

LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

	Affiliated to Federation Internationale Des Experts En Automobile					
	SOMPO INSURAN	CE SINGAPORE PL	F	Ref:	CS/SMO21012196/Atf3n2	
	50 RAFFLES PLAC SINGAPORE LAND	E #03-03 O TOWERSINGAPORE 048623	[Date:	17/01/2022	
			(Code:	SMO	
1.	Policy Particulars :- THIRD PARTY CLAIM					
l	Insured Veh.	SDJ 644S	Veh. Inspected		SJX 2054L	
I	Policy No.		Coverage (\$)		0.00	
	Claim No.	CMTD2103544/THE	Excess (\$)		0.00	
	Assign From	GRACE TEO	Assign Date		01/12/2021	
2. Vehicle Particulars & Condition						
	Make & Model	TOYOTA VIOS	c.c		1497	
I	Engine No.	HIDDEN	Year of Reg.		2010	
	Chassis No.	MR053HY9305165582	Colour		BLACK	
	Odometer	134688 KM	Steering		IN ORDER	
	Brakes	IN ORDER	Modification		SPORTS RIM	
(General	GOOD				
3. Conditions of Tyres						
		Size	Make		Balance	
I	R/H Front Tyre	195/55 R15	WEST LAKE		6 mm	
I	L/H Front Tyre	195/55 R15	WEST LAKE		6 mm	
I	R/H Rear Tyre	195/55 R15	WEST LAKE		6 mm	
I	L/H Rear Tyre	195/55 R15	WEST LAKE		6 mm	
4.	Description of Damages					
-	THE VEHICLE SUSTAINED DAMAGES AT THE REAR PORTION.					
	DAMAGES SEE DETAILS.					
5.	General Information					
4	Accident Date	01/12/2021	Inspection Date	!	01/12/2021	
	Survey held at	SM AUTOMOTIVE				
	BLK C, 1 KAKI BUKIT AVENUE 6 #01-43 SINGAPORE 417883					
5a.	Remarks					
/ E	A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.					
5b.	Estimate Days of Repair					
E	ESTIMATED NORMAL PERIOD FOR REPAIR: 6 Working Days					