

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CS/CTI21012204/KTY3E2

Date: 18/01/2022

REFERENCE

Handling Insurer: China Taiping Insurance (Singapore) Pte. Ltd. Policy No: DMPCSNW00200002100
Claimant Vehicle No : GBG6982R **Insured Vehicle No :** SJJ956X
Date of Loss: 25/11/2021 Nature of Claim: TP Claim No: SNM21D206925/C02/TOHHS

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: **GBG6982R**
Make & Model: NISSAN NV200, 1.5 (A) Engine No: K9KC400D057296
Reg. Date: 29/09/2017 (Man. Year: 2017) Chassis No: VSKYBAM20Z0145964
Colour: White Odometer: 131885 km
Engine Capacity: 1461 cc
Market Value/New Car Price: N/A
Sum Insured (S\$): **Market Value/New Car Price**

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable): Yes Footbrake (Serviceable): Yes
Handbrake (Serviceable): Yes Engine Modification: No Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size: 175/70 R14 Rear Tyre Size: 175/70 R14
Front Left Side: Kenda 9 mm Rear Left Side: APLUS 5 mm
Front Right Side: Kenda 9 mm Rear Right Side: APLUS 5 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	1,325.00	1,325.00	0.00	0.00
Miscellaneous Items	440.00	300.00	140.00	31.82
Labour	264.60	222.60	42.00	15.87
Paintwork Labour	314.42	314.42	0.00	0.00
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	2,344.02	2,162.02	182.00	7.76
Approved Total (Overridden) (S\$)		1,700.00		
(S\$)	2,344.02	1,700.00	644.02	27.48
+ GST 7.00/7.00% (S\$)	164.08	119.00	45.08	27.47
Nett Amount (S\$)	2,508.10	1,819.00	689.10	27.47

INSPECTION

Date of Assignment: 01/12/2021 Present Location: S & H Motor Pte Ltd (Sin Ming)
Date Inspected: 14/12/2021 Inspected At: S & H Motor Pte Ltd (Sin Ming)
Estimated Period of Repair: 4.0 days 160 Sin Ming Drive #07-02, Sin Ming AutoCity
Singapore 575722

Adjuster: KENNETH KONG

Manager: DENISE TAY KWEE CHENG

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Reference		
Part Source:	(Last Synchronised: 18 Jan 2022)	
Parts:	N/A	NISSAN NV200 1.5 (A) (Model not available in database)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for GBG6982R)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*parts		1,325.00 F	*1,325.00 F
Total Parts (S\$)						1,325.00

F=Franchise part.

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

No	Qty	Particulars	Repairer's	Amount
<u>Miscellaneous Items</u>				
1	1	Misc	440.00	300.00
Sub Total (\$\$)			440.00	300.00

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<u>Paintwork Labour</u>				
1	Labour for paintwork	New	314.42	314.42
<u>Labour Items</u>				
2	Labour for panel/mechanical	New	264.60	222.60
Gross Labour Cost (\$\$)			579.02	537.02

Report was unsubmitted during this print-out.

< END OF ESTIMATES >