

LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 1

PRE-REPAIR INSPECTION REPORT						
	SOMPO INSURAN	CE SINGAPORE PL		Ref:	CS3/SMO21012209/Atf3e2	
	50 RAFFLES PLAC TOWER SINGAPO	CE #03-03 SINGAPORE LAND PRE 048623		Date:	09/02/2022	
				Code:	SMO	
1.	Policy Particulars :- (THIRD PARTY CLAIM)					
	Insured Veh.	FBM 5500Z	Veh. Inspected	d	SLE 5941H	
	Policy No.		Coverage (\$)		0.00	
	Claim No.	CMTD2103538/SYH	Excess (\$)		0.00	
	Assign From	GRACE TEO	Assign Date		01/12/2021	
2.	Vehicle Particulars & Condition					
	Make & Model	MAZDA 2 HATCHBACK	c.c		1496	
	Engine No.	HIDDEN	Year of Reg.		2016	
	Chassis No.	JM6DJ2HAA01100815	Colour		SILVER	
	Odometer	66570 KM	Steering		IN ORDER	
	Brakes	IN ORDER	Modification		SPORTS RIM	
	General	GOOD				
3.	3. Conditions of Tyres					
		Size	Make		Balance	
	R/H Front Tyre	185/65 R15	YOKOHAMA		6 mm	
	L/H Front Tyre	185/65 R15	YOKOHAMA		6 mm	
	R/H Rear Tyre	185/65 R15	YOKOHAMA		6 mm	
	L/H Rear Tyre	185/65 R15	YOKOHAMA		6 mm	
4.	Description of Damages					
	THE VEHICLE SUSTAINED DAMAGES AT THE REAR N/S PORTION.					
5.	General Information					
	Accident Date	29/11/2021	Inspect Date /	Time	02/12/2021 (03:24 PM)	
	Survey held at	ECLIPSE AUTO PTE LTD				
	155 KAKI BUKIT AVENUE 1 #01□00 SHUN LI INDUSTRIAL PARK SINGAPORE 416012					
5a.	Remarks					
	A) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS. B) THE REPAIR ESTIMATE WAS NOT PRESENTED AT THE TIME OF INSPECTION. THE REPAIRER WAS TOLD TO PREPARE THE ESTIMATE. C) ENCLOSED PLEASE FIND DAMAGED VEHICLE PHOTOGRAPHS. D) THE ESTIMATED REPAIR COST OF THE DAMAGED VEHICLE IS IN THE REGION OF \$5,000-\$6,000					
5b.		Estimate Days of Repair				
	ESTIMATED NORMAL PERIOD FOR REPAIR: 7 Working Days					

Report Ref No. CS3/SMO21012209/Atf3e2

Inspected By

ADRIAN LING WAI PING

K.K.LAU CPT(RET)

B.Eng,AMSOE,AMIRTE,AMSAE-A,M.MATAI

 $BEng(Hons), B. Bus, MBA, PEng, PE, \, MInstAEA, MASME, MIRTE$

REGD Auto Consultant-SAE, Licensed Appraiser

Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contact or tort, is accepted to any third party who may reply on the Report wholly or in part. Any third party acting or replying on this Report, in whole or in part, does so at his or her own risk.